SITE ID	LOCATIONAL IDENTIFIER	LEAD GOOSENECK CURRENTLY PRESENT?	CURRENT STREET SIDE SERVICE LINE MATERIAL	WAS STREET SIDE SERVICE LINE MATERIAL EVER PREVIOUSLY LEAD?	STREET SIDE SERVICE LINE SIZE	STREET SIDE SERVICE LINE INSTALL DATE	CURRENT PROPERTY SIDE SERVICE LINE MATERIAL	PROPERTY SIDE SERVICE LINE SIZE	PROPERTY SIDE SERVICE LINE INSTALL DATE	BUILDING TYPE	BASIS OF STREET SIDE MATERIAL CLASSIFICATION	BASIS OF PROPERTY SIDE MATERIAL CLASSIFICATION	WAS PROPERTY SIDE MATERIAL FIELD VERIFIED?	DATE OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	METHOD OF PROPERTY SIDE FIELD VERIFICATION, IF APPLICABLE	NOTES ON BASIS OF MATERIAL CLASSIFICATION
83646535	807 NASH LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583691	720 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N			
76782831	805 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882495	716 YORKTOWN RD	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe in notes	
79515528	808 NASH LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783119	809 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317922	806 NASH LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783188	717 CUMBERLAND L	Unk	DI	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882410	813 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515660	804 NASH LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583672	721 CUMBERLAND L	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782813	817 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515517	802 NASH LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782749	725 CUMBERLAND L	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515973	821 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317813	800 NASH LN	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783139	729 CUMBERLAND L	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583651	825 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317916	823 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
76783010	801 CUMBERLAND L	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes	
76782803	829 CLOVER LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515684	821 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583698	805 CUMBERLAND L	Unk	DI	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782876	833 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317923	819 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
76782996	809 CUMBERLAND L	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782740	903 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
79515604	817 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515492	813 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882479	907 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882577	813 CUMBERLAND L	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783069	817 CUMBERLAND L	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515518	811 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75583530	911 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783632	821 CUMBERLAND L	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782756	915 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782872	825 CUMBERLAND L	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782761	919 CLOVER LN	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
79515907	809 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782911	933 LIBERTY DR	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583614	923 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317950	807 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
76782783	927 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583697	940 LIBERTY DR	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583567	931 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063683	805 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583633	935 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
78882549	936 LIBERTY DR	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515534	803 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783168	901 LINCOLN GREEN	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515974	934 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063671	800 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783208	905 LINCOLN GREEN	Unk	C	Unk	1"	1981	UNK-LG	Unknown	1981	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753302	930 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882252	802 MACK LN	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782908	909 LINCOLN GREEN	Unk	C	Unk	1"	1986	C	Unknown	1986	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782933	926 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646563	804 MACK LN	Unk	C	Unk	1"	2000	UNK-NOLG	Unknown	2000	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317900	806 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783148	922 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515713	913 LINCOLN GREEN	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515692	808 MACK LN	Unk	C	Unk	1"	2004	UNK-NOLG	Unknown	2004	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583623	918 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783590	912 LINCOLN GREEN	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			
79515901	810 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782878	914 CLOVER LN	Unk	UNK-NOLG	Unk		1991	C	Unknown	1991	SF	Installed after lead ban	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882544	908 LINCOLN GREEN	Unk	C	Unk	1"	1985	UNK-LG	Unknown	1985	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646582	910 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583661	904 LINCOLN GREEN	Unk	C	Unk	1"	1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515632	904 MACK LN	Unk	C	Unk	1"	2000	UNK-NOLG	Unknown	2000	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583705	906 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882439	900 LINCOLN GREEN	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N			
79317911	906 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782965	902 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583700	848 LINCOLN GREEN	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter	
79317925	908 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515827	832 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646570	828 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515637	910 MACK LN	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583708	841 LINCOLN GREEN	Unk	C	Unk	1"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882671	824 CLOVER LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515665	912 MACK LN	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782808	921 LIBERTY DR	Unk	C	Unk	1"	1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583542	820 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515638	914 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583669	925 LIBERTY DR	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782919	816 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318011	916 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882511	824 CUMBERLAND L	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882391	812 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
80063719	909 MACK LN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583576	820 CUMBERLAND L	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515630	808 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318007	903 MACK LN	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583689	713 CUMBERLAND (	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515733	937 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76782792	804 CLOVER LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782814	709 CUMBERLAND (	Unk	C	Unk	1"	1987	C	3/4"	1987	SF	Installation record	Field inspection only	N	3/6/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000055	933 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75583562	300 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
75583654	705 CUMBERLAND (	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82268779	4981 CAKE PKWY	Unk	DI	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installation record		N			
76783076	701 CUMBERLAND (	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
79515673	925 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
79515850	401 IROQUOIS CT	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
75583724	700 CUMBERLAND (	Unk	C	Unk	1"	1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515550	921 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
78882598	405 IROQUOIS CT	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
76782765	704 CUMBERLAND (	Unk	C	Unk		1981	UNK-LG	Unknown	1981	SF	Installation record		N			
79515515	917 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
78882638	409 IROQUOIS CT	Unk	UNK-LG	Unk		1979	C	Unknown	1979	SF		Field inspection only	Y	5/17/2024	Other - describe in notes	
75583593	708 CUMBERLAND (	Unk	C	Unk	1"	1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	7/25/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515757	913 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
78882590	411 IROQUOIS CT	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N			
76782896	712 CUMBERLAND (	Unk	C	Unk	1"	1983	UNK-LG	Unknown	1983	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063665	918 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
80063659	413 IROQUOIS CT	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	6/10/2024	Other - describe in notes	
76782884	716 CUMBERLAND (	Unk	C	Unk	1"	1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515584	920 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76783568	414 IROQUOIS CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
75583664	720 CUMBERLAND (	Unk	C	Unk	1"	1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515930	922 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
82753300	412 IROQUOIS CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
75583470	705 SCHUYKILL CT	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515541	924 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76783319	701 SCHUYKILL CT	Unk	C	Unk	1"	1982	C	Unknown	1982	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318003	926 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
78882454	406 IROQUOIS CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
76782894	700 SCHUYKILL CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			
79515698	928 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76783300	401 CHEROKEE CT	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N			
76783064	704 SCHUYKILL CT	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318055	930 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			

78882435	405 CHEROKEE CT	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
76782759	708 SCHUYKILL CT	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515591	932 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
76783221	409 CHEROKEE CT	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe in notes
76782980	726 CUMBERLAND L	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000090	934 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
79317806	936 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
79515662	415 CHEROKEE CT	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	7/12/2024	Other - describe in notes
76783084	708 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
79515533	938 FLYWHEEL CIR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
79515624	805 MACK LN	Unk	C	Unk	1"	2004	UNK-NOLG	Unknown	2004	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782742	704 YORKTOWN RD	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	7/10/2024	Other - describe in notes
78882200	412 CHEROKEE CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76783172	700 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
75583626	328 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882569	410 CHEROKEE CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
75583688	326 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783406	408 CHEROKEE CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
78882447	729 LINCOLN GREEN	Unk	C	Unk	1"	1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	9/3/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782772	324 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515491	404 CHEROKEE CT	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
79000074	801 LINCOLN GREEN	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583624	322 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783448	405 N LEXINGTON P	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
76783354	320 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583665	805 LINCOLN GREEN	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782801	407 FIELD TERRACE	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063779	409 N LEXINGTON P	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
79318048	405 FIELD TERRACE	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515708	413 N LEXINGTON P	Unk	UNK-LG	Unk		1980	C	Unknown	1980	SF		Field inspection only	Y	7/12/2024	Other - describe in notes
76782865	813 LINCOLN GREEN	Unk	C	Unk	1"	1982	UNK-LG	Unknown	1982	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063723	415 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76783129	817 LINCOLN GREEN	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782991	404 FIELD TERRACE	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882405	821 LINCOLN GREEN	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
78882290	501 BRULE PKWY	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
75583537	406 FIELD TERRACE	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
79515691	825 LINCOLN GREEN	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515720	505 FLAMBEAU PKW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
76783349	318 YORKTOWN RD	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515571	829 LINCOLN GREEN	Unk	C	Unk	1"	1985	UNK-LG	Unknown	1985	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646586	509 FLAMBEAU PKW	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
75583571	833 LINCOLN GREEN	Unk	C	Unk	1"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	6/18/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583606	316 YORKTOWN RD	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515866	513 FLAMBEAU PKW	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N		
76783146	837 LINCOLN GREEN	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782858	314 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063695	844 LINCOLN GREEN	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783496	521 FLAMBEAU PKW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
76783065	497 DAHL DR	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583598	840 LINCOLN GREEN	Unk	C	Unk	1"	1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882570	525 FLAMBEAU PKW	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
75583583	836 LINCOLN GREEN	Unk	C	Unk	3/4"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	N		Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782741	495 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583634	832 LINCOLN GREEN	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
78882608	493 DAHL DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783335	529 FLAMBEAU PKW	Unk	UNK-LG	Unk		1983	C	Unknown	1983	SF		Field inspection only	Y	6/3/2024	Other - describe in notes
75583475	828 LINCOLN GREEN	Unk	C	Unk	1"	1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	9/12/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882430	491 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783187	824 LINCOLN GREEN	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515752	533 FLAMBEAU PKW	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
79515949	489 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783059	820 LINCOLN GREEN	Unk	C	Unk	1"	1982	UNK-LG	Unknown	1982	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515748	537 FLAMBEAU PKW	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
76782953	487 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515810	816 LINCOLN GREEN	Unk	C	Unk	1"	1982	C	Unknown	1982	SF	Installation record	Field inspection only	N	3/11/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882441	485 DAHL DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782862	812 LINCOLN GREEN	Unk	C	Unk	3/4"	1986	C	Unknown	1986	SF	Installation record	Field inspection only	N	7/22/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515597	545 FLAMBEAU PKW	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76782975	483 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783651	601 FLAMBEAU CT	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76782861	808 LINCOLN GREEN	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782972	481 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515953	804 LINCOLN GREEN	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783446	605 FLAMBEAU CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
76782940	479 DAHL DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783575	609 FLAMBEAU CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
76783644	800 LINCOLN GREEN	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583662	480 DAHL DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317804	608 FLAMBEAU CT	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
75583628	730 LINCOLN GREEN	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882209	604 FLAMBEAU CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
79515804	628 YORKTOWN RD	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
76783013	482 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783557	600 FLAMBEAU CT	Unk	C	Unk		1981	C	Unknown	1981	SF	Installation record	Field inspection only	N		
75583629	624 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N		
76782834	484 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783565	544 FLAMBEAU PKW	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
75583528	620 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N		
78882404	512 BAYFIELD CT	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
76783066	486 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783123	616 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
78882344	516 BAYFIELD CT	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
78882355	505 RAULS TRCE	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76782895	488 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515943	520 BAYFIELD CT	Unk	UNK-LG	Unk		1979	C	Unknown	1979	SF			N	6/5/2024	Other - describe in notes
78882451	725 LIBERTY DR	Unk	C	Unk	1"	1977	UNK-LG	Unknown	1977	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783580	490 DAHL DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882222	521 BAYFIELD CT	Unk	UNK-LG	Unk		1980	C	Unknown	1980	SF		Field inspection only	Y	6/21/2024	Other - describe in notes
76783058	729 LIBERTY DR	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783074	492 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882471	517 BAYFIELD CT	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	6/3/2024	Other - describe in notes
75583636	600 REGAL CT	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515642	513 BAYFIELD CT	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76783347	494 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583721	604 REGAL CT	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783587	512 CHIPPEWA CT	Unk	UNK-LG	Unk		1984	C	Unknown	1984	SF		Field inspection only	Y	5/22/2024	Other - describe in notes
75583640	608 REGAL CT	Unk	C	Unk	1"	1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882382	516 CHIPPEWA CT	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76782825	496 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783508	520 CHIPPEWA CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
76783407	605 REGAL CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76783050	498 DAHL DR	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782873	601 REGAL CT	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882313	521 CHIPPEWA CT	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
79515732	227 YORKTOWN RD	Unk	UNK-NOLG	Unk		2007	UNK-NOLG	Unknown	2007	SF	Installed after lead ban	Installed after lead ban	N		
79515818	517 CHIPPEWA CT	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
76783186	805 LIBERTY DR	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882411	229 YORKTOWN RD	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783343	513 CHIPPEWA CT	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe in notes
76783046	809 LIBERTY DR	Unk	C	Unk	1"	1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583685	502 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515905	512 FLAMBEAU PKW	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76783160	504 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783534	813 LIBERTY DR	Unk	C	Unk	1"	1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515693	508 FLAMBEAU PKW	Unk	UNK-LG	Unk		1985	C	Unknown	1985	SF		Field inspection only	Y	5/16/2024	Other - describe in notes
79515690	506 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783028	817 LIBERTY DR	Unk	C	Unk	1"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317902	504 FLAMBEAU PKW	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76782854	508 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782788	821 LIBERTY DR	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515977	509 BRULE PKWY	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
76782961	510 TANGLEWOOD	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583616	825 LIBERTY DR	Unk	C	Unk	1"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882248	508 BRULE PKWY	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
78882670	507 TANGLEWOOD	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583718	829 LIBERTY DR	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783455	504 BRULE PKWY	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		

75583543	833 LIBERTY DR	Unk	C	Unk	1"	1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe
76783177	505 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882532	500 BRULE PKWY	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF		Field inspection only	Y	7/1/2024	Other - describe in notes
78882428	313 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515755	837 LIBERTY DR	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		
76783279	416 N LEXINGTON P	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N		
76782955	315 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76782930	901 LIBERTY DR	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N		
76783649	412 N LEXINGTON P	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
76782990	905 LIBERTY DR	Unk	C	Unk	1"	1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at me
78882474	317 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882395	319 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76783222	408 N LEXINGTON P	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe in notes
79515648	909 LIBERTY DR	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
76783609	404 N LEXINGTON P	Unk	UNK-LG	Unk		1979	C	Unknown	1979	SF		Field inspection only	Y	6/4/2024	Other - describe in notes
78882683	924 LIBERTY DR	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N		
76782821	321 YORKTOWN RD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76782936	920 LIBERTY DR	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N		
76783585	338 N LEXINGTON P	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	6/3/2024	Other - describe in notes
78882285	323 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76782835	916 LIBERTY DR	Unk	C	Unk	1"	1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N		
78882610	325 YORKTOWN RD	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
79318024	336 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
79515645	912 LIBERTY DR	Unk	C	Unk	1"	1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N		
79000072	327 YORKTOWN RD	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
79515959	334 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76782776	908 LIBERTY DR	Unk	C	Unk	1"	1986	C	Unknown	1986	SF	Installation record	Field inspection only	N		
76782898	329 YORKTOWN RD	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
79515531	332 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76783550	330 N LEXINGTON P	Unk	UNK-LG	Unk		1981	C	Unknown	1981	SF		Field inspection only	Y	6/10/2024	Other - describe in notes
76782774	328 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76782797	509 NATCHEZ CT	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		
76783366	328 N LEXINGTON P	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N		
76783025	326 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
79317822	505 NATCHEZ CT	Unk	C	Unk	1"	1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	9/4/2024	Other - describe
76782939	324 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783116	501 NATCHEZ CT	Unk	C	Unk	1"	1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		
76782917	322 BURL OAK DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
75583570	502 NATCHEZ CT	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		
79515842	329 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76782796	320 BURL OAK DR	Unk	UNK-NOLG	Unk		2002	C	1"	2002	SF	Installed after lead ban	Field inspection only	N	3/14/2025	Visual insp at me
76783016	506 NATCHEZ CT	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N		
76783598	331 N LEXINGTON P	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N		
79515553	510 NATCHEZ CT	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		
75583621	318 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783567	333 N LEXINGTON P	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
78882692	840 LIBERTY DR	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		
76782886	316 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783365	511 TARA CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
75583553	836 LIBERTY DR	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
76782904	314 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76782906	832 LIBERTY DR	Unk	C	Unk	1"	1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe
76782828	312 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783460	505 TARA CT	Unk	UNK-LG	Unk		1983	C	Unknown	1983	SF		Field inspection only	Y	5/22/2024	Other - describe in notes
78882453	828 LIBERTY DR	Unk	C	Unk	1"	1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe
78882408	602 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515908	503 TARA CT	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
76783124	824 LIBERTY DR	Unk	C	Unk	1"	1986	UNK-LG	Unknown	1986	SF	Installation record		N		
78882640	604 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
80063787	501 TARA CT	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	N		
76782789	820 LIBERTY DR	Unk	C	Unk	1"	1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe
75583580	311 BURL OAK DR	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783564	500 TARA CT	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	N		
79515967	816 LIBERTY DR	Unk	C	Unk	1"	1978	UNK-LG	Unknown	1978	SF	Installation record		N		
76783089	313 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783563	502 TARA CT	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	N		
76782768	812 LIBERTY DR	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/11/2024	Other - describe
76783318	315 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
78882483	504 TARA CT	Unk	C	Unk		1982	C	Unknown	1982	SF	Installation record	Field inspection only	N		
75583617	808 LIBERTY DR	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe
76783067	317 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783512	506 TARA CT	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N		
76782912	804 LIBERTY DR	Unk	C	Unk	1"	1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		
75583702	319 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783196	800 LIBERTY DR	Unk	C	Unk	1"	1980	UNK-LG	Unknown	1980	SF	Installation record		N		
78882261	339 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
76783044	321 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
78882579	730 LIBERTY DR	Unk	C	Unk	1"	1979	UNK-LG	Unknown	1979	SF	Installation record		N		
83119133	304 APACHE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	9/17/2024	Other - describe in notes
76783143	323 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783086	500 RALLIS TRCE	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
79515855	300 APACHE CT	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
76782973	325 BURL OAK DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
75583683	608 YORKTOWN RD	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N		
78882295	301 APACHE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes
80063666	327 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
75583566	604 YORKTOWN RD	Unk	C	Unk		1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
78882621	305 APACHE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe in notes
76783167	329 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783014	600 YORKTOWN RD	Unk	C	Unk		1979	UNK-LG	Unknown	1979	SF	Installation record		N		
76783356	309 APACHE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
79515614	331 BURL OAK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783127	520 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	6/25/2024	Other - describe in notes
76783570	316 CHEYENNE CT	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
76782755	348 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75583578	516 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/11/2024	Other - describe in notes
76783278	312 CHEYENNE CT	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
75583625	512 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	7/9/2024	Other - describe in notes
78882371	346 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882384	308 CHEYENNE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
76782882	508 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes
79515775	344 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515718	304 CHEYENNE CT	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
76783128	504 YORKTOWN RD	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
79515744	342 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783215	300 CHEYENNE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes
75583587	500 YORKTOWN RD	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes
75583653	340 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
78882639	301 CHEYENNE CT	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
75583468	503 YORKTOWN RD	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
83646562	338 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882496	305 CHEYENNE CT	Unk	C	Unk		1981	UNK-LG	Unknown	1981	SF	Installation record		N		
78882406	336 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75583539	608 CONSTITUTION	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe in notes
83646536	309 CHEYENNE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/10/2024	Other - describe in notes
75583603	334 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76783320	610 CONSTITUTION	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe in notes
78882219	313 CHEYENNE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
76783592	332 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79318028	317 CHEYENNE CT	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
80063680	330 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882399	625 CONSTITUTION	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	7/16/2024	Other - describe in notes
78882487	321 CHEYENNE CT	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record		N		
76783154	328 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515537	621 CONSTITUTION	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
78882301	511 BRULE PKWY	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N		
78882558	617 CONSTITUTION	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	7/10/2024	Other - describe in notes
76782853	605 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882223	513 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
78882600	515 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
78882634	609 CONSTITUTION	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
75583680	608 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
78882432	517 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
76782868	611 CONSTITUTION	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
78882475	519 BRULE PKWY	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N		
76782888	702 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76782938	605 CONSTITUTION	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
83646578	701 TANGLEWOOD	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		

GIS file "2024-01-25_Deforest_water_services.csv" join to export

78882201	523 BRULE PKWY	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N		
76782732	601 CONSTITUTION	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/24/2024	Other - describe in notes
78882353	511 LYNNBROOK DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N		
80063681	329 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583675	509 YORKTOWN RD	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
83119155	509 LYNNBROOK DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N		
78882206	327 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783207	513 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/17/2024	Other - describe in notes
78882256	507 LYNNBROOK DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N		
75583638	331 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583717	517 YORKTOWN RD	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N		
75583727	333 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882316	505 LYNNBROOK DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
76782735	601 YORKTOWN RD	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
76782984	335 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783289	506 LYNNBROOK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
75583595	605 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	7/16/2024	Other - describe in notes
76782744	337 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783515	510 LYNNBROOK CT	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N		
76782958	339 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317809	609 YORKTOWN RD	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76782751	341 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583679	613 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/13/2024	Other - describe in notes
76783153	343 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782941	617 YORKTOWN RD	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes
78882221	512 LYNNBROOK CT	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N		
75583592	345 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783027	621 YORKTOWN RD	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes
76783309	601 BRULE PKWY	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N		
76782883	358 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783170	604 BRULE PKWY	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882416	356 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
78882636	602 BRULE PKWY	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882550	701 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	9/5/2024	Other - describe in notes
75583725	350 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938896	600 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882469	705 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes
76783083	348 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882615	522 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
76782787	709 YORKTOWN RD	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
76783087	346 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76782754	713 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
76783149	717 YORKTOWN RD	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
76783425	518 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
83119151	340 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783017	721 YORKTOWN RD	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	6/11/2024	Other - describe in notes
76783418	516 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
76782900	338 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
76783125	725 YORKTOWN RD	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N		
79515658	514 BRULE PKWY	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		
75583569	729 YORKTOWN RD	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
78882452	512 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
76783599	332 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782934	615 LOUIS CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
78882463	510 BRULE PKWY	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		
76782849	330 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063786	613 LOUIS CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
76783096	703 TANGLEWOOD	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
78882283	322 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
76783081	706 TANGLEWOOD	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783048	611 LOUIS CT	Unk	C	Unk		1985	C	Unknown	1985	SF	Installation record	Field inspection only	N	6/14/2024	Other - describe in notes
76783539	320 N LEXINGTON P	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N		
75583667	609 LOUIS CT	Unk	C	Unk		1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	7/10/2024	Other - describe in notes
76782748	708 TANGLEWOOD	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783194	318 N LEXINGTON P	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	N		
76782851	710 TANGLEWOOD	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583674	316 N LEXINGTON P	Unk	UNK-LG	Unk		1983	C	Unknown	1983	SF		Field inspection only	Y	5/20/2024	Other - describe in notes
76783035	712 TANGLEWOOD	Unk	UNK-NOLG	Unk		2012	UNK-NOLG	Unknown	2012	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882656	314 N LEXINGTON P	Unk	UNK-LG	Unk		1984	C	Unknown	1984	SF		Field inspection only	Y	5/14/2024	Other - describe in notes
76783052	403 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783165	601 LOUIS CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
76782963	312 N LEXINGTON P	Unk	UNK-LG	Unk		1984	C	Unknown	1984	SF		Field inspection only	Y	5/14/2024	Visual insp at meter
79317949	404 ROSEMAL LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783114	600 LOUIS CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		
76783548	310 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
75583722	405 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515677	602 LOUIS CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		
76782758	308 N LEXINGTON P	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
75583575	406 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882271	604 LOUIS CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
78882540	306 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N		
76783009	407 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583605	606 LOUIS CT	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
75583645	304 N LEXINGTON P	Unk	UNK-LG	Unk		1984	C	Unknown	1984	SF		Field inspection only	Y	7/23/2024	Other - describe in notes
75583686	408 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782832	608 LOUIS CT	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N		
75583604	502 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
76782927	610 LOUIS CT	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N	6/5/2024	Other - describe in notes
76782844	409 ROSEMAL LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583659	504 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
84515417	612 LOUIS CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
76783110	616 LOUIS CT	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N		
76782738	410 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753264	506 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783161	622 LOUIS CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
76782946	411 ROSEMAL LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782811	508 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
75583619	624 LOUIS CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
78882667	412 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063784	510 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
75583618	626 LOUIS CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
76782786	512 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882530	628 LOUIS CT	Unk	C	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		
76783085	414 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	C	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583548	514 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
76783090	415 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377963	105 ACKER PKWY	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N		
76783006	516 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
76782994	416 ROSEMAL LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378119	201 ACKER PKWY	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
76783003	518 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
78882657	418 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783015	520 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
75583707	420 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377779	205 ACKER PKWY	Unk	UNK-LG	Unk		1972	C	Unknown	1972	SF		Field inspection only	Y	7/8/2024	Other - describe in notes
79515890	523 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
76782937	422 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378164	209 ACKER PKWY	Unk	UNK-LG	Unk		1960	UNK-LG	Unknown	1960	SF			N		
79515753	521 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
76783190	424 ROSEMAL LN	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377786	211 ACKER PKWY	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N		
82753299	519 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
80063672	303 BRUNS ST	Unk	UNK-NOLG	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N		
75377966	215 ACKER PKWY	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N		
80063796	517 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76783438	301 BRUNS ST	Unk	C	Unk	1"	1986	C	Unknown	1986	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318035	515 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
75378020	219 ACKER PKWY	Unk	UNK-LG	Unk		1972	C	Unknown	1972	SF		Field inspection only	Y	5/6/2024	Other - describe in notes
78882555	105 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378175	223 ACKER PKWY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N		
83646558	513 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882377	111 RENATA CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		
75377866	227 ACKER PKWY	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
83646564	511 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
76782945	113 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
75378178	231 ACKER PKWY	Unk	UNK-LG	Unk		1972	C	Unknown	1972	SF		Field inspection only	Y	7/8/2024	Other - describe in notes
79515650	509 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
76783360	115 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export

78882488	505 OLD INDIAN TRL	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882586	117 RENATA CT	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N				
75378159	101 OLD INDIAN TRL	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N				
78882602	119 RENATA CT	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377942	306 ACKER PKWY	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N				
75583560	503 OLD INDIAN TRL	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				
82753298	501 OLD INDIAN TRL	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377835	105 OLD INDIAN TRL	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe in notes		
76783613	121 RENATA CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				
78882691	123 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377773	405 MOHAWK TRL	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N				
76783042	238 N LEXINGTON P	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				
75378155	407 MOHAWK TRL	Unk	UNK-NOLG	Unk		1984	UNK-LG	Unknown	1984	SF	Installed after lead ban		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000073	235 N LEXINGTON P	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				
78882241	125 RENATA CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				
75378154	408 MOHAWK TRL	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes		
76783101	233 N LEXINGTON P	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783223	127 RENATA CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378006	404 MOHAWK TRL	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes		
76783103	237 N LEXINGTON P	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783513	129 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782915	429 OLD INDIAN TRL	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N				
75378180	220 ACKER PKWY	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N				
76783210	131 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
75583546	301 N LEXINGTON P	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N				
75378242	218 ACKER PKWY	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N				
80063668	133 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
75583561	303 N LEXINGTON P	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				
75378256	216 ACKER PKWY	Unk	UNK-LG	Unk		1967	UNK-LG	Unknown	1967	SF			N				
79515585	135 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377994	214 ACKER PKWY	Unk	UNK-LG	Unk		1966	UNK-LG	Unknown	1966	SF			N				
75378211	212 ACKER PKWY	Unk	UNK-LG	Unk		1966	C	Unknown	1966	SF		Field inspection only	Y	5/20/2024	Other - describe in notes		
76782922	309 N LEXINGTON P	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N				
75583291	210 ACKER PKWY	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N				
76783277	116 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782956	311 N LEXINGTON P	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N				
78882597	114 RENATA CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				
75378216	208 ACKER PKWY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N				
76782852	313 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N				
75378212	206 ACKER PKWY	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N				
78882417	315 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N				
76783394	110 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
79515695	317 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N				
75583448	204 ACKER PKWY	Unk	UNK-LG	Unk		1968	UNK-LG	Unknown	1968	SF			N				
79515697	202 ACKER PKWY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N				
76783182	319 N LEXINGTON P	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N				
79515792	321 N LEXINGTON P	Unk	DI	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes		
75377946	304 VALERIA DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export	
79515494	108 RENATA CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378172	308 VALERIA DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export	
78882373	104 RENATA CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583602	325 N LEXINGTON P	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N				
75377731	312 VALERIA DR	Unk	C	Unk	1"	1973	UNK-LG	Unknown	1973	SF	Installation record		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515809	102 RENATA CT	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				
79515782	327 N LEXINGTON P	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N				
76783235	213 BRUNS ST	Unk	C	Unk	1"	1991	UNK-NOLG	Unknown	1991	SF	Installation record	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378190	404 VALERIA DR	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N				
75378189	408 VALERIA DR	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583573	608 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782993	207 BRUNS ST	Unk	C	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N				
78882514	412 VALERIA DR	Unk	C	Unk	1"	1976	C	Unknown	1976	SF	Installation record	Field inspection only	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782957	605 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378191	414 VALERIA DR	Unk	C	Unk	1"	UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/13/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export	
78882473	205 BRUNS ST	Unk	C	Unk	1"	1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783000	609 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783259	203 BRUNS ST	Unk	C	Unk	1"	1994	UNK-NOLG	Unknown	1994	SF	Installation record	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583245	417 VALERIA DR	Unk	C	Unk	1"	1971	C	Unknown	1971	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export	
79515781	613 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783132	201 BRUNS ST	Unk	C	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
75377815	413 VALERIA DR	Unk	C	Unk	1"	1971	C	Unknown	1971	SF	Installation record	Field inspection only	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782856	617 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063720	199 BRUNS ST	Unk	C	Unk	1"	1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377749	409 VALERIA DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583563	621 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783327	197 BRUNS ST	Unk	C	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				
75378188	405 VALERIA DR	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783555	201 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				
76782790	624 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378241	325 VALERIA DR	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783574	301 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515741	626 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882418	303 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515919	630 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882236	305 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583574	634 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783206	301 VALERIA DR	Unk	C	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882235	307 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119135	638 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882554	509 N STEVENSON S	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N				
79515564	642 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783339	309 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882648	311 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782977	605 EAGLENEST LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				
78882694	124 E NORTH ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783628	313 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583527	213 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783569	501 DENNIS DR	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	5/20/2024	Other - describe in notes		
76783268	315 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783251	505 DENNIS DR	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	5/31/2024	Other - describe in notes		
76783608	317 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782846	215 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				
76783467	513 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	N				
76783622	401 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583596	217 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515566	403 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783120	221 N LEXINGTON P	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515670	517 DENNIS DR	Unk	C	Unk		1970	UNK-LG	Unknown	1970	SF	Installation record		N				
76783121	223 N LEXINGTON P	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
76783547	521 DENNIS DR	Unk	C	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N				
76783618	405 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317820	225 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783545	525 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	6/28/2024	Other - describe in notes		
76783630	407 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882668	227 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				
76783255	409 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882289	529 DENNIS DR	Unk	C	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N				
78882273	411 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783454	533 DENNIS DR	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	6/26/2024	Other - describe in notes		
78882303	413 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783653	537 DENNIS DR	Unk	C	Unk		1975	P	Unknown	1975	SF	Installation record	Field inspection only	Y	7/18/2024	Other - describe in notes		
80063669	404 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783549	541 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes		
79515961	231 N LEXINGTON P	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882260	402 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783468	545 DENNIS DR	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	N	11/22/2024	Visual insp at meter		
79515704	230 N LEXINGTON P	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				
80063689	400 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783579	549 DENNIS DR	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N				
76782960	401 MEADOW OAK '	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515659	806 KAROW ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882507	544 DENNIS DR	Unk	UNK-NOLG	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes		
75583723	421 MEADOW OAK '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				
79515918	316 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882576	540 DENNIS DR	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes		
76783026	423 MEADOW OAK '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882255	314 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515862	422 MEADOW OAK '	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N				GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882245	312 SCOTT DR	Unk	UNK-NOLG	Unk		1992	C	Unknown	1992	SF	Installed after lead ban	Field inspection only	Y	3/5/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export	

76782286	536 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	6/25/2024	Other - describe in notes
83119145	310 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782769	420 MEADOW OAK '	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76783256	532 DENNIS DR	Unk	C	Unk		1975	P	Unknown	1975	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes
78882472	308 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063686	418 MEADOW OAK '	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882287	528 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes
76783536	306 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515942	416 MEADOW OAK '	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76783519	304 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515784	414 MEADOW OAK '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		
79515596	524 DENNIS DR	Unk	C	Unk		1975	UNK-LG	Unknown	1975	SF	Installation record		N		
79515749	412 MEADOW OAK '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783498	302 SCOTT DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783336	520 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
78882685	408 MEADOW OAK '	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515742	301 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882456	516 DENNIS DR	Unk	C	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		
78882595	303 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782871	406 MEADOW OAK '	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515946	404 MEADOW OAK '	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
78882665	305 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882575	508 DENNIS DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes
78882396	307 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583637	402 MEADOW OAK '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		
76783483	502 DENNIS DR	Unk	C	Unk		1975	UNK-LG	Unknown	1975	SF	Installation record		N		
76783250	309 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583632	192 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882284	401 N MAIN ST	Unk	C	Unk	1"	1955	C	Unknown	1955	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583704	190 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		
80063694	311 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882482	409 N MAIN ST	Unk	C	Unk	1"	1955	UNK-LG	Unknown	1955	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783034	188 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515646	413 N MAIN ST	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882257	313 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783525	417 N MAIN ST	Unk	UNK-LG	N		1930	G	Unknown	1930	SF		Field inspection only	Y	5/28/2024	Other - describe in notes
76783344	315 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
78882616	700 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882258	105 E NORTH ST	Unk	C	Unk	1"	1956	C	Unknown	1956	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000076	317 N HALSOR ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882310	704 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783328	401 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783298	109 E NORTH ST	Unk	UNK-LG	Unk		1985	C	Unknown	1985	SF		Field inspection only	Y	6/4/2024	Other - describe in notes
76782954	706 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882299	403 N HALSOR ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783491	113 E NORTH ST	Unk	UNK-LG	Unk		1930	UNK-LG	Unknown	1930	SF			N		
76782795	405 MEADOW VIEW	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377752	105 W HOLUM ST	Unk	C	Unk	1"	1930	UNK-LG	Unknown	1930	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583558	409 MEADOW VIEW	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882620	102 N MAIN ST	Unk	UNK-NOLG	N		1900	G	Unknown	1900	SF	Installed after lead ban	Field inspection only	Y	5/27/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515747	117 E NORTH ST	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N		
76782950	408 MEADOW VIEW	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882693	108 N MAIN ST	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783463	121 E NORTH ST	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N		
75583687	404 MEADOW VIEW	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882464	205 E NORTH ST	Unk	UNK-LG	N		1920	G	Unknown	1920	SF		Field inspection only	N		
79515709	136 E HOLUM ST	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N		
75583476	800 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882484	209 E NORTH ST	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317828	140 E HOLUM ST	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installation record	Field inspection only	N	12/12/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782782	802 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882415	213 E NORTH ST	Unk	C	Unk	1"	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N	2/25/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783247	144 E HOLUM ST	Unk	UNK-LG	Unk		1920	UNK-LG	Unknown	1920	SF			N		
75583646	804 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882442	305 E NORTH ST	Unk	C	Unk	1"	1914	UNK-LG	Unknown	1914	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515962	806 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882337	309 E NORTH ST	Unk	C	Unk	1"	1940	UNK-LG	Unknown	1940	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782902	808 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882518	152 E HOLUM ST	Unk	UNK-NOLG	Unk		1910	UNK-LG	Unknown	1910	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783204	810 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378057	113 W HOLUM ST	Unk	C	Unk	1"	1961	UNK-LG	Unknown	1961	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783554	313 E NORTH ST	Unk	C	Unk	1"	1940	UNK-LG	Unknown	1940	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782760	812 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583485	121 W HOLUM ST	Unk	C	Unk	1"	1964	UNK-LG	Unknown	1964	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882297	401 COLUMBIA AVE	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N		
76782928	814 W LEXINGTON I	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119143	409 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515736	105 REIGSTAD ST	Unk	C	Unk	1"	1963	UNK-LG	Unknown	1963	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782885	816 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783227	417 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1860	C	Unknown	1860	SF	Installed after lead ban	Field inspection only	Y	5/21/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377777	109 REIGSTAD ST	Unk	C	Unk	1"	1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783021	818 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783370	421 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377993	113 REIGSTAD ST	Unk	C	Unk	1"	1974	UNK-LG	Unknown	1974	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882571	820 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882218	118 WASHINGTON S	Unk	UNK-LG	Unk		1920	UNK-LG	Unknown	1920	SF			N		
75583434	332 HARVARD DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782830	822 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783258	114 WASHINGTON S	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N		
75583286	100 QUAM LN	Unk	UNK-LG	Unk		1974	UNK-LG	Unknown	1974	SF			N		
75583643	824 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783280	504 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882476	400 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515787	512 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583268	200 HARVARD DR	Unk	C	Unk	1"	1963	C	Unknown	1963	SF	Installation record	Field inspection only	Y	5/27/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782987	312 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882666	516 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1975	UNK-LG	Unknown	1975	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377856	204 HARVARD DR	Unk	C	Unk	1"	1963	C	Unknown	1963	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882465	308 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882298	520 COLUMBIA AVE	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583660	304 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783646	208 HARVARD DR	Unk	C	Unk	1"	1963	UNK-LG	Unknown	1963	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783449	524 COLUMBIA AVE	Unk	P	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515603	305 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		
75583326	212 HARVARD DR	Unk	C	Unk	1"	1963	C	Unknown	1963	SF	Installation record	Field inspection only	Y	6/25/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783411	112 N CLEVELAND A	Unk	DI	Unk		1900	C	Unknown	1900	SF	Installation record	Field inspection only	N		
79515825	825 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583400	300 HARVARD DR	Unk	C	Unk	1"	1967	C	Unknown	1967	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882499	528 COLUMBIA AVE	Unk	C	Unk	1"	1955	C	Unknown	1955	SF	Installation record	Field inspection only	Y	6/11/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583505	304 HARVARD DR	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882203	210 N CLEVELAND A	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583344	308 HARVARD DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782815	821 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882202	521 PARK AVE	Unk	UNK-NOLG	Unk		1943	UNK-LG	Unknown	1943	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583283	312 HARVARD DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N	11/18/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583663	819 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783524	213 MADISON AVE	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783056	817 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882326	520 PARK AVE	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N		
75377985	316 HARVARD DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583670	815 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783623	524 PARK AVE	Unk	UNK-NOLG	Unk		1920	L	Unknown	1920	SF	Installed after lead ban	Field inspection only	Y	7/23/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377850	320 HARVARD DR	Unk	C	Unk	1"	1968	C	Unknown	1968	SF	Installation record	Field inspection only	Y	5/6/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783310	528 PARK AVE	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N		
76783075	811 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317827	532 PARK AVE	Unk	UNK-LG	Unk		1930	UNK-LG	Unknown	1930	SF			N		
83646537	809 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378048	324 HARVARD DR	Unk	C	Unk	1"	UN	UNK-LG	Unknown	UN	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783654	610 PARK AVE	Unk	P	Unk	1"	1900	UNK-LG	Unknown	1900	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378091	328 HARVARD DR	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515955	807 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882545	612 RUSSELL ST	Unk	P	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882334	805 W LEXINGTON I	Unk	UNK-NOLG	Unk		1993	C	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N	3/4/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378083	321 HARVARD DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783625	305 N CLEVELAND A	Unk	UNK-NOLG	Unk		1957	UNK-LG	Unknown	1957	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583323	317 HARVARD DR	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583666	803 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882213	604 PARK AVE	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	9/13/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export

79515561	801 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377754	313 HARVARD DR	Unk	C	Unk	1"	1978	UNK-LG	Unknown	1978	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882339	549 YAHARA ST	Unk	UNK-NOLG	Unk		1961	UNK-LG	Unknown	1961	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882376	707 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583425	309 HARVARD DR	Unk	C	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882307	605 YAHARA ST	Unk	UNK-NOLG	Unk		1954	C	Unknown	1954	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377741	305 HARVARD DR	Unk	C	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515685	705 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377822	205 HARVARD DR	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583709	703 W LEXINGTON I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783471	621 YAHARA ST	Unk	C	Unk	1"	1956	C	Unknown	1956	SF	Installation record	Field inspection only	Y	6/24/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377984	201 HARVARD DR	Unk	C	Unk	1"	1965	C	Unknown	1965	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515514	309 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			
76783260	629 YAHARA ST	Unk	C	Unk	1"	1960	C	Unknown	1960	SF	Installation record	Other - describe in notes	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882461	704 YAHARA ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N			
79515840	181 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			
78882538	716 YAHARA ST	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
75378138	108 REIGSTAD ST	Unk	C	Unk		1965	C	Unknown	1965	SF	Installation record	Field inspection only	N			
79515883	183 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783526	720 YAHARA ST	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N			
75378075	204 REIGSTAD ST	Unk	P	Unk		1964	UNK-LG	Unknown	1964	SF	Installation record		N			
76782867	185 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			
79515795	724 YAHARA ST	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N			
75378014	208 REIGSTAD ST	Unk	P	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe	in notes
79515844	187 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783218	728 YAHARA ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
75583432	205 REIGSTAD ST	Unk	P	Unk		1964	UNK-LG	Unknown	1964	SF	Installation record		N			
76782750	189 N LEXINGTON P	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882459	736 YAHARA ST	Unk	C	Unk		1960	C	Unknown	1960	SF	Installation record	Field inspection only	Y	6/26/2024	Other - describe	in notes
75377735	209 REIGSTAD ST	Unk	P	Unk		1963	C	Unknown	1963	SF	Installation record	Field inspection only	Y	6/28/2024	Other - describe	in notes
76783488	740 YAHARA ST	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N			
76783005	213 REIGSTAD ST	Unk	P	Unk		1965	UNK-LG	Unknown	1965	SF	Installation record		N			
76783019	193 N LEXINGTON P	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783323	400 N HALSOR ST	Unk	UNK-LG	Unk		1980	C	Unknown	1980	SF		Field inspection only	Y	5/13/2024	Visual insp at meter	
75377920	212 REIGSTAD ST	Unk	P	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	N			
79515960	735 KAROW ST	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N			
75583320	216 REIGSTAD ST	Unk	P	Unk		1966	UNK-LG	Unknown	1966	SF	Installation record		N			
83646568	701 W LEXINGTON I	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882477	731 KAROW ST	Unk	UNK-LG	Unk		1951	C	Unknown	1951	SF		Field inspection only	N			
75377890	220 REIGSTAD ST	Unk	P	Unk		1959	UNK-LG	Unknown	1959	SF	Installation record		N			
79515717	729 KAROW ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
76782850	308 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			
75378112	202 SUNSET DR	Unk	UNK-LG	Unk		1962	UNK-LG	Unknown	1962	SF			N			
76783241	725 KAROW ST	Unk	UNK-LG	Unk		1960	C	Unknown	1960	SF		Field inspection only	Y	6/19/2024	Other - describe	in notes
76782775	304 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			
75377883	221 SANFORD DR	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882335	721 KAROW ST	Unk	UNK-LG	Unk		1960	UNK-LG	Unknown	1960	SF			N			
79515972	606 EAGLENEST LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			
75377975	217 SANFORD DR	Unk	C	Unk	1"	1969	C	Unknown	1969	SF	Installation record	Field inspection only	Y	9/4/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783334	717 KAROW ST	Unk	UNK-LG	Unk		1968	C	Unknown	1968	SF		Field inspection only	Y	5/15/2024	Other - describe	in notes
76782777	604 EAGLENEST LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			
75583267	213 SANFORD DR	Unk	C	Unk	1"	1967	C	Unknown	1967	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882647	713 KAROW ST	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF		Field inspection only	Y	7/18/2024	Other - describe	in notes
78882291	700 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378089	209 SANFORD DR	Unk	C	Unk	1"	1967	C	Unknown	1967	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882520	709 KAROW ST	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	7/1/2024	Other - describe	in notes
79515649	704 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783500	705 KAROW ST	Unk	UNK-LG	Unk		1972	C	Unknown	1972	SF		Field inspection only	Y	5/24/2024	Other - describe	in notes
75378183	205 SANFORD DR	Unk	C	Unk	1"	1969	UNK-LG	Unknown	1969	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317826	708 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515608	405 MABEL ST	Unk	C	Unk		1940	UNK-LG	Unknown	1940	SF	Installation record		N			
75377894	204 SANFORD DR	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782762	712 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1994	C	Unknown	1994	SF	Installed after lead ban	Field inspection only	Y	2/25/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882400	704 KAROW ST	Unk	UNK-LG	Unk		1967	C	Unknown	1967	SF		Field inspection only	Y	5/17/2024	Other - describe	in notes
75377871	212 SANFORD DR	Unk	C	Unk	1"	1968	UNK-LG	Unknown	1968	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782889	716 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646565	708 KAROW ST	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
76782804	305 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			
75377910	216 SANFORD DR	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783562	712 KAROW ST	Unk	UNK-LG	Unk		1959	UNK-LG	Unknown	1959	SF			N			
76782875	217 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75583250	220 SANFORD DR	Unk	C	Unk	1"	1966	UNK-LG	Unknown	1966	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515771	716 KAROW ST	Unk	UNK-LG	Unk		1959	C	Unknown	1959	SF		Field inspection only	N			
76782766	213 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
76783001	209 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
78812128	720 KAROW ST	Unk	UNK-LG	Unk		1959	UNK-LG	Unknown	1959	SF			N			
75378253	302 SUNSET DR	Unk	C	Unk	1"	1965	C	Unknown	1965	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782986	725 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317947	724 KAROW ST	Unk	UNK-LG	Unk		1965	C	Unknown	1965	SF		Field inspection only	N			
75378171	306 SUNSET DR	Unk	UNK-LG	Unk		1966	UNK-LG	Unknown	1966	SF			N			
76782794	721 OVERLOOK TER	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783466	732 KAROW ST	Unk	UNK-LG	Unk		1959	C	Unknown	1959	SF		Field inspection only	Y	7/18/2024	Other - describe	in notes
75377921	310 SUNSET DR	Unk	C	Unk		1967	C	Unknown	1967	SF	Installation record	Field inspection only	N			
76783008	717 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783577	711 E NORTH ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378199	209 CORA ST	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782842	713 OVERLOOK TER	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378149	205 CORA ST	Unk	C	Unk	1"	1970	C	Unknown	1970	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063700	713 E NORTH ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583613	709 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378025	204 CORA ST	Unk	C	Unk	1"	1969	UNK-LG	Unknown	1969	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783486	709 E NORTH ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782753	705 OVERLOOK TER	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378087	208 CORA ST	Unk	C	Unk	1"	1973	UNK-LG	Unknown	1973	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783610	707 E NORTH ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782733	701 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378239	408 SUNSET DR	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	SF	Installed after lead ban	Field inspection only	Y	5/23/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783602	705 E NORTH ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782839	631 OVERLOOK TER	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378037	409 SUNSET DR	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	SF	Installed after lead ban	Field inspection only	Y	5/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646566	703 E NORTH ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583298	405 SUNSET DR	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782857	627 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377955	317 SUNSET DR	Unk	UNK-NOLG	Unk		1973	UNK-LG	Unknown	1973	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783532	701 E NORTH ST	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783456	623 OVERLOOK TER	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782976	313 SUNSET DR	Unk	UNK-LG	Unk		1968	UNK-LG	Unknown	1968	SF			N			
76782743	619 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583531	409 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882662	309 SUNSET DR	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N			
79515941	411 TRAIL SIDE DR	Unk	C	Unk		1999	C	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N	3/6/2025	Visual insp at meter	
79515950	615 OVERLOOK TER	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882318	413 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
75583597	610 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377743	305 SUNSET DR	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter	
76783301	417 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
76783142	620 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583259	301 SUNSET DR	Unk	C	Unk		1966	C	Unknown	1966	SF	Installation record	Field inspection only	Y	7/3/2024	Other - describe	in notes
78882503	419 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
80063778	209 SUNSET DR	Unk	UNK-LG	Unk		1966	UNK-LG	Unknown	1966	SF			N			
76782913	624 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882517	421 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
75377927	207 SUNSET DR	Unk	C	Unk		1969	C	Unknown	1969	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe	in notes
76782746	628 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378073	205 SUNSET DR	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	N			
78882572	632 OVERLOOK TER	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377932	201 SUNSET DR	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N			
76782910	636 OVERLOOK TER	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882426	423 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75378016	113 SUNSET DR	Unk	C	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe	in notes
76782840	640 OVERLOOK TER	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783520	425 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75583410	109 SUNSET DR	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe	in notes
79515582	639 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882311	429 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75378093	316 S MAIN ST	Unk	UNK-NOLG	Unk		2009	C	Unknown	2009	SF	Installed after lead ban	Field inspection only	Y	3/3/2025	Visual insp at meter	
79515944	635 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377907	300 S MAIN ST	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	N			

76783506	431 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	C	Unknown	1996	SF	Installed after lead ban	Field inspection only	Y	2/26/2025	Visual insp at meter	
75583701	631 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378197	204 S MAIN ST	Unk	C	Unk	1"	1920	UNK-LG	Unknown	1920	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063699	433 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
75583656	627 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	C	Unknown	1992	SF	Installed after lead ban	Field inspection only	N	3/12/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377952	124 S MAIN ST	Unk	C	Unk		1910	C	Unknown	1910	SF	Installation record	Field inspection only	Y	7/12/2024	Other - describe in notes	
79515852	623 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515765	116 S MAIN ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	SF	Installed after lead ban	Field inspection only	N	12/17/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515639	435 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
76782962	619 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783596	437 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
78882623	385 CAMPBELL HILL	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583706	615 EAGLEWATCH D	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882251	441 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
75377759	601 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75377811	374 CAMPBELL HILL	Unk	C	Unk	1"	2005	C	Unknown	2005	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882358	439 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
75378258	603 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583264	376 CAMPBELL HILL	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646572	501 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
75377930	605 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
75378248	380 CAMPBELL HILL	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882613	503 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
75378036	607 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882330	505 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75583369	384 CAMPBELL HILL	Unk	C	Unk	1"	2004	UNK-NOLG	Unknown	2004	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882423	507 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
80063714	388 CAMPBELL HILL	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583418	609 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
86482115	392 CAMPBELL HILL	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377753	611 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583427	108 COMMERCE ST	Unk	UNK-NOLG	Unk		1910	UNK-LG	Unknown	1910	SF	Installed after lead ban	Field inspection only	Y	3/7/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583610	703 HILLTOP DR	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
96814995	613 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882561	216 MARKET ST	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377872	615 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783266	428 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
76783051	204 MARKET ST	Unk	UNK-NOLG	Unk		1892	UNK-LG	Unknown	1892	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377737	617 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882242	426 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75377733	125 COMMERCE ST	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	Y	6/25/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377778	619 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583242	117 COMMERCE ST	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378262	621 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
79515535	422 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75378257	113 COMMERCE ST	Unk	UNK-NOLG	Unk		1930	L	Unknown	1930	SF	Installed after lead ban	Field inspection only	Y	5/30/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583338	623 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
83119128	418 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75377990	105 COMMERCE ST	Unk	UNK-NOLG	Unk		1930	C	Unknown	1930	SF	Installed after lead ban	Field inspection only	Y	5/20/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646577	414 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
78882563	625 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
78882506	410 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75377950	101 COMMERCE ST	Unk	UNK-NOLG	Unk		1930	UNK-LG	Unknown	1930	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583281	627 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783211	408 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75377901	209 S MAIN ST	Unk	C	Unk	1"	1922	L	Unknown	1922	SF	Installation record	Field inspection only	Y	7/11/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583405	629 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882696	406 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75378002	213 S MAIN ST	Unk	C	Unk	1"	1920	UNK-LG	Unknown	1920	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377768	631 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
78882237	404 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	C	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N	2/26/2025		
75583591	304 MARKET ST	Unk	P	Unk	1"	1900	UNK-LG	Unknown	1900	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583255	633 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783636	402 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75583256	312 MARKET ST	Unk	P	Unk	1"	1910	C	Unknown	1910	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583313	635 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75377905	316 MARKET ST	Unk	P	N	1"	1925	G	Unknown	1925	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882238	411 MEADOW VIEW	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378168	637 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75377909	320 MARKET ST	Unk	P	Unk	1"	1900	UNK-LG	Unknown	1900	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783369	413 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377792	639 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75377895	116 E ELM ST	Unk	UNK-NOLG	Unk		1925	C	Unknown	1925	SF	Installed after lead ban	Field inspection only	Y	6/18/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882457	501 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583354	641 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75378207	112 E ELM ST	Unk	UNK-NOLG	N		1959	G	Unknown	1959	SF	Installed after lead ban	Field inspection only	Y	6/26/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882676	503 MEADOW VIEW	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583502	313 S MAIN ST	Unk	UNK-NOLG	Unk		1954	UNK-LG	Unknown	1954	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515719	505 MEADOW VIEW	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378205	115 E ELM ST	Unk	UNK-NOLG	Unk		1920	UNK-LG	Unknown	1920	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317831	507 MEADOW VIEW	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377969	645 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75378123	317 S MAIN ST	Unk	UNK-NOLG	N		1940	G	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	5/21/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882502	509 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377767	647 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
91921196	311 S MAIN ST	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
75583471	511 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377842	649 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583282	401 S MAIN ST	Unk	C	Unk	1"	1928	UNK-LG	Unknown	1928	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515644	513 MEADOW VIEW	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377824	651 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
75583416	405 S MAIN ST	Unk	C	Unk	1"	1924	C	Unknown	1924	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377845	653 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
76783571	515 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377954	409 S MAIN ST	Unk	C	Unk		1923	C	Unknown	1923	SF	Installation record	Field inspection only	N			
75377740	655 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
78882262	705 HILLTOP DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377983	104 W ELM ST	Unk	UNK-LG	Unk		1971	UNK-LG	Unknown	1971	SF			N			
78882244	708 HILLTOP DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75378181	657 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
79515694	710 HILLTOP DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75583366	108 W ELM ST	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	7/12/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377761	659 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
78882467	601 MEADOW VIEW	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583486	404 S MAIN ST	Unk	C	Unk	1"	1900	C	Unknown	1900	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377943	661 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
79317951	603 MEADOW VIEW	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782992	408 S MAIN ST	Unk	C	Unk	1"	1940	C	Unknown	1940	SF	Installation record	Field inspection only	Y	5/17/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583340	663 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
76783402	606 MEADOW VIEW	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783118	412 S MAIN ST	Unk	C	Unk	1"	1922	UNK-LG	Unknown	1922	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377770	665 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
78882321	604 MEADOW VIEW	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583367	416 S MAIN ST	Unk	C	Unk	1"	1922	UNK-LG	Unknown	1922	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377931	667 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
79515954	602 MEADOW VIEW	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378012	420 S MAIN ST	Unk	C	Unk	1"	1900	UNK-LG	Unknown	1900	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583235	669 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
78882419	800 HILLTOP DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583318	424 S MAIN ST	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378163	671 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
78882286	801 HILLTOP DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378042	116 SOUTH ST	Unk	UNK-NOLG	Unk		1954	C	Unknown	1954	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583393	673 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
76783288	508 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378195	417 MAPLE ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377828	413 MAPLE ST	Unk	UNK-LG	Unk		1953	UNK-LG	Unknown	1953	SF			N			
75377874	675 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
76783572	506 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063673	409 MAPLE ST	Unk	UNK-NOLG	Unk		1950	UNK-LG	Unknown	1950	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515927	504 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583449	677 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
75583398	405 MAPLE ST	Unk	UNK-NOLG	Unk		1955	UNK-LG	Unknown	1955	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882663	502 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377976	679 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
75377974	115 W ELM ST	Unk	C	Unk		1959	C	Unknown	1959	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes	
76783212	500 MEADOW VIEW	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378134	642 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
75378021	112 W ELM ST	Unk	UNK-NOLG	Unk		1967	UNK-LG	Unknown	1967	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78812129	801 PHEASANT LN	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75377847	640 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
75378130	116 W ELM ST	Unk	UNK-NOLG	Unk		1954	UNK-LG	Unknown	1954	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882277	803 PHEASANT LN	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378007	638 SPRINGBROOK I	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			

75378053	200 HILL ST	Unk	UNK-LG	Unk		1956	C	Unknown	1956	SF		Field inspection only	N		
78882323	803 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882557	636 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75583397	404 MAPLE ST	Unk	UNK-NOLG	Unk		1952	C	Unknown	1952	SF	Installed after lead ban	Field inspection only	N	3/13/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583349	634 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515770	807 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377826	408 MAPLE ST	Unk	UNK-NOLG	Unk		1950	UNK-LG	Unknown	1950	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882481	904 PHEASANT LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882413	632 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75378220	412 MAPLE ST	Unk	UNK-NOLG	Unk		1953	UNK-LG	Unknown	1953	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377988	630 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75378128	416 MAPLE ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377800	628 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
79317901	813 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378133	202 SOUTH ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	SF	Installed after lead ban	Field inspection only	Y	5/30/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317824	811 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378117	626 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
76782969	210 SOUTH ST	Unk	UNK-NOLG	Unk		1952	UNK-LG	Unknown	1952	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882249	809 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377766	218 SOUTH ST	Unk	UNK-NOLG	Unk		1947	UNK-LG	Unknown	1947	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377782	624 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
75583495	222 SOUTH ST	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882232	805 PHEASANT LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377787	622 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
78882292	901 PHEASANT LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583292	217 HILL ST	Unk	UNK-NOLG	Unk		1957	C	Unknown	1957	SF	Installed after lead ban	Field inspection only	Y	5/30/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377885	620 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
78882407	903 PHEASANT LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377937	213 HILL ST	Unk	C	Unk		1958	C	Unknown	1958	SF	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter
78882497	905 PHEASANT LN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377884	618 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
75377861	616 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
75583244	208 HILL ST	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N		
75377825	212 HILL ST	Unk	UNK-LG	Unk		1965	UNK-LG	Unknown	1965	SF			N		
79515672	907 PHEASANT LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583415	614 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
75378084	216 HILL ST	Unk	C	Unk	1"	1966	C	Unknown	1966	SF	Installation record	Field inspection only	N		Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377810	612 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
78882460	909 PHEASANT LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063715	220 HILL ST	Unk	UNK-NOLG	Unk		1958	C	Unknown	1958	SF	Installed after lead ban	Field inspection only	Y	5/28/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378085	610 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
76783478	911 PHEASANT LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882617	608 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
78882567	901 HILLTOP DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583389	318 SOUTH ST	Unk	C	Unk	1"	1955	UNK-LG	Unknown	1955	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377795	606 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
78882485	515 VALLEY DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378113	604 SPRINGBROOK (	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
79515802	513 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583387	315 SOUTH ST	Unk	C	Unk	1"	1966	UNK-LG	Unknown	1966	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783306	511 VALLEY DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646626	319 SOUTH ST	Unk	C	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377941	701 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783244	509 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515985	325 SOUTH ST	Unk	C	Unk	1"	1971	C	Unknown	1971	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377817	703 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783517	507 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318031	329 SOUTH ST	Unk	C	Unk	1"	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783521	505 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583231	333 SOUTH ST	Unk	C	Unk	1"	1965	UNK-LG	Unknown	1965	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378058	702 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
83646627	337 SOUTH ST	Unk	C	Unk	1"	1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783543	501 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377935	400 SOUTH ST	Unk	C	Unk	1"	1991	UNK-NOLG	Unknown	1991	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378153	706 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
76783458	402 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515891	338 SOUTH ST	Unk	C	Unk	1"	1996	UNK-NOLG	Unknown	1996	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583371	708 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
78882436	404 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783093	334 SOUTH ST	Unk	C	Unk		1900	C	Unknown	1900	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes
75377873	710 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882279	406 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288730	324 MEADOW LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882383	408 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
75583247	326 SOUTH ST	Unk	C	Unk	1"	1984	UNK-LG	Unknown	1984	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583355	714 CREEK EDGE DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		
76783246	410 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882601	504 S HILL ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
79515932	6991 WHITE DEER LI	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
78882466	407 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583342	600 S HILL ST	Unk	C	Unk		1965	UNK-LG	Unknown	1965	SF	Installation record		N		
88824643	111 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
76783538	405 PRAIRIE GRASS '	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378079	604 S HILL ST	Unk	C	Unk		1971	C	Unknown	1971	SF	Installation record	Field inspection only	Y	7/15/2024	Other - describe in notes
79515922	104 PARADISE CIR	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882486	504 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378008	608 S HILL ST	Unk	C	Unk		1965	C	Unknown	1965	SF	Installation record	Field inspection only	N		
83646579	112 PARADISE CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
78882438	506 VALLEY DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882498	601 S HILL ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
76783421	905 HILLTOP DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583332	605 S HILL ST	Unk	C	Unk		1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes
79515540	109 PARADISE CT	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882394	907 HILLTOP DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377793	609 S HILL ST	Unk	C	Unk		1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter
79317945	113 PARADISE CT	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882470	909 HILLTOP DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317896	115 PARADISE CT	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
76783233	911 HILLTOP DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583482	305 MEADOW LN	Unk	C	Unk		1968	C	Unknown	1968	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes
79317913	117 PARADISE CT	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882212	4764 HILLTOP DR	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	6/18/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583376	309 MEADOW LN	Unk	C	Unk		1964	UNK-LG	Unknown	1964	SF	Installation record		N		
79515572	121 PARADISE CIR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646571	4770 HILLTOP DR	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646545	123 PARADISE CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
78882548	4776 HILLTOP DR	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783070	304 MEADOW LN	Unk	C	Unk		1963	C	Unknown	1963	SF	Field inspection only	Field inspection only	Y	2/25/2025	Visual insp at meter
76783494	4784 HILLTOP DR	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515508	124 PARADISE CIR	Unk	C	Unk	1"	2002	C	Unknown	2002	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882646	308 MEADOW LN	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N		
78882515	7156 HILLTOP CIR	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063775	125 PARADISE CIR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515706	420 MABEL ST	Unk	C	Unk	1"	1977	UNK-LG	Unknown	1977	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515556	127 PARADISE CIR	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377982	316 MEADOW LN	Unk	C	Unk		1965	UNK-LG	Unknown	1965	SF	Installation record		N		
79318012	129 PARADISE CIR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317920	126 PARADISE CIR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378026	321 MEADOW LN	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe in notes
76783234	416 MABEL ST	Unk	C	Unk	1"	1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515971	131 PARADISE CIR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583362	325 MEADOW LN	Unk	C	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	N		
76783138	412 MABEL ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
79317801	133 PARADISE CIR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783523	408 MABEL ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
75583240	325 WOODVALE DR	Unk	C	Unk		1971	UNK-LG	Unknown	1971	SF	Installation record		N		
79515745	404 MABEL ST	Unk	C	Unk		1956	C	Unknown	1956	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
78882593	321 WOODVALE DR	Unk	C	Unk		1971	C	Unknown	1971	SF	Installation record	Field inspection only	Y	7/12/2024	Other - describe in notes
76783416	628 YAHARA ST	Unk	C	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000092	128 PARADISE CIR	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515920	317 WOODVALE DR	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	6/26/2024	Other - describe in notes
79515544	135 PARADISE CIR	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783419	624 YAHARA ST	Unk	C	Unk	1"	1960	C	Unknown	1960	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377913	313 WOODVALE DR	Unk	C	Unk		1971	C	Unknown	1971	SF	Installation record	Field inspection only	N		
79515586	137 PARADISE CIR	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646619	620 YAHARA ST	Unk	C	Unk	1"	1993	UNK-NOLG	Unknown	1993	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515629	139 PARADISE CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
75378198	309 WOODVALE DR	Unk	C	Unk		1968	UNK-LG	Unknown	1968	SF	Installation record		N		
76782905	616 YAHARA ST	Unk	C	Unk	1"	1958	UNK-LG	Unknown	1958	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377849	305 WOODVALE DR	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
78882315	528 LINDE ST	Unk	UNK-LG	Unk		1949	C	Unknown	1949	SF		Field inspection only	N		
79515627	101 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N		
75377902	501 S HILL ST	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	N		
79318052	103 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2002	C	Unknown	2002	SF	Installed after lead ban	Field inspection only	Y	3/3/2025	Visual insp at meter
75583277	211 SOUTH ST	Unk	UNK-NOLG	Unk		1969	UNK-LG	Unknown	1969	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export

76783606	500 LINDE ST	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		
79317921	105 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
82753290	207 SOUTH ST	Unk	UNK-NOLG	Unk		1966	UNK-LG	Unknown	1966	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317910	107 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
76783068	105 SOUTH ST	Unk	UNK-NOLG	Unk		1967	UNK-LG	Unknown	1967	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783522	208 MADISON AVE	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N		
79515573	109 OAK SPRINGS CI	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
75378051	103 SOUTH ST	Unk	UNK-NOLG	Unk		1969	UNK-LG	Unknown	1969	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515700	444 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1946	UNK-LG	Unknown	1946	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515618	6854 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
79515575	101 SOUTH ST	Unk	UNK-NOLG	Unk		1973	C	Unknown	1973	SF	Installed after lead ban	Field inspection only	Y	7/10/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783607	440 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318050	6856 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
75378187	108 MEADOW LN	Unk	C	Unk		1986	UNK-LG	3/4"	1986	SF	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter
76783447	436 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1906	UNK-LG	Unknown	1906	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317948	6858 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75378219	112 MEADOW LN	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N		
79318033	432 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1923	UNK-LG	Unknown	1923	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317944	6860 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75377797	116 MEADOW LN	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N		
79515567	6862 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76783537	428 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1920	L	Unknown	1920	SF	Installed after lead ban	Field inspection only	Y	7/25/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377829	120 MEADOW LN	Unk	C	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installation record	Installed after lead ban	N		
79515701	424 COLUMBIA AVE	Unk	UNK-LG	Unk		1902	UNK-LG	Unknown	1902	SF			N		
79515563	6864 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
79515882	200 MEADOW LN	Unk	C	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installation record	Installed after lead ban	N		
79515716	6866 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76782899	420 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	5/22/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515729	6868 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75377869	213 MEADOW LN	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	6/10/2024	Other - describe in notes
79318049	416 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1920	UNK-LG	Unknown	1920	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063785	6870 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75377981	700 MEADOW CT	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N		
78882591	704 MEADOW CT	Unk	C	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		
79515785	404 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1920	C	Unknown	1920	SF	Installed after lead ban	Field inspection only	Y	5/16/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230686	6871 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79515702	400 COLUMBIA AVE	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	5/13/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583236	705 MEADOW CT	Unk	C	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		
84230690	6873 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75378145	701 MEADOW CT	Unk	C	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N		
76783595	209 N STEVENSON S	Unk	UNK-NOLG	N		1900	G	Unknown	1900	SF	Installed after lead ban	Field inspection only	Y	5/21/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515834	6874 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75377948	117 MEADOW LN	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
83646594	113 MEADOW LN	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		
83119134	6878 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
78882214	409 LINDE ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	SF	Installed after lead ban	Field inspection only	Y	5/14/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378077	109 MEADOW LN	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
83119149	6880 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
78882369	413 LINDE ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	SF	Installed after lead ban	Field inspection only	Y	5/31/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646618	6882 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
76783364	417 LINDE ST	Unk	UNK-NOLG	Unk		1945	UNK-LG	Unknown	1945	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377860	708 S MAIN ST	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
84938912	6886 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75377886	710 S MAIN ST	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N		
84938916	6888 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
78882494	425 LINDE ST	Unk	UNK-NOLG	Unk		1959	UNK-LG	Unknown	1959	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783162	712 S MAIN ST	Unk	C	Unk		1985	UNK-LG	Unknown	1985	SF	Installation record		N		
78882317	429 LINDE ST	Unk	UNK-NOLG	Unk		1955	C	Unknown	1955	SF	Installed after lead ban	Field inspection only	N	1/10/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230696	6887 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75583258	714 S MAIN ST	Unk	C	Unk		1985	UNK-LG	Unknown	1985	SF	Installation record		N		
76783345	433 LINDE ST	Unk	UNK-NOLG	Unk		1959	C	Unknown	1959	SF	Installed after lead ban	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230691	6889 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75583257	716 S MAIN ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
78882375	440 LINDE ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938885	6890 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583406	718 S MAIN ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes
76783296	436 LINDE ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	SF	Installed after lead ban	Field inspection only	Y	6/3/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515416	6892 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
76783388	432 LINDE ST	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515398	6894 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583295	720 S MAIN ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76783393	428 LINDE ST	Unk	UNK-NOLG	Unk		1973	UNK-LG	Unknown	1973	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515392	6896 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583299	722 S MAIN ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
76783267	424 LINDE ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377747	724 S MAIN ST	Unk	C	Unk	1"	1900	C	Unknown	1900	SF	Installation record	Field inspection only	Y	5/6/2024	Visual insp at meter
79515558	6898 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
76783546	420 LINDE ST	Unk	UNK-NOLG	Unk		1941	UNK-LG	Unknown	1941	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377929	728 S MAIN ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
79515751	6900 TUSCAN RIDGE	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783297	416 LINDE ST	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	5/16/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378023	730 S MAIN ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
79317817	6897 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
83646595	6899 TUSCAN RIDGE	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75377775	732 S MAIN ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
79515968	408 LINDE ST	Unk	UNK-NOLG	Unk		1930	C	3/4"	1930	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515524	4646 AUTUMN BLA2	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515634	4642 AUTUMN BLA2	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583525	301 N STEVENSON S	Unk	UNK-NOLG	Unk		1930	UNK-LG	Unknown	1930	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377802	734 S MAIN ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
79000089	4638 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882433	307 N STEVENSON S	Unk	UNK-NOLG	Unk		1925	C	Unknown	1925	SF	Installed after lead ban	Field inspection only	Y	5/28/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783060	736 S MAIN ST	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N		
79515506	4634 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783561	311 N STEVENSON S	Unk	UNK-NOLG	Unk		1953	UNK-LG	Unknown	1953	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583289	738 S MAIN ST	Unk	C	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installation record	Installed after lead ban	N		
75378109	100 VINBURN RD	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
75583467	409 YAHARA ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N		
75378121	124 MEADOW LN	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N		
78882327	417 YAHARA ST	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317899	4630 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583453	501 S MAIN ST	Unk	C	Unk		1967	C	Unknown	1967	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882354	429 YAHARA ST	Unk	C	Unk	1"	1960	C	Unknown	1960	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377805	105 MURRAY ST	Unk	UNK-NOLG	Unk		1964	UNK-LG	Unknown	1964	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515505	4626 AUTUMN BLA2	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783589	433 YAHARA ST	Unk	C	Unk	1"	1950	UNK-LG	Unknown	1950	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377900	109 MURRAY ST	Unk	UNK-NOLG	Unk		1966	C	Unknown	1966	SF	Installed after lead ban	Field inspection only	Y	3/4/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317934	4622 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783472	437 YAHARA ST	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N		
75378030	113 MURRAY ST	Unk	UNK-NOLG	Unk		1962	C	Unknown	1962	SF	Installed after lead ban	Field inspection only	Y	5/13/2024	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515380	4618 AUTUMN BLA2	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583322	4614 AUTUMN BLA2	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583520	117 MURRAY ST	Unk	UNK-NOLG	Unk		1978	UNK-LG	Unknown	1978	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882573	449 YAHARA ST	Unk	C	Unk	1"	1930	UNK-LG	Unknown	1930	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317814	4610 AUTUMN BLA2	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583508	112 MURRAY ST	Unk	UNK-NOLG	N		1975	G	Unknown	1975	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515640	4606 AUTUMN BLA2	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377897	116 MURRAY ST	Unk	UNK-LG	Unk		1916	UNK-LG	Unknown	1916	SF			N		
78882265	513 YAHARA ST	Unk	C	Unk	1"	1956	UNK-LG	Unknown	1956	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063783	4602 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377746	124 MURRAY ST	Unk	UNK-NOLG	Unk		1959	UNK-LG	Unknown	1959	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882264	517 YAHARA ST	Unk	C	Unk	1"	1974	C	Unknown	1974	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317926	4598 AUTUMN BLA2	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378192	412 MARKET ST	Unk	UNK-NOLG	Unk		1940	UNK-LG	Unknown	1940	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783453	512 YAHARA ST	Unk	C	Unk	1"	1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515569	4599 SUNBURST DR	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75377926	410 MARKET ST	Unk	UNK-NOLG	Unk		1978	DI	Unknown	1978	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80276301	405 ANDERSON ST	Unk	C	Unk	1"	1968	UNK-LG	Unknown	1968	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515740	4603 SUNBURST DR	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378225	404 MARKET ST	Unk	UNK-NOLG	Unk		1909	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318013	4607 SUNBURST DR	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882508	409 ANDERSON ST	Unk	C	Unk		1967	UNK-LG	Unknown	1967	SF	Installation record		N		
75378182	400 MARKET ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317907	4611 SUNBURST DR	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783441	413 ANDERSON ST	Unk	C	Unk		1965	C	Unknown	1965	SF	Installation record	Field inspection only	Y	5/6/2024	
79515921	509 S HILL ST	Unk	C	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N		
76783175	4615 SUNBURST DR	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882607	417 ANDERSON ST	Unk	C	Unk		1958	C	Unknown	1958	SF	Installation record	Field inspection only	Y	7/12/2024	Other - describe in notes
75377730	301 ACKER PKWY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N		
79317928	4619 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882566	421 ANDERSON ST	Unk	C	Unk		1970	UNK-LG	Unknown	1970	SF	Installation record		N		
80063662	425 ANDERSON ST	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	N		
79515588	4623 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882588	305 ACKER PKWY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
78882660	429 ANDERSON ST	Unk	C	Unk		1970	UNK-LG	Unknown	1970	SF	Installation record		N		

83646560	4627 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378019	309 ACKER PKWY	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	5/29/2024	Other - describe in notes	
75377868	313 ACKER PKWY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Other - describe in notes	N			
78882568	424 ANDERSON ST	Unk	C	Unk		1966	UNK-LG	Unknown	1966	SF	Installation record		N			
79318054	4635 SUNBURST DR	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378218	317 ACKER PKWY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N			
78882560	420 ANDERSON ST	Unk	C	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes	
75583460	4639 SUNBURST DR	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378111	401 ACKER PKWY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N			
76783413	416 ANDERSON ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
75377791	6822 CONSERVANCY	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583401	405 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882266	412 ANDERSON ST	Unk	C	Unk		1960	C	Unknown	1960	SF	Installation record	Field inspection only	N			
79515633	6818 CONSERVANCY	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583315	409 ACKER PKWY	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N			
79515914	6814 CONSERVANCY	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515676	404 ANDERSON ST	Unk	C	Unk		1964	UNK-LG	Unknown	1964	SF	Installation record		N			
79515520	6810 CONSERVANCY	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377936	413 ACKER PKWY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	N			
76783464	401 N STEVENSON S	Unk	C	Unk	1"	1962	C	Unknown	1962	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583494	4634 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377891	501 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882345	405 N STEVENSON S	Unk	UNK-NOLG	Unk		1954	C	Unknown	1954	SF	Installed after lead ban	Field inspection only	Y	6/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782942	4630 PRAIRIE FIRE C	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583260	505 ACKER PKWY	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	6/19/2024	Other - describe in notes	
75378160	509 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	5/16/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583463	4626 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783639	409 N STEVENSON S	Unk	UNK-NOLG	Unk		1960	UNK-LG	Unknown	1960	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583483	4622 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583253	513 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783332	413 N STEVENSON S	Unk	UNK-NOLG	Unk		1956	UNK-LG	Unknown	1956	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378208	4618 PRAIRIE FIRE C	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783269	417 N STEVENSON S	Unk	UNK-NOLG	Unk		1961	UNK-LG	Unknown	1961	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583276	521 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	C	Unknown	1976	SF	Installed after lead ban	Field inspection only	Y	5/23/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583492	4614 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515754	4610 PRAIRIE FIRE C	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378131	525 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063701	421 N STEVENSON S	Unk	UNK-NOLG	Unk		1959	UNK-LG	Unknown	1959	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515620	4606 PRAIRIE FIRE C	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583380	529 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783558	425 N STEVENSON S	Unk	UNK-NOLG	Unk		1957	UNK-LG	Unknown	1957	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318039	4602 PRAIRIE FIRE C	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783307	440 W LINCOLN DR	Unk	UNK-NOLG	Unk		1969	UNK-LG	Unknown	1969	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377839	533 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	6/11/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783226	436 W LINCOLN DR	Unk	UNK-NOLG	Unk		1964	C	Unknown	1964	SF	Installed after lead ban	Field inspection only	Y	6/3/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583358	537 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515555	4598 PRAIRIE FIRE C	Unk	UNK-NOLG	Unk		2012	UNK-NOLG	Unknown	2012	SF	Installed after lead ban		N			
79515790	432 W LINCOLN DR	Unk	UNK-NOLG	Unk		1971	UNK-LG	Unknown	1971	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317823	4594 PRAIRIE FIRE C	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583512	601 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783445	428 W LINCOLN DR	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	SF	Installed after lead ban	Field inspection only	Y	6/26/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583458	4591 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783427	424 W LINCOLN DR	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	SF	Installed after lead ban	Field inspection only	Y	7/16/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000094	4595 PRAIRIE FIRE C	Unk	C	Unk	1"	2009	UNK-NOLG	Unknown	2009	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583359	605 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	5/17/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783624	420 W LINCOLN DR	Unk	UNK-NOLG	Unk		1971	UNK-LG	Unknown	1971	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515594	4599 PRAIRIE FIRE C	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583424	613 ACKER PKWY	Unk	UNK-NOLG	Unk		1979	UNK-LG	Unknown	1979	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938884	416 W LINCOLN DR	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N			
79317816	4603 PRAIRIE FIRE C	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882539	412 W LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377738	617 ACKER PKWY	Unk	UNK-NOLG	Unk		1978	C	Unknown	1978	SF	Installed after lead ban	Field inspection only	Y	5/15/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317849	4607 PRAIRIE FIRE C	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377999	621 ACKER PKWY	Unk	UNK-NOLG	Unk		1978	C	Unknown	1978	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317924	4611 PRAIRIE FIRE C	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783276	408 W LINCOLN DR	Unk	C	Unk		1970	C	Unknown	1970	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes	
75583377	625 ACKER PKWY	Unk	UNK-NOLG	Unk		1983	UNK-LG	Unknown	1983	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317931	4615 PRAIRIE FIRE C	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882519	409 E LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377855	629 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	5/16/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583488	4619 PRAIRIE FIRE C	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646542	413 E LINCOLN DR	Unk	UNK-NOLG	Unk		1965	UNK-LG	Unknown	1965	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515501	4623 PRAIRIE FIRE C	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583363	633 ACKER PKWY	Unk	UNK-NOLG	Unk		1986	C	Unknown	1986	SF	Installed after lead ban	Field inspection only	Y	5/15/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882547	417 E LINCOLN DR	Unk	UNK-LG	Unk		1964	UNK-LG	Unknown	1964	SF			N			
75377758	701 ACKER PKWY	Unk	UNK-NOLG	Unk		1984	C	Unknown	1984	SF	Installed after lead ban	Field inspection only	Y	5/15/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317853	4627 PRAIRIE FIRE C	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783542	421 E LINCOLN DR	Unk	UNK-NOLG	Unk		1971	C	Unknown	1971	SF	Installed after lead ban	Field inspection only	Y	7/10/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377865	705 ACKER PKWY	Unk	UNK-NOLG	Unk		1981	C	Unknown	1981	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515705	4631 PRAIRIE FIRE C	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515570	425 E LINCOLN DR	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515826	4635 PRAIRIE FIRE C	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783282	429 E LINCOLN DR	Unk	UNK-NOLG	Unk		1965	C	Unknown	1965	SF	Installed after lead ban	Field inspection only	Y	7/10/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378124	709 ACKER PKWY	Unk	UNK-NOLG	Unk		1981	C	Unknown	1981	SF	Installed after lead ban	Field inspection only	Y	6/27/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583238	713 ACKER PKWY	Unk	UNK-NOLG	Unk		1981	UNK-LG	Unknown	1981	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515669	4639 PRAIRIE FIRE C	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515592	6806 CONSERVANCY	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377836	717 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	6/3/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515496	6802 CONSERVANCY	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882239	437 E LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646556	721 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	UNK-LG	Unknown	1982	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882526	441 E LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583379	725 ACKER PKWY	Unk	UNK-NOLG	Unk		1983	C	Unknown	1983	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065432	6742 CONSERVANCY	Unk	P	Unk	1-1/2"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318010	428 E LINCOLN DR	Unk	UNK-NOLG	Unk		1971	C	Unknown	1971	SF	Installed after lead ban	Field inspection only	Y	5/6/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583347	729 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	UNK-LG	Unknown	1982	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065429	6738 CONSERVANCY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75377736	801 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	6/21/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646550	424 E LINCOLN DR	Unk	UNK-NOLG	Unk		1963	C	Unknown	1963	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065440	6734 CONSERVANCY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75583357	805 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515536	420 E LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063724	416 E LINCOLN DR	Unk	UNK-NOLG	Unk		1972	C	Unknown	1972	SF	Installed after lead ban	Field inspection only	Y	6/20/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377790	809 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	Y	6/3/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065436	6730 CONSERVANCY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75377854	813 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	Y	5/22/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882348	412 E LINCOLN DR	Unk	UNK-NOLG	Unk		1970	UNK-LG	Unknown	1970	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065437	6726 CONSERVANCY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75583262	817 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
79317819	413 W LINCOLN DR	Unk	UNK-NOLG	Unk		1968	UNK-LG	Unknown	1968	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065441	6722 CONSERVANCY	Unk	P	Unk	1-1/2"	2020	P	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783400	417 W LINCOLN DR	Unk	UNK-NOLG	Unk		1963	UNK-LG	Unknown	1963	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824612	6524 TRAILS EDGE C	Unk	P	Unk	1-1/2"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583360	825 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882627	421 W LINCOLN DR	Unk	UNK-NOLG	Unk		1961	C	Unknown	1961	SF	Installed after lead ban	Field inspection only	Y	5/29/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824613	6520 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75377898	829 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783582	425 W LINCOLN DR	Unk	UNK-NOLG	Unk		1963	C	Unknown	1963	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065439	6516 TRAILS EDGE C	Unk	P	Unk	1-1/2"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378071	833 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515696	429 W LINCOLN DR	Unk	UNK-NOLG	Unk		1959	UNK-LG	Unknown	1959	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065430	6512 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75583433	837 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882363	420 NORTHVIEW CT	Unk	P	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515654	6823 CONSERVANCY	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882210	416 NORTHVIEW CT	Unk	C	Unk		1975	UNK-LG	Unknown	1975	SF	Installation record		N			
75377823	841 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317914	6827 CONSERVANCY	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882385	412 NORTHVIEW CT	Unk	C	Unk		1975	UNK-LG	Unknown	1975	SF	Installation record		N			
75377764	901 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515663	6831 CONSERVANCY	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783363	408 NORTHVIEW CT	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
75378067	905 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515589	6835 CONSERVANCY	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783634	404 NORTHVIEW CT	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
79515545	6839 CONSERVANCY	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783505	401 NORTHVIEW CT	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	6/27/2024	Other - describe in notes	
82753304	6843 CONSERVANCY	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377846	913 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317852	6847 CONSERVANCY	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882625	405 NORTHVIEW CT	Unk	C	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N			
75583317	917 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583588	6851 CONSERVANCY	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378118	921 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783395	601 NORTHVIEW CII	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	

75583444	4629 AUTUMN BLA2	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378146	925 ACKER PKWY	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783305	605 NORTHVIEW CII	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes	
79515513	4625 AUTUMN BLA2	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583272	929 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882414	609 NORTHVIEW CII	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N			
75377892	933 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515580	4621 AUTUMN BLA2	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783248	613 NORTHVIEW CII	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes	
79515598	4617 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583422	937 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
76783429	610 NORTHVIEW CII	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes	
79318051	4613 AUTUMN BLA2	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515894	936 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
76783553	606 NORTHVIEW CII	Unk	C	Unk		1975	UNK-LG	Unknown	1975	SF	Installation record		N			
75377867	932 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515543	4609 AUTUMN BLA2	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783401	415 NORTHVIEW CT	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
75583445	928 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515549	4610 SUNBURST DR	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377819	924 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882347	419 NORTHVIEW CT	Unk	P	Unk	1"	1976	C	Unknown	1976	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515579	4614 SUNBURST DR	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783422	605 E NORTH ST	Unk	P	Unk	1"	1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515797	609 E NORTH ST	Unk	P	Unk	1"	1977	UNK-LG	Unknown	1977	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515641	4618 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377906	920 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783530	428 N STEVENSON S	Unk	UNK-LG	Unk		1958	UNK-LG	Unknown	1958	SF			N			
82753258	4622 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583234	916 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515623	424 N STEVENSON S	Unk	UNK-NOLG	Unk		1958	C	Unknown	1958	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583477	4626 SUNBURST DR	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378017	912 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882230	420 N STEVENSON S	Unk	UNK-NOLG	Unk		1957	UNK-LG	Unknown	1957	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515605	4630 SUNBURST DR	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515402	416 N STEVENSON S	Unk	UNK-NOLG	Unk		1955	C	Unknown	1955	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583316	908 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318014	4634 SUNBURST DR	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783605	408 N STEVENSON S	Unk	UNK-NOLG	Unk		1950	UNK-LG	Unknown	1950	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378226	904 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318025	4638 SUNBURST DR	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783604	320 N STEVENSON S	Unk	UNK-NOLG	Unk		1945	UNK-LG	Unknown	1945	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515557	4642 SUNBURST DR	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377989	900 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783440	404 N STEVENSON S	Unk	UNK-NOLG	Unk		1970	P	Unknown	1970	SF	Installed after lead ban	Field inspection only	Y	6/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000058	6834 CONSERVANCI	Unk	C	Unk	1"	2005	UNK-NOLG	Unknown	2005	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583383	836 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	C	Unknown	1988	SF	Installed after lead ban	Field inspection only	Y	3/4/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515418	6838 CONSERVANCI	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583511	832 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882274	6842 CONSERVANCI	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515707	6846 CONSERVANCI	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583517	828 ACKER PKWY	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
78882534	308 N STEVENSON S	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	Y	7/15/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318008	6850 CONSERVANCI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583265	824 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938902	6786 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75377923	820 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938904	6790 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75378074	816 ACKER PKWY	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
83646559	220 N STEVENSON S	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515988	812 ACKER PKWY	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783265	216 N STEVENSON S	Unk	UNK-NOLG	Unk		1954	UNK-LG	Unknown	1954	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378061	808 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	Y	7/2/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938920	6798 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882605	212 N STEVENSON S	Unk	UNK-LG	Unk		1945	UNK-LG	Unknown	1945	SF			N			
75378115	804 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482113	6782 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882421	208 N STEVENSON S	Unk	UNK-NOLG	Unk		1940	C	Unknown	1940	SF	Installed after lead ban	Field inspection only	N	1/22/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938921	6778 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783333	204 N STEVENSON S	Unk	UNK-LG	Unk		1940	UNK-LG	Unknown	1940	SF			N			
75378103	800 ACKER PKWY	Unk	UNK-NOLG	Unk		1983	UNK-LG	Unknown	1983	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482132	6770 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75378004	728 ACKER PKWY	Unk	UNK-NOLG	Unk		1983	UNK-LG	Unknown	1983	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882350	316 COLUMBIA AVE	Unk	C	Unk		1900	L	Unknown	1900	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646623	724 ACKER PKWY	Unk	UNK-LG	Unk		1985	C	Unknown	1985	SF		Field inspection only	N			
78882227	118 N STEVENSON S	Unk	P	Unk	1"	1927	L	Unknown	1927	SF	Installation record	Field inspection only	Y	3/12/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882204	114 N STEVENSON S	Unk	UNK-NOLG	Unk		1907	UNK-LG	Unknown	1907	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378120	720 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783331	110 N STEVENSON S	Unk	UNK-NOLG	Unk		1900	UNK-LG	Unknown	1900	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583374	716 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	5/20/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482134	6754 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882584	104 N STEVENSON S	Unk	UNK-NOLG	Unk		1951	UNK-LG	Unknown	1951	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377750	712 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	C	Unknown	1985	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482130	6750 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783396	309 COLUMBIA AVE	Unk	P	Unk	1"	1930	C	Unknown	1930	SF	Installation record	Field inspection only	Y	6/10/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378105	708 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	UNK-LG	Unknown	1982	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482131	6746 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882536	117 N DURKEE ST	Unk	P	Unk	1"	1940	UNK-LG	Unknown	1940	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378150	704 ACKER PKWY	Unk	UNK-NOLG	Unk		1983	UNK-LG	Unknown	1983	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783254	109 N STEVENSON S	Unk	UNK-NOLG	Unk		1900	L	Unknown	1900	SF	Installed after lead ban	Field inspection only	Y	5/23/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288716	6545 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
87288715	6541 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882333	115 N STEVENSON S	Unk	UNK-NOLG	Unk		1945	UNK-LG	Unknown	1945	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583243	700 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	5/22/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288713	6537 CONSERVANCI	Unk	P	Unk	1-1/2"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583296	632 ACKER PKWY	Unk	UNK-NOLG	Unk		1985	UNK-LG	Unknown	1985	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882401	416 E HOLUM ST	Unk	C	Unk		1965	C	Unknown	1965	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes	
86741044	6533 CONSERVANCI	Unk	P	Unk	1-1/2"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583394	628 ACKER PKWY	Unk	UNK-NOLG	Unk		1982	C	Unknown	1982	SF	Installed after lead ban	Field inspection only	Y	5/20/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783191	428 E HOLUM ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N			
75378169	624 ACKER PKWY	Unk	UNK-NOLG	Unk		1979	UNK-LG	Unknown	1979	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783614	432 E HOLUM ST	Unk	UNK-LG	Unk		1895	L	Unknown	1895	SF		Field inspection only	Y	3/3/2025	Visual insp at meter	
79318006	620 ACKER PKWY	Unk	UNK-NOLG	Unk		1978	UNK-LG	Unknown	1978	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378201	616 ACKER PKWY	Unk	UNK-NOLG	Unk		1979	UNK-LG	Unknown	1979	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741050	6521 CONSERVANCI	Unk	P	Unk	1-1/2"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882224	540 E HOLUM ST	Unk	C	Unk		1920	C	Unknown	1920	SF	Installation record	Field inspection only	Y	6/24/2024	Other - describe in notes	
86482126	6513 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
79515731	612 ACKER PKWY	Unk	UNK-NOLG	Unk		1980	UNK-LG	Unknown	1980	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482137	6517 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75583343	608 ACKER PKWY	Unk	UNK-NOLG	Unk		1979	C	Unknown	1979	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515703	100 N CLEVELAND A	Unk	C	Unk		1955	C	Unknown	1955	SF	Installation record	Field inspection only	Y	7/8/2024	Other - describe in notes	
86741036	6509 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882349	616 PARK AVE	Unk	P	Unk	1"	1971	C	Unknown	1971	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377784	604 ACKER PKWY	Unk	UNK-NOLG	Unk		1979	UNK-LG	Unknown	1979	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741035	6505 CONSERVANCI	Unk	P	Unk	1-1/2"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063693	624 RUSSELL ST	Unk	P	Unk	1"	1970	UNK-LG	Unknown	1970	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741041	6504 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
79515529	700 RUSSELL ST	Unk	P	Unk	1"	1969	UNK-LG	Unknown	1969	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583290	600 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741046	6508 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783337	704 RUSSELL ST	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288700	6512 CONSERVANCI	Unk	P	Unk	1-1/2"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377970	536 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	5/17/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783078	708 RUSSELL ST	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741040	6516 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75377756	532 ACKER PKWY	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF		Field inspection only	Y	5/28/2024	Other - describe in notes	
87288728	6520 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75583504	528 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	C	Unknown	1976	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515805	716 RUSSELL ST	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288722	6524 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783597	720 RUSSELL ST	Unk	P	Unk	1"	1973	UNK-LG	Unknown	1973	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378214	524 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741048	6538 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
78882296	724 RUSSELL ST	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378255	520 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	5/6/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741049	6542 CONSERVANCI	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783457	725 RUSSELL ST	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583304	516 ACKER PKWY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
79515599	6871 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N			
80063780	721 RUSSELL ST	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583330	512 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515760	6869 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N			
76783415	717 RUSSELL ST	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377971	508 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646575	6867 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N			

75583443	504 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	3/6/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783641	709 RUSSELL ST	Unk	P	Unk	1"	1971	C	Unknown	1971	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583411	500 ACKER PKWY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N		
79515681	6865 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
79515981	412 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	N		
76783493	705 RUSSELL ST	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318015	6863 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
78882673	701 RUSSELL ST	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583506	408 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	UNK-LG	Unknown	1977	SF	Installed after lead ban		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119159	6861 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
78882512	621 RUSSELL ST	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583364	404 ACKER PKWY	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	SF	Installed after lead ban	Field inspection only	Y	5/24/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515551	6859 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
78882293	617 RUSSELL ST	Unk	P	Unk	1"	1973	C	Unknown	1973	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515911	6857 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
76783299	620 PARK AVE	Unk	P	Unk	1"	1983	C	Unknown	1983	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377933	400 ACKER PKWY	Unk	UNK-NOLG	Unk		1976	C	Unknown	1976	SF	Installed after lead ban	Field inspection only	Y	6/4/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063734	6855 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
79317917	500 HANKS HOLLOW	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
78882360	700 PARK AVE	Unk	P	Unk	1"	1969	UNK-LG	Unknown	1969	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515710	6853 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75377748	504 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	7/17/2024	Other - describe in notes
79515793	704 PARK AVE	Unk	P	Unk	1"	1969	UNK-LG	Unknown	1969	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583514	508 HANKS HOLLOW	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
78882198	708 PARK AVE	Unk	P	Unk	1"	1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515822	6849 YELLOWWOOI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
75377739	512 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes
78882379	712 PARK AVE	Unk	P	Unk	1"	1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318029	6819 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783242	716 PARK AVE	Unk	P	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583333	516 HANKS HOLLOW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
79515657	6817 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
79515746	720 PARK AVE	Unk	P	Unk	1"	1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	7/2/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378029	520 HANKS HOLLOW	Unk	C	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N		
79515699	6815 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783640	724 PARK AVE	Unk	P	Unk	1"	1993	UNK-NOLG	Unknown	1993	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583497	528 HANKS HOLLOW	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
83646546	6813 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
75377977	532 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
79515964	6811 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
79515798	721 PARK AVE	Unk	P	Unk	1"	1971	UNK-LG	Unknown	1971	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377858	600 HANKS HOLLOW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes
79515761	6809 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783245	717 PARK AVE	Unk	P	Unk	1"	1973	UNK-LG	Unknown	1973	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583378	604 HANKS HOLLOW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
79515552	6807 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
78882240	713 PARK AVE	Unk	P	Unk	1"	1968	UNK-LG	Unknown	1968	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583274	608 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		
79317848	6805 YELLOWWOOI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
79318032	709 PARK AVE	Unk	P	Unk	1"	1968	C	Unknown	1968	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583413	612 HANKS HOLLOW	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
79318034	6751 VILLAGE WALK	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
75583515	629 HANKS HOLLOW	Unk	C	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installation record	Installed after lead ban	N		
79515502	6753 VILLAGE WALK	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783295	705 PARK AVE	Unk	UNK-LG	Unk		1965	UNK-LG	Unknown	1965	SF			N		
76782918	213 N JOHNSON ST	Unk	C	Unk	1"	1953	UNK-LG	Unknown	1953	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583348	625 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes
79000088	6757 VILLAGE WALK	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
76783619	209 N JOHNSON ST	Unk	C	Unk	1"	1955	C	Unknown	1955	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378038	621 HANKS HOLLOW	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
76783355	6761 VILLAGE WALK	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
76783444	205 N JOHNSON ST	Unk	C	Unk	1"	1955	C	Unknown	1955	SF	Installation record	Field inspection only	Y	5/27/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377780	617 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes
79515803	704 COLUMBIA AVE	Unk	UNK-LG	Unk		1957	UNK-LG	Unknown	1957	SF			N		
76783359	6763 VILLAGE WALK	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
75583384	613 HANKS HOLLOW	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/17/2024	Other - describe in notes
76782970	6765 VILLAGE WALK	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
78882541	708 COLUMBIA AVE	Unk	C	Unk	1"	1960	UNK-LG	Unknown	1960	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783062	609 HANKS HOLLOW	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
76783181	605 HANKS HOLLOW	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe in notes
76782964	6767 VILLAGE WALK	Unk	UNK-NOLG	Unk		2014	UNK-NOLG	Unknown	2014	SF	Installed after lead ban	Installed after lead ban	N		
76783275	712 COLUMBIA AVE	Unk	C	Unk	1"	1959	UNK-LG	Unknown	1959	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583294	601 HANKS HOLLOW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes
79317919	6771 VILLAGE WALK	Unk	UNK-NOLG	Unk		2010	UNK-NOLG	Unknown	2010	SF	Installed after lead ban	Installed after lead ban	N		
78882505	716 COLUMBIA AVE	Unk	C	Unk	1"	1965	C	Unknown	1965	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378252	509 WOODVALE DR	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
79317821	6775 VILLAGE WALK	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
83119157	720 COLUMBIA AVE	Unk	C	Unk	1"	1965	UNK-LG	Unknown	1965	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583499	604 SHAGBARK LN	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter
79317915	6777 VILLAGE WALK	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
78882425	724 COLUMBIA AVE	Unk	C	Unk	1"	1967	C	Unknown	1967	SF	Installation record	Field inspection only	Y	6/3/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000093	6781 VILLAGE WALK	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
76783403	728 COLUMBIA AVE	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N		
75583399	608 SHAGBARK LN	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
79317818	6783 VILLAGE WALK	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
78882393	216 N HALSOR ST	Unk	UNK-LG	Unk		1968	UNK-LG	Unknown	1968	SF			N		
79000078	6785 VILLAGE WALK	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
75583356	612 SHAGBARK LN	Unk	C	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N		
79000071	6787 VILLAGE WALK	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
75378194	616 SHAGBARK LN	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N		
79515848	6791 VILLAGE WALK	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76783650	737 COLUMBIA AVE	Unk	C	Unk	1"	1945	UNK-LG	Unknown	1945	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377830	621 SHAGBARK LN	Unk	C	Unk	1"	1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515849	6793 VILLAGE WALK	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
78882622	725 COLUMBIA AVE	Unk	C	Unk	1"	1920	UNK-LG	Unknown	1920	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377745	617 SHAGBARK LN	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	6/5/2024	Other - describe in notes
83646553	6795 VILLAGE WALK	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
78882449	721 COLUMBIA AVE	Unk	C	Unk	1"	1952	C	Unknown	1952	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377912	613 SHAGBARK LN	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
79515975	609 SHAGBARK LN	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
83646554	6797 VILLAGE WALK	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
78882374	717 COLUMBIA AVE	Unk	C	Unk	1"	1952	C	Unknown	1952	SF	Installation record	Field inspection only	Y	6/19/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783311	713 COLUMBIA AVE	Unk	C	Unk	1"	1959	UNK-LG	Unknown	1959	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317932	6816 REDSPIRE LN	Unk	UNK-NOLG	Unk		2010	UNK-NOLG	Unknown	2010	SF	Installed after lead ban	Installed after lead ban	N		
75583493	605 SHAGBARK LN	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
76783420	709 COLUMBIA AVE	Unk	C	Unk	1"	1975	UNK-LG	Unknown	1975	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318027	6812 REDSPIRE LN	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N		
75378028	601 SHAGBARK LN	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
78882678	6808 REDSPIRE LN	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
75583392	600 CHOKECHERRY	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
79515936	105 N JOHNSON ST	Unk	C	Unk		1900	C	Unknown	1900	SF	Installation record	Field inspection only	N		
75583325	604 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes
76783281	101 N JOHNSON ST	Unk	UNK-LG	Unk		1958	C	Unknown	1958	SF		Field inspection only	Y	7/19/2024	Other - describe in notes
79515763	6804 REDSPIRE LN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583431	608 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes
83646603	6801 CONSERVANC	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75377914	612 CHOKECHERRY	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
75378203	537 SOUTH ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230698	6803 CONSERVANC	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N		
78882664	616 CHOKECHERRY	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N		
83646632	6805 CONSERVANC	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75377889	503 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583365	620 CHOKECHERRY	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N		
75583301	6807 CONSERVANC	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75378059	505 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377992	624 CHOKECHERRY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	5/24/2024	Other - describe in notes
75377922	629 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
79515776	6811 CONSERVANC	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75583341	625 CHOKECHERRY	Unk	C	Unk		1983	UNK-LG	Unknown	1983	SF	Installation record		N		
79515780	4641 MISTFLOWER	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75377820	621 CHOKECHERRY	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes
75377831	507 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783184	4637 MISTFLOWER	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377852	514 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N		
76783185	4633 MISTFLOWER	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377808	512 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377995	613 CHOKECHERRY	Unk	C	Unk		1976	UNK-LG	Unknown	1976	SF	Installation record		N		
75583454	4629 MISTFLOWER	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378238	510 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378081	609 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/17/2024	Other - describe in notes
75583426	4625 MISTFLOWER	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377986	605 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	7/18/2024	Other - describe in notes
75583331	508 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583480	4620 MISTFLOWER	Unk	UNK-NOLG	Unk		2013	UNK-NOLG	Unknown	2013	SF	Installed after lead ban	Installed after lead ban	N		
75583429	601 CHOKECHERRY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes

75378129	506 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583403	4624 MISTFLOWER (	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378240	400 WOODVALE DR	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	6/21/2024	Other - describe in notes	
75378247	504 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583251	4628 MISTFLOWER (	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583396	502 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
75377837	404 WOODVALE DR	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N			
75583404	4632 MISTFLOWER (	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378185	500 RIVERVIEW CT	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583522	408 WOODVALE DR	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/28/2024	Other - describe in notes	
75583328	4636 MISTFLOWER (	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583329	615 SOUTH ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			
75583229	412 WOODVALE DR	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N			
78882677	4640 MISTFLOWER (	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N			
75377908	500 SUNNYBROOK (	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377916	500 WOODVALE DR	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	9/17/2024	Other - describe in notes	
79317918	7706 INDIGO DR	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583285	504 WOODVALE DR	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	7/2/2024	Other - describe in notes	
79515984	7708 INDIGO DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377834	502 SUNNYBROOK (	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515726	508 WOODVALE DR	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N			
79515587	7710 INDIGO DR	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583297	700 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583412	512 WOODVALE DR	Unk	C	Unk		1977	UNK-LG	Unknown	1977	SF	Installation record		N			
79515493	7712 INDIGO DR	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378106	702 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75377928	516 WOODVALE DR	Unk	C	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			
79317815	7714 INDIGO DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378217	704 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378010	521 WILD PLUM DR	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
75583293	706 BROOK ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000059	7715 INDIGO DR	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377939	517 WILD PLUM DR	Unk	C	Unk		1980	UNK-LG	Unknown	1980	SF	Installation record		N			
75377729	708 BROOK ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515583	7716 INDIGO DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377888	513 WILD PLUM DR	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N			
75377832	710 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317854	7718 INDIGO DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377896	712 BROOK ST	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378070	800 BROOK ST	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515616	7721 INDIGO DR	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583345	505 WILD PLUM DR	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes	
75377962	802 BROOK ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515945	7723 INDIGO DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583503	401 SOUTH ST	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583230	804 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515758	7725 INDIGO DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378210	501 WILD PLUM DR	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N			
75378043	806 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583435	500 WILD PLUM DR	Unk	C	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installation record	Installed after lead ban	N			
79318026	7722 INDIGO DR	Unk	C	Unk	1"	2010	P	Unknown	2010	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378193	808 BROOK ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515500	7726 INDIGO DR	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583484	504 WILD PLUM DR	Unk	C	Unk		1978	UNK-LG	Unknown	1978	SF	Installation record		N			
75378202	810 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377887	508 WILD PLUM DR	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N			
75583462	7727 INDIGO DR	Unk	UNK-NOLG	Unk		2013	UNK-NOLG	Unknown	2013	SF	Installed after lead ban	Installed after lead ban	N			
75583308	812 BROOK ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063696	7728 INDIGO DR	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646538	512 WILD PLUM DR	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
75378246	814 BROOK ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063707	7730 INDIGO DR	Unk	C	Unk	1"	2016	P	Unknown	2016	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583314	505 HANKS HOLLOW	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
79515963	7732 INDIGO DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378147	816 BROOK ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583498	501 HANKS HOLLOW	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	6/4/2024	Other - describe in notes	
83119148	7734 INDIGO DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377728	811 BROOK ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882659	535 SOUTH ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N			
83646592	7736 INDIGO DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378260	809 BROOK ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583490	508 SOUTH ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482112	7753 BULRUSH CIR	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75378063	807 BROOK ST	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667933	7755 BULRUSH CIR	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
83646601	805 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378090	468 SUNSET DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
90942262	7757 BULRUSH CIR	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	SF	Installed after lead ban	Installed after lead ban	N			
75378213	803 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377798	464 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288731	7741 INDIGO DR	Unk	C	Unk	1"	2019	P	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377919	460 SUNSET DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
91921195	7832 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515983	7831 BLUESTEM TRI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378206	801 BROOK ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583284	452 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646613	7830 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378033	709 BROOK ST	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377959	448 SUNSET DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230697	7829 BLUESTEM TRI	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583336	707 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515767	444 SUNSET DR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515385	7828 BLUESTEM TRI	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377903	705 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378069	440 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646617	7827 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378078	703 BROOK ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583368	436 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
91505723	7826 BLUESTEM TRI	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377968	701 BROOK ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753305	7825 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377744	602 SUNNYBROOK (	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646610	7824 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515857	432 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583249	604 SUNNYBROOK (	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515394	7823 BLUESTEM TRI	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583350	428 SUNSET DR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583335	606 SUNNYBROOK (	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515987	7822 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377961	424 SUNSET DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515779	7821 BLUESTEM TRI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583352	420 SUNSET DR	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583420	515 ISLAND DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82058816	7820 BLUESTEM TRI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377804	416 SUNSET DR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378245	513 ISLAND DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515406	7819 BLUESTEM TRI	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583254	417 SUNSET DR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583252	511 ISLAND DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753289	7818 BLUESTEM TRI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377816	405 STONERIDGE TE	Unk	UNK-NOLG	Unk		1988	C	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N	2/28/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377967	509 ISLAND DR	Unk	C	Unk	1"	2000	UNK-NOLG	Unknown	2000	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063790	7817 BLUESTEM TRI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377765	409 STONERIDGE TE	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378261	507 ISLAND DR	Unk	C	Unk	1"	1996	UNK-NOLG	Unknown	1996	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938890	7816 BLUESTEM TRI	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377755	413 STONERIDGE TE	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377965	505 ISLAND DR	Unk	C	Unk	1"	1996	UNK-NOLG	Unknown	1996	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515796	7815 BLUESTEM TRI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378086	417 STONERIDGE TE	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583438	503 ISLAND DR	Unk	C	Unk	1"	1999	UNK-NOLG	Unknown	1999	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783350	421 STONERIDGE TE	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515978	502 ISLAND DR	Unk	C	Unk	1"	1999	UNK-NOLG	Unknown	1999	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515886	7730 CATCHFLY LN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378000	425 STONERIDGE TE	Unk	C	Unk	1"	1991	UNK-NOLG	Unknown	1991	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377973	504 ISLAND DR	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063661	7729 CATCHFLY LN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378122	420 STONERIDGE TE	Unk	C	Unk	1"	1930	C	Unknown	1930	SF	Installation record	Field inspection only	Y	6/5/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378107	506 ISLAND DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783030	7727 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782989	7725 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119156	412 STONERIDGE TE	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583233	508 ISLAND DR	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783012	7723 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646544	408 STONERIDGE TE	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export

75378024	510 ISLAND DR	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
76783193	7721 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378088	404 STONERIDGE TE	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378249	512 ISLAND DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783071	7719 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377997	400 STONERIDGE TE	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515674	7717 CATCHFLY LN	Unk	C	Unk	1"	2009	UNK-NOLG	Unknown	2009	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378170	700 SUNNYBROOK (	Unk	C	Unk	1"	2000	UNK-NOLG	Unknown	2000	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583382	429 SUNSET DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583319	702 SUNNYBROOK (	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515613	7715 CATCHFLY LN	Unk	C	Unk	1"	2009	UNK-NOLG	Unknown	2009	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378066	433 SUNSET DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515843	7713 CATCHFLY LN	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377853	437 SUNSET DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378110	704 SUNNYBROOK (	Unk	C	Unk	1"	2000	UNK-NOLG	Unknown	2000	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583385	401 HAWTHORN CT	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583370	706 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515512	7711 CATCHFLY LN	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377813	708 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377991	405 HAWTHORN CT	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515666	7709 CATCHFLY LN	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377783	800 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378221	409 HAWTHORN CT	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515656	7707 CATCHFLY LN	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583228	413 HAWTHORN CT	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
75583339	802 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063728	7705 CATCHFLY LN	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377734	412 HAWTHORN CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377769	804 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317802	7706 CATCHFLY LN	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583337	408 HAWTHORN CT	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377879	806 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646608	7708 CATCHFLY LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377818	404 HAWTHORN CT	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378015	808 SUNNYBROOK (	Unk	C	Unk	1"	2004	UNK-NOLG	Unknown	2004	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783049	7710 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377881	400 HAWTHORN CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377760	449 SUNSET DR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377771	810 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583478	7712 CATCHFLY LN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119139	453 SUNSET DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583487	817 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318053	7714 CATCHFLY LN	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378251	457 SUNSET DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515609	7716 CATCHFLY LN	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377998	461 SUNSET DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515628	7718 CATCHFLY LN	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377789	465 SUNSET DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377785	502 SOUTH ST	Unk	C	Unk	1"	1993	UNK-NOLG	Unknown	1993	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378046	811 SUNNYBROOK (	Unk	C	Unk	1"	2004	UNK-NOLG	Unknown	2004	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783061	7722 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783199	500 SOUTH ST	Unk	C	Unk	1"	1985	UNK-LG	Unknown	1985	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583305	809 SUNNYBROOK (	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783041	7724 CATCHFLY LN	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377794	416 SOUTH ST	Unk	C	Unk	1"	1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882632	807 SUNNYBROOK (	Unk	C	Unk	1"	2003	UNK-NOLG	Unknown	2003	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646628	7726 CATCHFLY LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378056	600 SOUTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
75583311	805 SUNNYBROOK (	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753301	7728 CATCHFLY LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646593	7732 CATCHFLY LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378076	608 SOUTH ST	Unk	UNK-NOLG	Unk		1987	C	Unknown	1987	SF	Installed after lead ban	Field inspection only	Y	5/17/2024	Other - describe in notes	
75378158	803 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938914	7734 CATCHFLY LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377949	612 SOUTH ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
75377877	801 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482135	7711 AUTUMN BLA2	Unk	C	Unk	1"	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583459	616 SOUTH ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
75583353	713 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583388	710 SOUTH ST	Unk	C	Unk		1900	C	Unknown	1900	SF	Installation record	Field inspection only	Y	6/21/2024	Other - describe in notes	
76783151	7707 AUTUMN BLA2	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377801	711 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378022	709 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646622	720 SOUTH ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
75583489	7703 AUTUMN BLA2	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378102	707 SUNNYBROOK (	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
76783348	722 SOUTH ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
80276300	7701 AUTUMN BLA2	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377833	705 SUNNYBROOK (	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377899	724 SOUTH ST	Unk	C	Unk	1"	1984	C	1"	1984	SF	Installation record	Field inspection only	Y	5/9/2024	Customer self id	
79317912	6907 LARK SPUR LN	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N			
75377776	703 SUNNYBROOK (	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377924	726 SOUTH ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe in notes	
79000075	4710 INNOVATION I	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583246	523 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583423	728 SOUTH ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
76783583	4720 INNOVATION I	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N			
75378050	732 SOUTH ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
75378209	521 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515539	4730 INNOVATION I	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N			
75583455	734 SOUTH ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	6/18/2024	Other - describe in notes	
75377788	519 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753296	4740 INNOVATION I	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782793	736 SOUTH ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
75583419	517 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378152	738 SOUTH ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
79515635	4760 INNOVATION I	Unk	C	Unk	1"	2015	C	Unknown	2015	SF	Installation record	Field inspection only	Y	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378250	515 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377762	513 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882478	4770 INNOVATION I	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646543	423 S LEXINGTON PI	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N			
75378001	511 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515743	4780 INNOVATION I	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
75583430	421 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
75583513	419 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	7/11/2024	Other - describe in notes	
75378148	509 RIVERSIDE DR	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	2001	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378097	417 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	6/3/2024	Other - describe in notes	
79515874	7609 AUTUMN BLA2	Unk	DI	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583309	413 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
75377960	505 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515947	7617 AUTUMN BLA2	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378254	411 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes	
75583237	503 RIVERSIDE DR	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515408	7625 AUTUMN BLA2	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583391	501 RIVERSIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378049	409 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	6/21/2024	Other - describe in notes	
78882434	7633 AUTUMN BLA2	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583273	501 SUNNYBROOK (	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882300	7641 AUTUMN BLA2	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378126	407 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
75583395	500 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378156	405 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N			
75583300	502 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119126	4855 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75583519	504 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583417	403 S LEXINGTON PI	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N			
75378027	506 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063727	401 S LEXINGTON PI	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N			
75378060	508 RIVERSIDE DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583303	420 S LEXINGTON PI	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes	
75583302	422 S LEXINGTON PI	Unk	C	Unk		1984	UNK-LG	Unknown	1984	SF	Installation record		N			
75377925	510 RIVERSIDE DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
83646551	4867 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75583312	424 S LEXINGTON PI	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N			
75377862	512 RIVERSIDE DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119122	4871 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75378080	426 S LEXINGTON PI	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
83646548	4875 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75377944	514 RIVERSIDE DR	Unk	C	Unk	1"	1998	UNK-NOLG	Unknown	1998	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377781	430 S LEXINGTON PI	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N			
83646552	4879 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75378125	432 S LEXINGTON PI	Unk	C	Unk		1987	C	Unknown	1987	SF	Installation record	Installed after lead ban	N			
75377870	516 RIVERSIDE DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646596	4869 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
75378092	518 RIVERSIDE DR	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export

75377875	436 S LEXINGTON PI	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N		
83646588	4881 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75378101	812 SOUTH ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
75378003	607 SUNNYBROOK I	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646630	4837 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75378259	605 SUNNYBROOK I	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646609	4841 INNOVATION I	Unk	C	Unk	2"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377814	820 SOUTH ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
80063675	603 SUNNYBROOK I	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377799	822 SOUTH ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N		
84230693	4845 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75583248	818 RIVER RD	Unk	UNK-LG	Unk	2"	1955	UNK-LG	Unknown	1955	SF			N		
84230680	4849 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
75378162	830 SOUTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N		
75377951	824 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75583479	900 SOUTH ST	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe in notes
84230687	4819 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75378052	902 SOUTH ST	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N		
84515383	4823 INNOVATION I	Unk	C	Unk	2"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377980	820 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	C	Unknown	2004	SF	Installed after lead ban	Field inspection only	Y	2/26/2025	
84515384	4827 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75378096	904 SOUTH ST	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N		
75378082	818 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
75378032	908 SOUTH ST	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N		
75377742	816 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
84230668	4821 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
84515379	4825 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583288	912 SOUTH ST	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes
75378065	814 WOODS GLEN C	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
75583361	916 SOUTH ST	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N		
84230684	4829 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583414	812 WOODS GLEN C	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
75583440	920 SOUTH ST	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	7/9/2024	Other - describe in notes
84230683	4833 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583280	809 WOODS GLEN C	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
75583407	412 SOUTH ST	Unk	C	Unk	1"	1993	UNK-NOLG	Unknown	1993	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782914	811 WOODS GLEN C	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
84515377	4805 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79515910	913 SOUTH ST	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583402	813 WOODS GLEN C	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N		
84515378	4809 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79317946	915 SOUTH ST	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378222	815 WOODS GLEN C	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N		
84515375	4813 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79515610	917 SOUTH ST	Unk	UNK-NOLG	Unk		2009	UNK-NOLG	Unknown	2009	SF	Installed after lead ban	Installed after lead ban	N		
75378127	817 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
79515523	919 SOUTH ST	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515387	4803 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583421	819 WOODS GLEN C	Unk	UNK-NOLG	Unk		2007	UNK-NOLG	Unknown	2007	SF	Installed after lead ban	Installed after lead ban	N		
79317851	921 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377964	821 WOODS GLEN C	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
84515390	4807 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79515909	922 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583324	823 WOODS GLEN C	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
79515873	923 SOUTH ST	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515389	4811 INNOVATION I	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
78882254	708 E HOLUM ST	Unk	UNK-LG	Unk		1950	C	Unknown	1950	SF		Field inspection only	Y	7/12/2024	Other - describe in notes
79515830	924 SOUTH ST	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783342	712 E HOLUM ST	Unk	UNK-LG	Unk		1956	C	Unknown	1956	SF		Field inspection only	Y	5/29/2024	Other - describe in notes
79515769	925 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783398	716 E HOLUM ST	Unk	UNK-LG	Unk		1956	UNK-LG	Unknown	1956	SF			N		
79317929	926 SOUTH ST	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028063	7658 AUTUMN BLA2	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N		
78882556	720 E HOLUM ST	Unk	UNK-LG	Unk		1955	UNK-LG	Unknown	1955	SF			N		
92779615	7662 AUTUMN BLA2	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N		
79515651	927 SOUTH ST	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515601	724 E HOLUM ST	Unk	C	Unk		1958	UNK-LG	Unknown	1958	SF	Installation record		N		
88065455	7604 AUTUMN BLA2	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
79318002	928 SOUTH ST	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783243	728 E HOLUM ST	Unk	UNK-LG	Unk		1958	UNK-LG	Unknown	1958	SF			N		
79515655	929 SOUTH ST	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
92701062	7710 AUTUMN BLA2	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N		
79515934	732 E HOLUM ST	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N		
79317905	930 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824609	7806 AUTUMN BLA2	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882336	736 E HOLUM ST	Unk	C	Unk		1950	C	Unknown	1950	SF	Installation record	Field inspection only	N		
79515980	931 SOUTH ST	Unk	C	Unk	1"	2006	UNK-NOLG	Unknown	2006	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783556	804 E HOLUM ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N		
88065450	7802 AUTUMN BLA2	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
79515714	932 SOUTH ST	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882553	817 E HOLUM ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
85667604	7747 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882226	812 E HOLUM ST	Unk	UNK-LG	Unk		1979	C	Unknown	1979	SF		Field inspection only	Y	5/28/2024	Other - describe in notes
88824605	7804 BLUESTEM TRI	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515619	933 SOUTH ST	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515667	816 E HOLUM ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N		
90028077	7805 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515612	934 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783450	824 E HOLUM ST	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
86741055	7806 BLUESTEM TRI	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515622	935 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063679	828 E HOLUM ST	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N		
86967003	7807 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515530	936 SOUTH ST	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317855	821 E HOLUM ST	Unk	C	Unk		1966	C	Unknown	1966	SF	Installation record	Other - describe in notes	N		
90028074	7808 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063708	937 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783443	825 E HOLUM ST	Unk	UNK-LG	Unk		1969	UNK-LG	Unknown	1969	SF			N		
90292479	7809 BLUESTEM TRI	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515777	938 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063703	939 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515519	829 E HOLUM ST	Unk	UNK-LG	Unk		1982	UNK-LG	Unknown	1982	SF			N		
85668539	7810 BLUESTEM TRI	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515808	940 SOUTH ST	Unk	C	Unk	1"	2016	P	1"	2016	SF	Installation record	Installed after lead ban	N	3/6/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063658	941 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515522	831 E HOLUM ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		
80063704	942 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882220	833 E HOLUM ST	Unk	C	Unk		1968	C	Unknown	1968	SF	Installation record	Field inspection only	Y	6/3/2024	Other - describe in notes
90942263	7811 BLUESTEM TRI	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515885	943 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882217	104 BRUNS ST	Unk	C	Unk		1974	UNK-LG	Unknown	1974	SF	Installation record		N		
92779607	7805 AUTUMN BLA2	Unk	C	Unk	1"	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515611	944 SOUTH ST	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	SF	Installed after lead ban	Installed after lead ban	N		
90028061	6963 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882215	106 BRUNS ST	Unk	C	Unk	1"	1974	C	Unknown	1974	SF	Installation record	Field inspection only	Y	5/20/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753277	945 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882585	200 BRUNS ST	Unk	C	Unk	1"	1972	UNK-LG	Unknown	1972	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824637	6965 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515730	947 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783551	204 BRUNS ST	Unk	C	Unk		1973	C	Unknown	1973	SF	Installation record	Field inspection only	Y	7/9/2024	Other - describe in notes
79515879	949 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000087	208 BRUNS ST	Unk	C	Unk	1"	1973	UNK-LG	Unknown	1973	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882328	214 BRUNS ST	Unk	C	Unk		1973	UNK-LG	Unknown	1973	SF	Installation record		N		
90292444	6967 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515735	953 SOUTH ST	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86966961	6969 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515595	511 SHANE ODONNI	Unk	UNK-NOLG	Unk		2007	UNK-NOLG	Unknown	2007	SF	Installed after lead ban	Installed after lead ban	N		
78882443	816 JEFFERSON ST	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	6/28/2024	Other - describe in notes
90028075	6971 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515542	509 SHANE ODONNI	Unk	UNK-NOLG	Unk		2007	UNK-NOLG	Unknown	2007	SF	Installed after lead ban	Installed after lead ban	N		
79515986	221 EVERGREEN LN	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	N		
79515504	507 SHANE ODONNI	Unk	UNK-NOLG	Unk		2007	UNK-NOLG	Unknown	2007	SF	Installed after lead ban	Installed after lead ban	N		
88824625	6973 CRYSTAL CREE	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882493	217 EVERGREEN LN	Unk	C	Unk		1981	UNK-LG	Unknown	1981	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753294	504 SHANE ODONNI	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
86967007	6975 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882513	213 EVERGREEN LN	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119138	502 SHANE ODONNI	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
79515916	209 EVERGREEN LN	Unk	C	Unk		1974	UNK-LG	Unknown	1974	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741056	6977 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753259	500 SHANE ODONNI	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
76783437	205 EVERGREEN LN	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	N		
82753282	117 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482121	6979 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882305	201 EVERGREEN LN	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Other - describe in notes	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export

82753279	113 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741042	6981 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783559	208 EVERGREEN LN	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288706	6983 CRYSTAL CREE	Unk	P	Unk	1"	2019	P	1"	2019	SF	Installation record	Installed after lead ban	N	3/6/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119131	212 EVERGREEN LN	Unk	C	Unk		1973	UNK-LG	Unknown	1973	SF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515399	129 CROOKED TREE	Unk	C	Unk	1"	2018	P	1"	2018	SF	Installation record	Installed after lead ban	N	3/6/2025	Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288702	7608 AUTUMN BLA2	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646629	127 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783325	216 EVERGREEN LN	Unk	C	Unk		1973	C	Unknown	1973	SF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783647	220 EVERGREEN LN	Unk	C	Unk		1986	UNK-LG	Unknown	1986	SF	Installation record		N		
87288734	7606 AUTUMN BLA2	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
84515404	125 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783591	804 JEFFERSON ST	Unk	UNK-LG	Unk		1975	C	Unknown	1975	SF		Other - describe in notes	N		
84938906	7602 AUTUMN BLA2	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646631	123 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783573	800 JEFFERSON ST	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes
84938895	7600 AUTUMN BLA2	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646549	121 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882619	213 S HALSOR ST	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N		
84938893	4812 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515397	120 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783240	209 S HALSOR ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
84938892	4818 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230677	122 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882403	205 S HALSOR ST	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
87288720	4824 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882288	737 E HOLUM ST	Unk	C	Unk		1951	C	Unknown	1951	SF	Installation record	Field inspection only	Y	7/16/2024	Other - describe in notes
84230694	124 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288698	4830 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783475	733 E HOLUM ST	Unk	C	Unk		1951	C	Unknown	1951	SF	Installation record	Field inspection only	Y	3/6/2024	Other - describe in notes
84938887	126 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824611	4836 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783479	729 E HOLUM ST	Unk	C	Unk		1951	C	Unknown	1951	SF	Installation record	Field inspection only	N		
84230671	128 CROOKED TREE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938918	4842 INNOVATION I	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N		
85667610	725 E HOLUM ST	Unk	UNK-LG	Unk		1900	C	Unknown	1900	SF		Field inspection only	Y	5/16/2024	Other - describe in notes
83119152	111 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938910	4848 INNOVATION I	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882211	717 E HOLUM ST	Unk	C	Unk		1951	C	Unknown	1951	SF	Installation record	Field inspection only	N		
82753293	109 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938907	6992 CRYSTAL CREE	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783518	713 E HOLUM ST	Unk	UNK-LG	Unk		1951	UNK-LG	Unknown	1951	SF			N		
84938903	6990 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753285	107 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783612	705 E HOLUM ST	Unk	UNK-LG	Unk		1955	C	Unknown	1955	SF		Field inspection only	N		
86482136	6988 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753295	105 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063674	701 E HOLUM ST	Unk	UNK-LG	Unk		1952	C	Unknown	1952	SF		Field inspection only	Y	5/13/2024	Visual insp at meter
88065457	6986 CRYSTAL CREE	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515917	103 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783528	617 E HOLUM ST	Unk	C	Unk		1962	C	Unknown	1962	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe in notes
87288725	6984 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753273	101 CROOKED TREE	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
78882422	613 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
82753260	100 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288707	6980 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119142	102 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028066	6976 CRYSTAL CREE	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N		
78882689	601 E HOLUM ST	Unk	UNK-LG	Unk		1959	UNK-LG	Unknown	1959	SF			N		
79515904	104 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938899	6978 CRYSTAL CREE	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882429	117 S CLEVELAND A'	Unk	UNK-LG	Unk		1984	C	Unknown	1984	SF		Field inspection only	Y	7/3/2024	Other - describe in notes
82753280	106 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824621	6974 CRYSTAL CREE	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882269	608 DEFOREST ST	Unk	UNK-LG	Unk		1900	C	Unknown	1900	SF			N	2/27/2025	Visual insp at meter
82753275	108 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783367	612 DEFOREST ST	Unk	UNK-LG	Unk		1920	C	Unknown	1920	SF		Field inspection only	N		
90028071	6972 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515990	110 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646625	616 DEFOREST ST	Unk	C	Unk		1900	C	3/4"	1900	SF	Installation record	Field inspection only	N		
86966960	6968 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753283	112 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824639	6966 CRYSTAL CREE	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N		
76783303	620 DEFOREST ST	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	7/9/2024	Other - describe in notes
83119141	114 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783224	614 DEFOREST ST	Unk	UNK-LG	Unk		1910	C	Unknown	1910	SF		Field inspection only	N		
86966958	6964 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753270	116 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783432	625 DEFOREST ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe in notes
76782771	310 ACKER PKWY	Unk	C	Unk		1981	C	Unknown	1981	SF	Installation record	Field inspection only	N		
88824618	6962 CRYSTAL CREE	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882332	621 DEFOREST ST	Unk	C	Unk		1973	C	Unknown	1973	SF	Installation record	Field inspection only	N		
76783351	205 OLD INDIAN TRI	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76783497	617 DEFOREST ST	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N		
76783503	413 W MOHAWK TR	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76783499	613 DEFOREST ST	Unk	C	Unk		1965	C	Unknown	1965	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes
80063710	6822 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
80063798	204 OLD INDIAN TRI	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N		
79515661	609 DEFOREST ST	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N		
76782734	201 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
79515664	201 S CLEVELAND A'	Unk	UNK-LG	Unk		1963	UNK-LG	Unknown	1963	SF			N		
76783439	205 S CLEVELAND A'	Unk	UNK-LG	Unk		1962	UNK-LG	Unknown	1962	SF			N		
75583582	205 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76782985	219 S CLEVELAND A'	Unk	UNK-LG	Unk		1962	UNK-LG	Unknown	1962	SF			N		
78882207	209 MOHAWK TRL	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	6/20/2024	Other - describe in notes
80063717	6830 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
79515969	223 S CLEVELAND A'	Unk	UNK-LG	Unk		1962	UNK-LG	Unknown	1962	SF			N		
76783169	301 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
78882272	614 JEFFERSON ST	Unk	UNK-LG	Unk		1972	UNK-LG	Unknown	1972	SF			N		
80063718	6834 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76783037	305 MOHAWK TRL	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
76783430	618 JEFFERSON ST	Unk	C	Unk		1973	C	Unknown	1973	SF	Installation record	Field inspection only	Y	5/27/2024	Other - describe in notes
76782892	309 MOHAWK TRL	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes
79515835	6836 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76783588	616 JEFFERSON ST	Unk	C	Unk		1972	C	Unknown	1972	SF	Installation record	Field inspection only	N		
75583608	313 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
78882516	620 JEFFERSON ST	Unk	UNK-LG	Unk		1970	UNK-LG	Unknown	1970	SF			N		
79515839	6840 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
75583612	317 MOHAWK TRL	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe in notes
76783302	549 JEFFERSON ST	Unk	C	Unk		1964	C	Unknown	1964	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes
80063797	6842 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
78882611	320 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76783629	308 S CLEVELAND A'	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N		
80063691	6844 REDSPIRE LN	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
76783643	316 MOHAWK TRL	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N		
78882424	312 S CLEVELAND A'	Unk	UNK-LG	Unk		1969	UNK-LG	Unknown	1969	SF			N		
76783045	312 MOHAWK TRL	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes
76783476	316 S CLEVELAND A'	Unk	C	Unk		1966	C	Unknown	1966	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes
78882412	308 MOHAWK TRL	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
75583556	304 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
84938922	964 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782966	300 MOHAWK TRL	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	N		
76783417	400 S CLEVELAND A'	Unk	C	Unk	3/4"	1980	C	3/4"	1980	SF	Installation record	Field inspection only	Y	5/13/2024	Other - describe in notes
78882603	208 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
76782752	204 MOHAWK TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N		
84515403	968 CLOVER LN	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783274	404 S CLEVELAND A'	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes
75583559	200 MOHAWK TRL	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	Y	7/3/2024	Other - describe in notes
84515393	970 CLOVER LN	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783358	408 S CLEVELAND A'	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	7/15/2024	Other - describe in notes
76782779	304 OLD INDIAN TRI	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
84938898	972 CLOVER LN	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783257	412 S CLEVELAND A'	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes
79515900	308 OLD INDIAN TRI	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N		
84938905	974 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783600	214 S CLEVELAND A'	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N		
79515965	400 OLD INDIAN TRI	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N		
86741054	978 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783405	212 S CLEVELAND A'	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF		Field inspection only	N		
79515902	404 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N		
86967006	980 CLOVER LN	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783249	210 S CLEVELAND A'	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N		
76782924	406 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	SF	Installed after lead ban	Installed after lead ban	N		
90028069	982 CLOVER LN	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783271	206 S CLEVELAND A'	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N		

76782781	408 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065456	984 CLOVER LN	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882342	204 S CLEVELAND A'	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
79000077	410 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86967008	986 CLOVER LN	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515626	535 E HOLUM ST	Unk	UNK-LG	Unk		1952	UNK-LG	Unknown	1952	SF			N			
76782807	412 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288709	965 CLOVER LN	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
76783484	529 E HOLUM ST	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
78882684	414 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288726	969 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882253	525 E HOLUM ST	Unk	UNK-LG	Unk		1900	UNK-LG	Unknown	1900	SF			N			
76782848	416 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882234	523 E HOLUM ST	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
90292445	973 CLOVER LN	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
78882427	977 CLOVER LN	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782982	420 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515898	517 E HOLUM ST	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
78882229	422 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063656	513 E HOLUM ST	Unk	UNK-LG	Unk		1951	UNK-LG	Unknown	1951	SF			N			
86741039	985 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783140	424 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824614	989 CLOVER LN	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783474	433 E HOLUM ST	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N			
87288735	993 CLOVER LN	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646621	426 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882390	429 E HOLUM ST	Unk	UNK-LG	Unk		1952	UNK-LG	Unknown	1952	SF			N			
79515498	425 E HOLUM ST	Unk	C	Unk		1950	C	Unknown	1950	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe in notes	
86482119	976 CLOVER LN	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783115	428 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882270	421 E HOLUM ST	Unk	UNK-LG	Unk		1945	UNK-LG	Unknown	1945	SF			N			
88065428	6508 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
79317811	430 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065427	6504 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
79318038	432 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783387	409 E HOLUM ST	Unk	UNK-LG	Unk		1920	UNK-LG	Unknown	1920	SF			N			
88065445	6505 TRAILS EDGE C	Unk	P	Unk	1-1/2"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515933	425 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000061	403 E HOLUM ST	Unk	UNK-LG	Unk		1983	C	Unknown	1983	SF		Field inspection only	Y	6/3/2024	Other - describe in notes	
88065443	6507 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
76783436	401 E HOLUM ST	Unk	UNK-LG	Unk		1920	UNK-LG	Unknown	1920	SF			N			
88065448	6509 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
76783004	423 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583577	421 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065449	6511 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
79515935	419 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515915	420 DEFOREST ST	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N			
88824608	6513 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
76782926	417 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515647	424 DEFOREST ST	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N			
88824606	6517 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
75583551	415 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783428	428 DEFOREST ST	Unk	C	Unk		1955	C	Unknown	1955	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
88824640	6521 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
78882672	413 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824641	6523 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
80063777	432 DEFOREST ST	Unk	UNK-LG	Unk		1953	UNK-LG	Unknown	1953	SF			N			
76783011	411 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824619	6525 TRAILS EDGE C	Unk	P	Unk	1-1/2"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783617	436 DEFOREST ST	Unk	C	Unk		1957	C	Unknown	1957	SF	Installation record	Field inspection only	Y	5/30/2024	Other - describe in notes	
78882649	409 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824615	6527 TRAILS EDGE C	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N			
78882331	440 DEFOREST ST	Unk	C	Unk		1954	C	Unknown	1954	SF	Installation record	Field inspection only	N			
75583622	407 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515979	4653 INNOVATION I	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
83119146	108 S CLEVELAND A'	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
76782764	405 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782978	4645 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515559	201 JEFFERSON ST	Unk	C	Unk		1930	C	Unknown	1930	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes	
78882492	403 OLD INDIAN TRI	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783287	4637 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119150	205 JEFFERSON ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
83646602	220 POCAHONTAS L	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N			
76783283	4629 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515739	313 JEFFERSON ST	Unk	UNK-NOLG	Unk		1920	C	Unknown	1920	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882389	216 POCAHONTAS L	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N			
76783322	4621 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783346	317 JEFFERSON ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783315	4613 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783135	321 JEFFERSON ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882633	208 POCAHONTAS L	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583491	4605 INNOVATION I	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782770	504 SHAWNEE CT	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583631	4634 INNOVATION I	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882582	409 JEFFERSON ST	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N			
76783202	508 SHAWNEE CT	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583590	4630 INNOVATION I	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882606	417 JEFFERSON ST	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N			
75583450	4628 INNOVATION I	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782802	512 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583446	4624 INNOVATION I	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783578	425 JEFFERSON ST	Unk	C	Unk		1985	C	Unknown	1985	SF	Installation record	Field inspection only	Y	5/23/2024	Other - describe in notes	
79515956	516 SHAWNEE CT	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882205	429 JEFFERSON ST	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N			
79515877	6131 DANIELLE RD	Unk	C	Unk		UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			
76783531	505 JEFFERSON ST	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N			
76782827	524 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646569	6123 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646539	509 JEFFERSON ST	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N			
79515821	6109 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583555	528 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783409	513 JEFFERSON ST	Unk	UNK-LG	Unk		1986	C	Unknown	1986	SF		Field inspection only	Y	3/3/2025	Visual insp at meter	
80063733	6101 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	5/14/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317807	521 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783136	517 JEFFERSON ST	Unk	C	Unk		1981	C	Unknown	1981	SF	Installation record	Field inspection only	Y	5/22/2024	Other - describe in notes	
79515865	6097 DANIELLE RD	Unk	C	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782879	517 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783461	521 JEFFERSON ST	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N			
79515828	6093 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	5/14/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782824	513 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
76783324	525 JEFFERSON ST	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
76783104	509 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515870	6089 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	5/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119158	529 JEFFERSON ST	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
79515876	6085 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783469	533 JEFFERSON ST	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N			
78882669	505 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515858	6092 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	5/6/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783652	537 JEFFERSON ST	Unk	UNK-LG	Unk		1981	UNK-LG	Unknown	1981	SF			N			
79515625	501 SHAWNEE CT	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515856	6100 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783183	541 JEFFERSON ST	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
75583534	200 POCAHONTAS L	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515875	6110 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515863	512 W MOHAWK TR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583648	538 DAHL DR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			
79515820	6114 DANIELLE RD	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063726	534 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515562	516 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583565	532 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063716	6120 DANIELLE RD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783117	520 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515878	6105 DANIELLE RD	Unk	P	Unk		UN	P	Unknown	UN	SF	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783122	524 DAHL DR	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583690	524 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583641	516 DAHL DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782877	528 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515903	4299 DAENTL RD	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
76782887	512 DAHL DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75583681	532 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782739	601 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783203	508 DAHL DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515899	4291 DAENTL RD	Unk	C	Unk		UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			
79317930	537 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515888	4281 DAENTL RD	Unk	C	Unk		UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			

75583682	504 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515851	4298 BUCKLEY RD	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
76783198	462 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782843	533 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783205	464 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938897	910 YORKTOWN RD	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783159	529 W MOHAWK TR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515762	466 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938891	908 YORKTOWN RD	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515600	525 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882444	468 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515414	906 YORKTOWN RD	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783088	521 W MOHAWK TR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783094	470 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
82753291	904 YORKTOWN RD	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
78882352	517 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288712	902 YORKTOWN RD	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
82753262	915 EVENING SHADI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782901	509 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063667	472 DAHL DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515546	839 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882521	505 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783126	474 DAHL DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
79515773	841 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782959	501 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783174	476 DAHL DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882645	425 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515723	913 APPLE BLOSSOM	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583564	477 DAHL DR	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782784	421 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
79515832	915 APPLE BLOSSOM	Unk	UNK-NOLG	Unk		2012	UNK-NOLG	Unknown	2012	SF	Installed after lead ban	Installed after lead ban	N			
75583599	475 DAHL DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783633	417 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
79317909	917 APPLE BLOSSOM	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583550	473 DAHL DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			
76782767	418 W MOHAWK TR	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515509	919 APPLE BLOSSOM	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646587	316 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515737	845 SHOOTING STAI	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583652	422 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783020	320 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317812	846 SHOOTING STAI	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783043	500 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583568	324 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79000091	847 SHOOTING STAI	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515715	504 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783108	400 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515806	848 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515686	404 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783018	205 POCAHONTAS L	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
79515499	849 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782829	408 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882661	209 POCAHONTAS L	Unk	UNK-LG	Unk		1985	C	Unknown	1985	SF		Field inspection only	Y	5/13/2024	Other - describe in notes	
79515738	850 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063687	412 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782785	213 POCAHONTAS L	Unk	UNK-LG	Unk		1985	C	Unknown	1985	SF		Field inspection only	Y	5/21/2024	Other - describe in notes	
79515688	851 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063725	416 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583544	217 POCAHONTAS L	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N			
76783357	852 SHOOTING STAI	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583581	500 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			
79317825	305 OLD INDIAN TRL	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
79515593	853 SHOOTING STAI	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583639	504 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515872	414 W MOHAWK TR	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF		Field inspection only	Y	9/19/2024	Other - describe in notes	
79515734	855 SHOOTING STAI	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583720	330 YORKTOWN RD	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783100	605 W MOHAWK TR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583241	857 SHOOTING STAI	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583726	331 YORKTOWN RD	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			
75583644	609 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515801	858 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583657	601 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783036	613 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583474	859 SHOOTING STAI	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063677	602 GREENFIELD DR	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583693	617 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783032	861 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583538	621 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783134	863 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583712	625 W MOHAWK TR	Unk	UNK-NOLG	Unk		1992	C	Unknown	1992	SF	Installed after lead ban	Field inspection only	Y	3/3/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783137	801 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783352	601 GREENFIELD DR	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782916	629 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783031	803 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783024	407 YORKTOWN RD	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882654	633 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515766	805 SHOOTING STAI	Unk	C	Unk	1"	2008	UNK-NOLG	Unknown	2008	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782974	501 YORKTOWN RD	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646624	701 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782929	807 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583547	603 STERLING CIR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583609	705 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583524	809 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583541	605 STERLING CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515957	709 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783292	811 SHOOTING STAI	Unk	C	Unk	1"	2015	P	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515923	713 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783507	608 STERLING CIR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783023	813 SHOOTING STAI	Unk	C	Unk	1"	2014	UNK-NOLG	Unknown	2014	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782869	717 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782845	606 STERLING CIR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782903	815 SHOOTING STAI	Unk	UNK-NOLG	Unk		2014	UNK-NOLG	Unknown	2014	SF	Installed after lead ban	Installed after lead ban	N			
76782881	721 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583611	604 STERLING CIR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583466	817 SHOOTING STAI	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583673	725 W MOHAWK TR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583658	603 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882351	820 SHOOTING STAI	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782983	105 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
76782988	605 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515602	819 SHOOTING STAI	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646589	801 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783166	607 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
79317803	822 SHOOTING STAI	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782944	805 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782891	609 GREENFIELD DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782997	809 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318004	821 SHOOTING STAI	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882635	813 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783109	611 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317898	823 SHOOTING STAI	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783645	613 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583655	817 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515687	824 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782880	821 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515772	825 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583536	615 GREENFIELD DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
79515652	825 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515525	827 SHOOTING STAI	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515560	826 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782995	829 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782806	632 CONSTITUTION	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515510	829 SHOOTING STAI	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783047	833 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783079	630 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318009	831 SHOOTING STAI	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783111	837 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515759	628 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
79515547	833 SHOOTING STAI	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783176	901 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782819	626 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
83119147	835 SHOOTING STAI	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782998	905 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515727	624 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			

79515871	837 SHOOTING STAI	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882246	622 CONSTITUTION	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	SF	Installed after lead ban	Installed after lead ban	N			
78882378	909 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515568	944 STAR GAZER DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783157	913 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782812	618 CONSTITUTION	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			
75583719	917 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515554	942 STAR GAZER DR	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782897	616 CONSTITUTION	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			
82753292	940 STAR GAZER DR	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
76783038	921 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938913	938 STAR GAZER DR	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75583677	925 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646591	921 SKYLARK LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782967	629 CONSTITUTION	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
79317800	929 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515409	923 SKYLARK LN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882637	631 CONSTITUTION	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
76782874	933 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
88824627	925 SKYLARK LN	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782810	633 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
76783040	937 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783200	635 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
75583600	941 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515381	929 SKYLARK LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782798	945 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482142	933 SKYLARK LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783130	637 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
82753287	926 SKYLARK LN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882589	949 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783603	639 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646547	922 SKYLARK LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783156	953 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783144	641 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
82753263	930 SKYLARK LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783152	957 CLOVER LN	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583586	643 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646576	924 SKYLARK LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583649	645 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782817	960 CLOVER LN	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646583	920 SKYLARK LN	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N			
76782870	647 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
76782823	301 PRAIRIE GRASS `	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938923	928 SKYLARK LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782925	701 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583532	936 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
91505720	924 STAR GAZER DR	Unk	P	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783164	703 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
78882690	932 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
91505726	929 STAR GAZER DR	Unk	P	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583694	705 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
76782818	928 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92701049	934 STAR GAZER DR	Unk	P	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782800	707 CONSTITUTION	Unk	UNK-NOLG	Unk		1996	UNK-NOLG	Unknown	1996	SF	Installed after lead ban	Installed after lead ban	N			
78882583	709 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			
79515831	806 YORKTOWN RD	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
76782780	924 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583585	711 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318037	804 YORKTOWN RD	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515847	920 W MOHAWK TR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782909	713 CONSTITUTION	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063685	802 YORKTOWN RD	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583710	916 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783171	715 CONSTITUTION	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515845	801 YORKTOWN RD	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
79515783	803 YORKTOWN RD	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782816	912 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783077	618 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583642	908 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782836	616 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515615	807 YORKTOWN RD	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
76782791	904 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515895	810 YORKTOWN RD	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782921	614 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583650	900 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515401	4130 GREAT BRIDGE	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782737	612 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583552	836 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288701	4128 GREAT BRIDGE	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515928	610 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515926	832 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515931	4122 GREAT BRIDGE	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783321	608 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230676	4118 GREAT BRIDGE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583678	828 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583703	606 GREENFIELD DR	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938909	4114 GREAT BRIDGE	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882420	824 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783173	604 GREENFIELD DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119140	4110 GREAT BRIDGE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583615	820 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882609	603 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515846	4106 GREAT BRIDGE	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782736	816 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583526	605 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230692	4127 GREAT BRIDGE	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783178	812 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782923	607 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667817	4129 GREAT BRIDGE	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646620	808 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882592	609 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782979	611 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583554	804 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119121	4131 GREAT BRIDGE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882629	613 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515970	800 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583635	615 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646557	205 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			
76782778	617 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583572	740 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583549	704 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	C	Unknown	1997	SF	Installed after lead ban	Field inspection only	Y	2/26/2025	Visual insp at meter	
76783022	720 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882599	706 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063781	716 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782773	352 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882626	712 W MOHAWK TR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583579	350 COUNTRY CLOV	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			
76783033	708 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583716	330 BURL OAK DR	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
75583711	704 W MOHAWK TR	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782931	700 W MOHAWK TR	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515966	602 SOUTHBOUND I	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063682	632 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
80063670	800 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
83646574	628 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
79515532	802 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646567	624 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
79515756	804 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882509	620 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119153	806 SOUTHBOUND I	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783195	616 W MOHAWK TR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782943	204 TRAIL SIDE DR	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			
79515521	803 NASH LN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515682	805 NASH LN	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
90292464	4136 PARKER CT	Unk	C	Unk	1"	2021	C	Unknown	2021	SF	Installation record	Installed after lead ban	N	2/27/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230675	4138 PARKER CT	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667813	4077 HANOVER DR	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	SF	Installed after lead ban	Installed after lead ban	N			
85667605	4140 PARKER CT	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87017026	4186 BEAR TREE PKI	Unk	DI	Unk	6"	UN	UNK-LG	Unknown	UN	NONRES	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
89624158	6400 PEDERSON XIN	Unk	P	Unk		UN	P	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
87288711	4139 PARKER CT	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
89793952	6450 PEDERSON XIN	Unk	P	Unk		UN	P	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
85667909	4137 PARKER CT	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92779618	4137 HANOVER DR	Unk	C	Unk	1"	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667914	4133 PARKER CT	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export

91921197	6250 FOUNTAINHEA	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92779608	4138 HANOVER DR	Unk	C	Unk	1"	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92779613	4063 GREAT BRIDGE	Unk	P	Unk	1"	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
90942432	6248 JOHN F KENNE	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	SF	Installed after lead ban	Installed after lead ban	N			
81814294	4134 HANOVER DR	Unk	C	Unk	2"	UN	P	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
92701067	4071 GREAT BRIDGE	Unk	P	Unk	1"	UN	P	Unknown	UN	SF	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667608	6238 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84613958	6201 WILLIAMSBUR	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
81340472	6203 WILLIAMSBUR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
83178868	6205 WILLIAMSBUR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installation record	N			
92701065	4093 BEAR TREE PK\	Unk	P	Unk	1"	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83178866	6207 WILLIAMSBUR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
75378231	241-247 W NORTH S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
79515678	100 W N ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Field inspection only	Field inspection only	N			
78882445	515-517 PARK AVEN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
92779610	4117 BEAR TREE PK\	Unk	P	Unk	1"	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032400	509-515 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
76782722	517-527 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
80063732	4081 HANOVER DR	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	SF	Installed after lead ban	Installed after lead ban	N			
76782723	532-534 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
85667814	4089 HANOVER DR	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
76782725	524-530 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
85667606	4093 HANOVER DR	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
78032413	516-522 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
91921192	4101 HANOVER DR	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N			
78032401	508-514 TRAILSIDE I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
79515982	4117 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032469	700-706 HILLTOP DF	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Field inspection only	N			
82753269	4121 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753286	606 HILLTOP DR	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
82753276	4125 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753266	4133 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882687	533 N STEVENSON S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
86482123	6245 FOUNTAINHEA	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78612165	533 N STEVENSON S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
78882448	324-328 EAST HOLU	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter	
90942259	6247 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783261	408-412 EAST HOLU	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Other - describe in notes	N			
88065447	6249 FOUNTAINHEA	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783465	444-446 EAST HOLU	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
83646616	6253 FOUNTAINHEA	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882322	448-452 EAST HOLU	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
86482122	6255 FOUNTAINHEA	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783423	544-548 EAST HOLU	Unk	UNK-LG	Unk		UN	L	Unknown	UN	SF		Field inspection only	Y	5/24/2024	Visual insp at meter	
84938886	6257 FOUNTAINHEA	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783317	729-733 COLUMBIA	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
86482118	6259 FOUNTAINHEA	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783593	701-705 COLUMBIA	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/15/2024	Other - describe in notes	
84938917	6260 FOUNTAINHEA	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N			
76782712	200-208 NORTH HAI	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
90028067	6258 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378157	507 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75378064	505 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
88065454	6256 FOUNTAINHEA	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377840	503 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
84515420	6254 FOUNTAINHEA	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938908	6252 FOUNTAINHEA	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378068	500 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
88824607	6248 FOUNTAINHEA	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377987	502 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75378009	504 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
86482124	6245 JOHN F KENNE	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N			
75583334	506 PRAIRIE VIEW C	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75377958	820 RIVER RD	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
95064448	201 COMMERCE ST	Unk	UNK-NOLG	Unk		UN	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119132	6251 JOHN F KENNE	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741038	201 COMMERCE ST	Unk	UNK-NOLG	Unk		UN	C	1"	UN	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288729	6253 JOHN F KENNE	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882446	305-309 JEFFERSON	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
90292461	6255 JOHN F KENNE	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782710	391-397 BLACKBERR	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
87288736	6257 JOHN F KENNE	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288733	6259 JOHN F KENNE	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76503401	390-396 BLACKBERR	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
88065433	6264 JOHN F KENNE	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76503399	391-397 COUNTRY C	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
88824620	6256 JOHN F KENNE	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032427	808-814 RUMLEY RL	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
83646541	6254 JOHN F KENNE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032424	800-806 RUMLEY RL	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
82753278	6250 JOHN F KENNE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032426	801-807 RUMLEY RL	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
90028064	6242 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032425	809-815 RUMLEY RL	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
75583278	122 W HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
86966955	6235 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377732	104-106 COMMERC	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
90942261	6237 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378018	124-126 COMMERC	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
75377727	6241 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378174	701 S HILL ST	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
86966959	4177 HANOVER DR	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515989	119 CROOKED TREE	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
83119129	4181 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783150	883 W NORTH ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
88065442	4185 HANOVER DR	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783097	4995 HWY V	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
90028059	4193 HANOVER DR	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76503400	548-554 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
96814444	6231 DAGNY LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782716	540-546 SEMINOLE	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Field inspection only	N			
90292457	6236 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782701	308-314 WINN COU	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
85667603	6234 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782699	300-306 WINN COU	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
88824622	6225 FOUNTAINHEA	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782705	301-307 WINN COU	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
90292478	6227 FOUNTAINHEA	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782707	309-315 WINN COU	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
87288723	6229 FOUNTAINHEA	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82759522	520-526 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
88824626	6233 FOUNTAINHEA	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028073	4146 HANOVER DR	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515382	4141 HANOVER DR	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782728	509-515 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
90028068	4145 HANOVER DR	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82759527	517-523 SEMINOLE	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Field inspection only	N			
83646615	4149 HANOVER DR	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783147	525-531 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
80782748	533-539 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
88824623	4161 HANOVER DR	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782706	541-547 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
84515411	4165 HANOVER DR	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032428	621-631 OLD INDIAN	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
76782709	609-615 OLD INDIAN	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
90292462	4169 HANOVER DR	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938894	4173 HANOVER DR	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782700	617-623 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
87288727	6232 DAGNY LN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230678	6230 DAGNY LN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782703	641-647 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
76503391	618-624 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
84230667	6228 DAGNY LN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782704	610-616 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
75377878	101 SEMINOLE WAY	Unk	UNK-LG	Unk		1974	UNK-LG	Unknown	1974	SF			N			
78032443	602-608 SEMINOLE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	MF			N			
75583436	105 SEMINOLE WAY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N			
75378045	689 691 697 SOUTH	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378186	109 SEMINOLE WAY	Unk	UNK-LG	Unk		1980	C	Unknown	1980	SF		Field inspection only	Y	7/19/2024	Other - describe in notes	
75378227	116 VINBURN RD	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378165	113 SEMINOLE WAY	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
78032415	821 S MAIN ST	Unk	C	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installation record		N			
75377843	117 SEMINOLE WAY	Unk	UNK-LG	Unk		1973	C	Unknown	1973	SF		Field inspection only	Y	6/28/2024	Other - describe in notes	
86741052	6351 LOFTUS RD UN	Unk	P	Unk		UN	P	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75583239	121 SEMINOLE WAY	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			

75377904	125 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	N			
91214063	7743 INDIGO DR	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	SF	Installed after lead ban	Installed after lead ban	N			
76783112	129 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
75378094	133 SEMINOLE WAY	Unk	C	Unk		1975	C	Unknown	1975	SF	Installation record	Field inspection only	Y	7/10/2024	Other - describe in notes	
86482141	4627 BELLFLOWER I	Unk	P	Unk		UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75378055	141 SEMINOLE WAY	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	5/17/2024	Other - describe in notes	
75583287	145 SEMINOLE WAY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
75378179	149 SEMINOLE WAY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N			
75377863	153 SEMINOLE WAY	Unk	C	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
75583408	157 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
95292228	1525 RIVER ROA	Unk	UNK-NOLG	Unk		UN	C	1"	UN	NONRES	Installed after lead ban	Field inspection only	N			
75378013	165 SEMINOLE WAY	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF		Field inspection only	Y	6/24/2024	Other - describe in notes	
92701055	6710 CONSERVANCY	Unk	UNK-NOLG	Unk		2023	UNK-NOLG	Unknown	2023	SF	Installed after lead ban	Installed after lead ban	N			
75378173	169 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
92779624	6712 CONSERVANCY	Unk	UNK-NOLG	Unk		2023	UNK-NOLG	Unknown	2023	SF	Installed after lead ban	Installed after lead ban	N			
75583381	173 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92779616	6706 CONSERVANCY	Unk	UNK-NOLG	Unk		2023	UNK-NOLG	Unknown	2023	SF	Installed after lead ban	Installed after lead ban	N			
75378166	201 SEMINOLE WAY	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N			
75377956	156 SEMINOLE WAY	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N			
91334415	4936-4954 INNOVA1	Unk	C	Unk		UN	C	Unknown	UN	MF	Installed after lead ban	Installed after lead ban	N			
75378116	152 SEMINOLE WAY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	N			
91334416	4914-4932 INNOVA1	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Field inspection only	N	3/5/2025	Visual insp at meter	
75583270	148 SEMINOLE WAY	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	SF			N			
91654798	4910 INNOVATION I	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	MF	Installed after lead ban	Installed after lead ban	N			
78882618	6321 ROSTAD DR	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
75377911	144 SEMINOLE WAY	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
78032422	6325 PEPSI WAY	Unk	UNK-NOLG	Unk		UN	C	2"	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583441	140 SEMINOLE WAY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	11/7/2024	Visual insp at meter	
75378054	136 SEMINOLE WAY	Unk	UNK-LG	Unk		1976	UNK-LG	Unknown	1976	SF			N			
88658650	6325 PEPSI WAY # 2	Unk	UNK-NOLG	Unk		UN	C	2"	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378224	132 SEMINOLE WAY	Unk	C	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	Y	6/28/2024	Other - describe in notes	
88658649	6325 PEPSI WAY # 3	Unk	UNK-NOLG	Unk		UN	C	3"	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378167	128 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
81946459	6317 ROSTAD WAY	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79515711	124 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
81261177	6311 ROSTAD DR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
75377947	120 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	UNK-LG	Unknown	1977	SF			N			
80063721	6305 ROSTAD DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
75378047	116 SEMINOLE WAY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N			
78032471	6303 PEPSI WAY	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
82062230	6167 PEPSI WAY	Unk	DI	Unk	6"	UN	UNK-LG	Unknown	UN	NONRES	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
95061515	6133-6139 PEPSI WA	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Installed after lead ban	N			
79515548	108 SEMINOLE WAY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N			
78032468	6115-6129 PEPSI WA	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
75583261	104 SEMINOLE WAY	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	SF			N			
78882357	601 DEER RUN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032466	6101-6111 PEPSI WA	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
78882501	603 DEER RUN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78886714	6176 PEPSI WAY	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
76783452	605 DEER RUN	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482114	6097 PEPSI WAY	Unk	DI	Unk		UN	DI	3/4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78882361	604 DEER RUN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882525	6097 PEPSI WAY	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78882306	602 DEER RUN	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515606	902 RUMLEY RUN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032467	4021 MERIDIAN DR	Unk	UNK-NOLG	Unk		2011	UNK-NOLG	Unknown	2011	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515823	4111 MERIDIAN DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	NONRES	Installed after lead ban	Installed after lead ban	N			
80063678	904 RUMLEY RUN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82062229	4131 MERIDIAN DR	Unk	UNK-NOLG	Unk		2010	UNK-NOLG	Unknown	2010	NONRES	Installed after lead ban	Installed after lead ban	N			
79515671	906 RUMLEY RUN	Unk	C	Unk	1"	2002	UNK-NOLG	Unknown	2002	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
94480479	6308 PEPSI WAY	Unk	DI	Unk	6"	UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317904	903 RUMLEY RUN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
80063788	905 RUMLEY RUN	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	SF	Installed after lead ban	Installed after lead ban	N			
76783238	103 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515421	4300 DURAFORM LI	Unk	UNK-NOLG	Unk		2014	UNK-NOLG	Unknown	2014	NONRES	Installed after lead ban	Installed after lead ban	N			
76783236	105 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
82062234	6385 N TOWNE RD	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	NONRES	Installed after lead ban	Installed after lead ban	N			
76783237	107 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76783229	109 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
76783228	111 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
83646634	6446 N TOWNE RD	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
78882543	113 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2002	UNK-NOLG	Unknown	2002	SF	Installed after lead ban	Installed after lead ban	N			
84515413	5954 DAENTL SERVI	Unk	DI	Unk		UN	P	1"	UN	NONRES	Installation record	Installed after lead ban	N			
76783230	117 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
87749402	4661 DALMORE RD	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
91505725	4313 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
92701052	4315 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783372	125 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
92779621	4319 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783378	127 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
91505721	4325 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
91505722	4327 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783375	131 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
93899304	4313-4341 DURAFO	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
76783382	133 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	SF	Installed after lead ban	Installed after lead ban	N			
90942436	4331 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783219	128 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
90942433	4335 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783386	124 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
91214059	4337 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783442	120 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
90942437	4339 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
76783381	116 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
91214060	4341 DURAFORM LI	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
87017027	6361 N TOWNE RD	Unk	DI	Unk		2019	DI	Unknown	2019	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
76783385	112 CARRIAGE WAY	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
82759508	6371 N TOWNE RD	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installation record	N		Visual insp at meter	
79515617	954 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515867	952 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82720396	6380 N TOWNE RD	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
95278553	6380 N TOWNE RD	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79000060	950 SILVER RIPPLE W	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
94505582	6380 N TOWNE RD	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515815	945 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86214891	6485 STACK DR	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	NONRES	Installed after lead ban	Installed after lead ban	N			
79515861	948 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
90297562	6501 N TOWNE DR	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Installed after lead ban	N			
80063663	943 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83231140	6501 N TOWNE DR	Unk	DI	N		UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515750	946 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86214890	6551 N TOWNE RD	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Installed after lead ban	N			
80063729	944 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515811	941 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
95061510	6500 STACK DR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515786	942 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515824	940 SILVER RIPPLE W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741053	6351 LOFTUS RD UN	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79515774	938 SILVER RIPPLE W	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N			
87288703	6351 LOFTUS RD UN	Unk	DI	Unk		UN	C	6"	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79515675	939 SILVER RIPPLE W	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741051	6351 LOFTUS RD UN	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79515924	936 SILVER RIPPLE W	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92779611	6258 JOHN F KENNE	Unk	C	Unk	1"	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583695	92 SEMINOLE WAY	Unk	UNK-LG	Unk		1978	UNK-LG	Unknown	1978	SF			N			
92779620	6262 RONALD REAG	Unk	P	Unk		UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			
76782893	96 SEMINOLE WAY	Unk	UNK-LG	Unk		1976	C	Unknown	1976	SF	Installation record	Field inspection only	N			
76783158	100 SEMINOLE WAY	Unk	UNK-LG	Unk		1977	C	Unknown	1977	SF	Installation record	Field inspection only	N			
92701069	6239 FOUNTAINHEA	Unk	C	Unk	1"	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882233	205 MOHICAN PASS	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
91505724	6227 DAGNY LN	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782757	209 MOHICAN PASS	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782949	213 MOHICAN PASS	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783586	217 MOHICAN PASS	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782981	216 MOHICAN PASS	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783057	212 MOHICAN PASS	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782971	208 MOHICAN PASS	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783197	204 MOHICAN PASS	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882682	200 MOHICAN PASS	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882450	301 SEMINOLE WAY	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
79515958	305 SEMINOLE WAY	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	SF			N			
76783220	307 SEMINOLE WAY	Unk	C	Unk		1980	C	Unknown	1980	SF	Installation record	Field inspection only	N			
76783462	401 SEMINOLE WAY	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	6/27/2024	Other - describe in notes	
78882643	405 SEMINOLE WAY	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N			
78882490	408 SEMINOLE WAY	Unk	UNK-LG	Unk		1979	UNK-LG	Unknown	1979	SF			N			
78882397	404 SEMINOLE WAY	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N			

79515565	400 SEMINOLE WAY	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	N		
82753261	7743 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753281	7745 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119127	7747 STONECROP W	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515819	7749 STONECROP W	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
79515880	7752 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646607	7750 STONECROP W	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515816	7748 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288705	7746 STONECROP W	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515807	7744 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515764	7742 STONECROP W	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515794	7740 STONECROP W	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	SF	Installed after lead ban	Installed after lead ban	N		
91214053	7712 STONECROP W	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824624	4877 SUNNY SPRING	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86966954	4873 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86967002	4869 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028062	4865 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86967004	4861 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86966956	4860 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86967005	4864 SUNNY SPRING	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938919	976 GRIFFIN WAY	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86966957	993 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028065	991 GRIFFIN WAY	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N		
88065453	987 GRIFFIN WAY	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065452	985 GRIFFIN WAY	Unk	P	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
85668596	979 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288717	977 GRIFFIN WAY	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88065426	975 GRIFFIN WAY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
88065446	971 GRIFFIN WAY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
88065438	969 GRIFFIN WAY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
86482128	967 GRIFFIN WAY	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230672	961 GRIFFIN WAY	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938888	965 GRIFFIN WAY	Unk	P	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028070	988 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80446337	986 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
85668597	984 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028078	982 GRIFFIN WAY	Unk	P	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515400	980 GRIFFIN WAY	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515422	974 GRIFFIN WAY	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515396	972 GRIFFIN WAY	Unk	P	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741043	927 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90292441	928 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90028080	929 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824616	930 LAVENDER WAY	Unk	UNK-NOLG	Unk		2020	UNK-NOLG	Unknown	2020	SF	Installed after lead ban	Installed after lead ban	N		
85667609	931 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288718	932 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90292480	933 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288721	934 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90942257	935 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90942254	936 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90292463	937 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288732	938 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90292442	939 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482125	940 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938915	941 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
90942258	942 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482139	944 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230689	945 LAVENDER WAY	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
91921194	946 LAVENDER WAY	Unk	C	Unk	1"	2022	UNK-NOLG	Unknown	2022	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288710	947 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515412	948 LAVENDER WAY	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482120	949 LAVENDER WAY	Unk	UNK-NOLG	Unk		2019	UNK-NOLG	Unknown	2019	SF	Installed after lead ban	Installed after lead ban	N		
84938900	950 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482111	951 LAVENDER WAY	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
91921198	952 LAVENDER WAY	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753284	925 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753272	927 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753267	929 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753274	931 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753271	933 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646581	937 RUMLEY RUN	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
84230682	939 RUMLEY RUN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646573	941 RUMLEY RUN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230695	943 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230681	945 RUMLEY RUN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667607	947 RUMLEY RUN	Unk	UNK-NOLG	Unk		2021	UNK-NOLG	Unknown	2021	SF	Installed after lead ban	Installed after lead ban	N		
91214052	949 RUMLEY RUN	Unk	C	Unk	1"	2021	UNK-NOLG	Unknown	2021	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938889	953 RUMLEY RUN	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
88824642	951 RUMLEY RUN	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230679	922 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583451	923 RUMLEY RUN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515391	924 RUMLEY RUN	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
82753268	926 RUMLEY RUN	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
83646633	928 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119137	930 RUMLEY RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
88824604	932 RUMLEY RUN	Unk	C	Unk	1"	2020	UNK-NOLG	Unknown	2020	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646584	934 RUMLEY RUN	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
84938901	936 RUMLEY RUN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230688	938 RUMLEY RUN	Unk	C	Unk	1"	2018	UNK-NOLG	Unknown	2018	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84938911	940 RUMLEY RUN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783642	919 RUMLEY RUN	Unk	C	Unk	1"	2015	UNK-NOLG	Unknown	2015	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515653	920 RUMLEY RUN	Unk	C	Unk	1"	2010	UNK-NOLG	Unknown	2010	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515511	917 RUMLEY RUN	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317908	918 RUMLEY RUN	Unk	C	Unk	1"	2012	UNK-NOLG	Unknown	2012	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377859	916 RUMLEY RUN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515590	915 RUMLEY RUN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583447	914 RUMLEY RUN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515668	913 RUMLEY RUN	Unk	C	Unk	1"	2009	UNK-NOLG	Unknown	2009	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063791	911 RUMLEY RUN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583594	912 RUMLEY RUN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318005	909 RUMLEY RUN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	2007	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79317927	907 RUMLEY RUN	Unk	C	Unk	1"	2011	UNK-NOLG	Unknown	2011	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583523	908 RUMLEY RUN	Unk	C	Unk	1"	2013	UNK-NOLG	Unknown	2013	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
84515410	6507 GANDER RUN	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
79515837	6511 GANDER RUN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646561	6517 GANDER RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119136	6521 GANDER RUN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
83119144	6520 GANDER RUN	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
86741045	6516 GANDER RUN	Unk	C	Unk	1"	2019	UNK-NOLG	Unknown	2019	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515814	6512 GANDER RUN	Unk	C	Unk	1"	2016	UNK-NOLG	Unknown	2016	SF	Installation record	Installed after lead ban	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515951	6508 GANDER RUN	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	SF	Installed after lead ban	Installed after lead ban	N		
83646606	6504 GANDER RUN	Unk	UNK-NOLG	Unk		2018	UNK-NOLG	Unknown	2018	SF	Installed after lead ban	Installed after lead ban	N		
75583469	505 YORKTOWN RD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
76783239	606 CONSTITUTION	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
76782826	614 CONSTITUTION	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
78882392	627 CONSTITUTION	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	7/16/2024	Other - describe in notes
79515538	623 CONSTITUTION	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
78882559	619 CONSTITUTION	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	7/10/2024	Other - describe in notes
75583533	607 LOUIS CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
75583668	614 LOUIS CT	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		
78882440	618 LOUIS CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
76783163	620 LOUIS CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
79515817	630 LOUIS CT	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N		
76783107	515 YORKTOWN RD	Unk	DI	Unk		UN	DI	10"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter
95143880	404 YORKTOWN RD	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter
76783113	107 ACKER PKWY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
75378035	410 MOHAWK TRL	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes
75378005	406 MOHAWK TRL	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		
75378161	203 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
75378072	400 VALERIA DR	Unk	C	Unk	1"	1961	C	Unknown	1961	SF	Installation record	Field inspection only	Y	6/3/2024	Other - describe GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378196	410 VALERIA DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
75378228	416 VALERIA DR	Unk	C	Unk		1963	UNK-LG	Unknown	1963	MF	Installation record		N		
75378229	424 VALERIA DR	Unk	C	Unk	1"	1963	UNK-LG	Unknown	1963	MF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378232	429 VALERIA DR	Unk	C	Unk	1"	1963	UNK-LG	Unknown	1963	MF	Installation record		N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032438	421 VALERIA DR	Unk	C	Unk	1"	1963	C	Unknown	1963	MF	Installation record	Field inspection only	N		GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515800	305 VALERIA DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N		
95061509	517 N STEVENSON S	Unk	UNK-NOLG	Unk		1994	UNK-NOLG	Unknown	1994	MF	Installed after lead ban	Installed after lead ban	N		
78882268	312 E NORTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installed after lead ban	Installed after lead ban	N		
76783293	502 NELSON CT	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	NONRES	Installed after lead ban	Installed after lead ban	N		
78882208	146 E NORTH ST	Unk	UNK-LG	Unk		1930	UNK-LG	Unknown	1930	SF			N		
76783514	128 E NORTH ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N		
76782702	505 N MAIN ST	Unk	UNK-NOLG	Unk		UN	DI	4"	UN	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me GIS file "2024-01-25_Deforest_water_services.csv" join to export
95061512	509 N MAIN ST	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter
78032446	100 W NORTH ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		
79927947	100 W NORTH ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		

78032439	200 W NORTH ST	Unk	C	Unk		1985	C	Unknown	1985	NONRES	Installation record	Field inspection only	N			
76783383	208 W NORTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installed after lead ban	Installed after lead ban	N			
78032410	225 W NORTH ST	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	MF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032402	209 W NORTH ST	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	MF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032444	109 W NORTH ST	Unk	UNK-LG	Unk		1982	C	Unknown	1982	MF		Field inspection only	Y	5/27/2024	Other - describe in notes	
78882367	109 W NORTH ST # 1	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/27/2024	Other - describe in notes	
78882462	424 N MAIN ST	Unk	C	Unk		1960	C	Unknown	1960	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
79204309	420 N MAIN ST	Unk	C	Unk	1"	1977	C	Unknown	1977	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882388	416 N MAIN ST	Unk	C	Unk	1"	1997	UNK-NOLG	Unknown	1997	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82759509	308 N MAIN ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78032441	210 N MAIN ST	Unk	C	Unk		1978	C	Unknown	1978	NONRES	Installation record	Field inspection only	N	1/24/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782711	321 N MAIN ST	Unk	DI	Unk	6"	1981	DI	4"	1981	NONRES	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782713	321 N MAIN ST	Unk	DI	Unk	6"	1981	C	1-1/2"	1981	NONRES	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882364	118 ANTIQUE LN	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	NONRES			N			
78882338	120 ANTIQUE LN	Unk	UNK-LG	Unk		1980	UNK-LG	Unknown	1980	NONRES			N			
76783495	116 ANTIQUE LN UN	Unk	C	Unk	1"	UN	UNK-LG	Unknown	UN	NONRES	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
83557944	112 ANTIQUE LN	Unk	UNK-NOLG	Unk		1991	UNK-NOLG	Unknown	1991	MF	Installed after lead ban	Installed after lead ban	N			
76783473	129 E NORTH ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
76783655	608 PARK AVE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783470	502 N HALSOR ST	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	7/19/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882580	407 TRAIL SIDE DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
82753303	427 TRAIL SIDE DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
75583307	443 TRAIL SIDE DR	Unk	C	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76782715	529 TRAIL SIDE DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
78882329	421 YAHARA ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
79927948	500 E NORTH ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
76783399	406 E NORTH ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	SF	Installed after lead ban	Installed after lead ban	N			
76783477	408 E NORTH ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
78882562	410 E NORTH ST	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/22/2024	Other - describe in notes	
78882542	412 E NORTH ST	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
78882578	510 BASSETT ST UNI	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79639874	500 BASSETT ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	MF	Installed after lead ban	Installed after lead ban	N			
78882380	510 BASSETT ST UNI	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Installation record	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032445	504 BASSETT ST	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	MF	Installed after lead ban	Installed after lead ban	N			
78032470	506 BASSETT ST	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes	
78882642	510 BASSETT ST # C	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882356	600 BASSETT ST # 1	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515631	510 BASSETT ST # D	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515892	602 BASSETT ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783353	510 BASSETT ST # E	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882686	605 BASSETT ST A	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032419	609 BASSETT ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
95292235	605 BASSETT ST E	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
76782714	614 BAKKE DR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	NONRES	Installed after lead ban	Installed after lead ban	N			
84515419	612 STOKELY DR	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Installation record	N		Visual insp at meter	
95064449	604 STOKELY DR	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	NONRES	Installed after lead ban	Installed after lead ban	N			
78882398	601 STOKELY DR A	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783270	612 STOKELY DR	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78032436	505 STOKELY DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
78032442	601 STOKELY DR B	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783285	801 BURTON BLVD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
78882524	805 BURTON BLVD	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	NONRES	Installed after lead ban	Installed after lead ban	N			
78882523	809 BURTON BLVD	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	NONRES	Installed after lead ban	Installed after lead ban	N			
79153171	813 BURTON BLVD	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	NONRES	Installed after lead ban	Installed after lead ban	N			
76782727	720 LITTLE POTATO	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	NONRES	Installed after lead ban	Installed after lead ban	N			
78032437	804 BURTON BLVD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
79515621	800 BURTON BLVD	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	NONRES	Installed after lead ban	Installed after lead ban	N			
78882346	705 STOKELY DR	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	NONRES	Installed after lead ban	Installed after lead ban	N			
95143889	612 BURTON BLVD	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	NONRES	Installed after lead ban	Installed after lead ban	N			
95292227	609 BURTON BLVD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
95061511	600 BURTON BLVD S	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N			
78032407	600 BURTON BLVD S	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N			
79256116	612 N STEVENSON S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
75583232	610 N STEVENSON S	Unk	DI	Unk	8"	UN	C	3/4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
98694261	801 LITTLE POTATO	Unk	UNK-NOLG	Unk		2016	UNK-NOLG	Unknown	2016	NONRES	Installed after lead ban	Installed after lead ban	N			
82265673	751 SHONKOO WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
79515948	521 N STEVENSON S	Unk	UNK-NOLG	Unk		1985	UNK-LG	Unknown	1985	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
87288714	710 SHONKOO WAY	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
94505583	749 LITTLE POTATO	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
78882250	234 COLUMBIA AVE	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
79515725	316 N STEVENSON S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782724	304 LINDE ST	Unk	P	Unk	1-1/2"	1984	C	Unknown	1984	MF	Installation record	Field inspection only	Y	5/28/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032440	301 LINDE ST	Unk	P	Unk	1-1/2"	1984	UNK-LG	Unknown	1984	MF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782717	305 LINDE ST	Unk	P	Unk	1-1/2"	1984	C	Unknown	1984	MF	Installation record	Field inspection only	Y	5/24/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75120908	304 COLUMBIA AVE	Unk	P	Unk	1-1/2"	1982	UNK-LG	Unknown	1982	MF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882325	300 COLUMBIA AVE	Unk	P	Unk	1-1/2"	1983	C	Unknown	1983	MF	Installation record	Field inspection only	Y	7/18/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83646605	236 COLUMBIA AVE	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78882564	212 COLUMBIA AVE	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78882522	204 COLUMBIA AVE	Unk	P	Unk	1-1/2"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882565	113 N DURKEE ST	Unk	P	Unk	1-1/2"	1950	C	Unknown	1950	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882535	206 E HOLUM ST	Unk	P	Unk	1-1/2"	1900	UNK-LG	Unknown	1900	MF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032403	210 E HOLUM ST	Unk	C	Unk		1970	C	Unknown	1970	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882531	210 E HOLUM ST	Unk	UNK-NOLG	Unk		1970	C	Unknown	1970	NONRES	Installation record	Installation record	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378230	300 E HOLUM ST	Unk	UNK-NOLG	Unk		1960	C	Unknown	1960	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783487	316 E HOLUM ST # 1	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783481	320 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882231	332 E HOLUM ST	Unk	C	Unk		1974	C	Unknown	1974	NONRES	Installation record	Field inspection only	N			
76783253	111 N STEVENSON S	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882409	420 E HOLUM ST	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/14/2024	Other - describe in notes	
76783620	436 E HOLUM ST	Unk	UNK-LG	Unk		UN	L	Unknown	UN	SF		Field inspection only	Y	3/3/2025	Visual insp at meter	
79228371	520 E HOLUM ST	Unk	C	Unk		UN	C	3/4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
83646540	520 E HOLUM	Unk	CI-U	Unk		UN	CI-U	4"	UN	NONRES	Installation record	Field inspection only	N			
81340475	206 N JOHNSON ST	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783380	727 PARK AVE	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
79515581	723 PARK AVE	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/31/2024	Other - describe in notes	
76783408	726 COLUMBIA AVE	Unk	C	Unk	1"	UN	UNK-LG	Unknown	UN	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882624	212 N HALSOR ST	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783509	805 E HOLUM ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
76783510	813 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882402	820 E HOLUM ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	SF	Installed after lead ban	Installed after lead ban	N			
78882362	837 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882581	841 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783552	206 BRUNS ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	7/9/2024	Other - describe in notes	
78882228	210 BRUNS ST	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
78882437	212 BRUNS ST	Unk	C	Unk	1"	UN	UNK-LG	Unknown	UN	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667816	218 BRUNS ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
95143894	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
29618271	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
96228893	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
95143888	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	8"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
89101173	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
82265680	815 JEFFERSON ST	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N			
78882431	721 E HOLUM ST	Unk	UNK-LG	Unk		1950	UNK-LG	Unknown	1950	SF			N			
76783214	623 JEFFERSON ST	Unk	DI	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
76783213	619 JEFFERSON ST	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76782719	615 JEFFERSON ST	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter	
76783601	216 S CLEVELAND A	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783272	208 S CLEVELAND A	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882343	202 S CLEVELAND A	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
80063792	519 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783131	505 E HOLUM ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	NONRES	Installed after lead ban	Installed after lead ban	N			
76783391	407 E HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783362	405 E HOLUM ST	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
78032404	508 DEFOREST ST	Unk	C	Unk		1970	C	Unknown	1970	MF	Installation record	Field inspection only	Y	5/16/2024	Other - describe in notes	
78032405	512 DEFOREST ST	Unk	UNK-LG	Unk		1973	UNK-LG	Unknown	1973	MF			N			
76782729	516 DEFOREST ST	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	MF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032423	520 DEFOREST ST	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	MF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882275	524 DEFOREST ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
83119130	110 S CLEVELAND A	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782726	201 DANBURY CT	Unk	UNK-NOLG	Unk		1977	C	Unknown	1977	MF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782721	205 DANBURY CT	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	MF			N			
76782730	206 DANBURY CT	Unk	UNK-NOLG	Unk		1976	UNK-LG	Unknown	1976	MF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78032412	110 S STEVENSON S	Unk	UNK-NOLG	Unk		UN	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
95143887	110 S STEVENSON S	Unk	UNK-NOLG	Unk		UN	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
82062221	120 S STEVENSON S	Unk	UNK-NOLG	Unk		UN	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
82268778	300 JEFFERSON ST	Unk	DI	Unk	6"	UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
88460846	300 JEFFERSON ST	Unk	DI	Unk	6"	UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063698	405 JEFFERSON ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	7/17/2024	Other - describe in notes	
76783594	421 JEFFERSON ST	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	N			
76783533	301 SOUTHBOUND I	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783179	545 JEFFERSON ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78032418	520 JEFFERSON ST	Unk	UNK-NOLG	Unk		1975	C	Unknown	1975	MF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter	
78032420	512 JEFFERSON ST	Unk	UNK-LG	Unk		1975	UNK-LG	Unknown	1975	MF			N			
75583713	542 DAHL DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783073	528 DAHL DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			

76782935	520 DAHL DR	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783063	636 CONSTITUTION	Unk	UNK-NOLG	Unk		1997	UNK-NOLG	Unknown	1997	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782841	608 SOUTHBOUND I	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
78886711	829 SOUTHBOUND I	Unk	C	Unk		UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
79317850	815 SOUTHBOUND I	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
79317933	801 SOUTHBOUND I	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782890	360 BLACKBERRY LN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75583671	354 BLACKBERRY LN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782864	352 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
76782833	344 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2004	UNK-NOLG	Unknown	2004	SF	Installed after lead ban	Installed after lead ban	N			
79515893	336 BLACKBERRY LN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
95292234	805 TANGLEWOOD	Unk	DI	Unk		UN	DI	Unknown	UN	MF	Installation record	Field inspection only	N	3/5/2025	Visual insp at meter	
95292230	335 BLACKBERRY LN	Unk	UNK-NOLG	Unk		2005	UNK-NOLG	Unknown	2005	MF	Installed after lead ban	Installed after lead ban	N			
95292231	357 BLACKBERRY LN	Unk	DI	Unk		UN	DI	Unknown	UN	MF	Installation record	Field inspection only	N	3/5/2025	Visual insp at meter	
76783631	107 RENATA CT	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/31/2024	Other - describe in notes	
78882386	109 RENATA CT	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882216	106 RENATA CT	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
79515712	211 BRUNS ST	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
78073857	931 E HOLUM ST	Unk	C	Unk		1992	UNK-NOLG	Unknown	1992	MF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882370	940 E HOLUM ST	Unk	C	Unk		1960	C	Unknown	1960	NONRES	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter	
79256115	937 E HOLUM ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80782752	7372 N TOWNE RD	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
80782744	7372 N TOWNE RD	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
80782745	7372 N TOWNE RD	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
80782746	7372 N TOWNE RD	Unk	UNK-NOLG	Unk		2017	UNK-NOLG	Unknown	2017	NONRES	Installed after lead ban	Installed after lead ban	N			
78032409	101 S MAIN ST	Unk	C	Unk		2006	UNK-NOLG	Unknown	2006	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
95292232	101 ETHUN PL	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	NONRES	Installed after lead ban	Installed after lead ban	N			
95292233	125 E HOLUM ST	Unk	UNK-NOLG	Unk		2006	UNK-NOLG	Unknown	2006	NONRES	Installed after lead ban	Installed after lead ban	N			
79639875	203 LIBRARY ST	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	Y			
78882630	145 E HOLUM ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78882628	145 E HOLUM ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75583279	136 W HOLUM ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	NONRES			N			
95061516	100 E HOLUM ST	Unk	UNK-NOLG	Unk		2015	UNK-NOLG	Unknown	2015	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515722	134 E HOLUM ST	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378236	100 S MAIN ST	Unk	C	Unk	1"	1986	C	Unknown	1986	NONRES	Installation record	Field inspection only	Y	5/27/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377751	109 W HOLUM ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/27/2024	Other - describe in notes	
75377807	115 REGSTAD ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
81814293	220 S MAIN ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75377945	200 S MAIN ST	Unk	C	Unk		1964	C	1"	1964	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377806	136 S MAIN ST	Unk	C	Unk		1979	C	1"	1979	NONRES	Installation record	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583428	128 S MAIN ST	Unk	C	Unk		UN	L	Unknown	UN	SF	Installation record	Field inspection only	Y	6/10/2024	Other - describe in notes	
75583456	112 S MAIN ST	Unk	C	Unk		1920	L	Unknown	1920	SF	Installation record	Field inspection only	Y	8/13/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583696	100 COMMERCE ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installed after lead ban	Field inspection only	Y	5/13/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583692	100 COMMERCE ST	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	NONRES	Installed after lead ban	Field inspection only	Y	5/13/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75370000	234 LIBRARY ST	Unk	DI	Unk		UN	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378176	142 MARKET ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter	
75377857	151 COMMERCE ST	Unk	UNK-NOLG	Unk		UN	UNK-LG	Unknown	UN	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377915	148 MARKET ST	Unk	UNK-NOLG	Unk		1950	UNK-LG	Unknown	1950	NONRES	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378234	148 MARKET ST	Unk	UNK-NOLG	Unk		1950	C	Unknown	1950	NONRES	Installed after lead ban	Field inspection only	N	3/11/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378034	105 PLEASANT VW	Unk	UNK-NOLG	N		1900	G	Unknown	1900	SF	Installed after lead ban	Field inspection only	Y	5/14/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583518	109 PLEASANT VW	Unk	C	Unk		1925	UNK-LG	Unknown	1925	SF	Installation record		N			
75583346	115 PLEASANT VW	Unk	UNK-NOLG	Unk		1920	C	Unknown	1920	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378223	119 PLEASANT VW	Unk	UNK-NOLG	Unk		1920	C	Unknown	1920	SF	Installed after lead ban	Field inspection only	Y	7/17/2024	Other - describe	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515896	112 PLEASANT VW	Unk	C	N		1940	G	Unknown	1940	SF	Installation record	Field inspection only	Y	5/17/2024	Other - describe in notes	
80063657	120 PLEASANT VW	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
75583373	123 PLEASANT VW	Unk	UNK-NOLG	Unk		1900	C	Unknown	1900	SF	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75377774	401 MARKET ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter	
75583442	324 MARKET ST	Unk	P	Unk	1"	1920	UNK-LG	Unknown	1920	SF	Installation record		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
75583386	119 E ELM ST	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter	
75377838	105 MEADOW LN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
75377917	101 MEADOW LN	Unk	C	Unk		UN	UNK-LG	Unknown	UN	SF	Installation record		N			
75378104	102 VINBURN RD	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
75377918	781 S MAIN ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N	3/11/2025	Visual insp at meter	
75378041	639 S MAIN ST	Unk	DI	Unk	6"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378108	645 S MAIN ST	Unk	DI	Unk	6"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378100	635 S MAIN ST	Unk	DI	Unk	6"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378139	633 S MAIN ST	Unk	DI	Unk	6"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378095	627 S MAIN ST	Unk	DI	Unk	6"	UN	C	6"	UN	NONRES	Installation record	Field inspection only	N			
75378039	623 S MAIN ST	Unk	P	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N			
75378044	625 S MAIN ST	Unk	C	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installation record	Installed after lead ban	N			
75369999	621 S MAIN ST	Unk	P	Unk		UN	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N	11/21/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378144	619 S MAIN ST	Unk	C	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378143	619 S MAIN ST A	Unk	P	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378141	607 S MAIN ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378142	611 S MAIN ST	Unk	C	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75378140	615 S MAIN ST	Unk	P	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
75378137	617 S MAIN ST	Unk	P	Unk		1985	DI	6"	1985	NONRES	Installation record	Field inspection only	N			
75378136	605 S MAIN ST	Unk	C	Unk		1985	DI	6"	1985	NONRES	Installation record	Field inspection only	N			
75378235	601 S MAIN ST	Unk	C	Unk		1975	DI	6"	1975	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75583516	119 MURRAY ST	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
75583437	104 MURRAY ST	Unk	C	Unk		UN	C	3/4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75377940	416 MARKET ST	Unk	UNK-NOLG	Unk		1977	C	3/4"	1977	NONRES	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
75378243	408 MARKET ST	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
75583306	417 ACKER PKWY	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
79317903	529 WILD PLUM DR	Unk	C	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installation record	Installed after lead ban	N			
75377938	525 WILD PLUM DR	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/6/2024	Other - describe in notes	
75377841	101 RIVERWOOD BN	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/14/2024	Other - describe in notes	
76783054	105 RIVERWOOD BN	Unk	UNK-LG	Unk		1984	UNK-LG	Unknown	1984	SF			N			
75583375	109 RIVERWOOD BN	Unk	UNK-LG	Unk		1983	UNK-LG	Unknown	1983	SF			N			
75583390	201 RIVERWOOD BN	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	7/19/2024	Other - describe in notes	
75377809	205 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
75378031	209 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
75583510	213 RIVERWOOD BN	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N			
75583457	217 RIVERWOOD BN	Unk	C	Unk		1984	C	Unknown	1984	SF	Installation record	Field inspection only	Y	6/19/2024	Other - describe in notes	
75377812	301 RIVERWOOD BN	Unk	C	Unk		1983	C	Unknown	1983	SF	Installation record	Field inspection only	Y	6/19/2024	Other - describe in notes	
75377979	305 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
75377803	309 RIVERWOOD BN	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	Y	5/21/2024	Other - describe in notes	
75378244	313 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
75583496	317 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			
75583263	405 RIVERWOOD BN	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N			
75377827	409 RIVERWOOD BN	Unk	UNK-LG	Unk		1985	UNK-LG	Unknown	1985	SF			N			
75378132	413 RIVERWOOD BN	Unk	C	Unk		1986	C	Unknown	1986	SF	Installation record	Field inspection only	N			
78882675	417 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			
75377996	400 RIVERWOOD BN	Unk	C	Unk		1979	C	Unknown	1979	SF	Installation record	Field inspection only	Y	5/13/2024	Visual insp at meter	
75583481	408 RIVERWOOD BN	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	N			
75583266	412 RIVERWOOD BN	Unk	UNK-LG	Unk		1986	UNK-LG	Unknown	1986	SF			N			
75377848	416 RIVERWOOD BN	Unk	UNK-NOLG	Unk		1988	UNK-NOLG	Unknown	1988	SF	Installed after lead ban	Installed after lead ban	N			
75377821	417 MAYAPPLE CIR	Unk	UNK-NOLG	Unk		1989	UNK-NOLG	Unknown	1989	SF	Installed after lead ban	Installed after lead ban	N			
75583509	413 MAYAPPLE CIR	Unk	UNK-NOLG	Unk		1987	UNK-NOLG	Unknown	1987	SF	Installed after lead ban	Installed after lead ban	N			
75377953	409 MAYAPPLE CIR	Unk	C	Unk		1978	C	Unknown	1978	SF	Installation record	Field inspection only	Y	5/29/2024	Other - describe in notes	
82753265	505 SHANE ODONNI	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
82753288	115 CROOKED TREE	Unk	C	Unk	1"	2017	UNK-NOLG	Unknown	2017	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79639876	110 EVCO CIR	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78886700	121 EVCO CIR	Unk	DI	Unk		UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
78032411	4866 COUNTY HWY	Unk	UNK-NOLG	Unk		UN	C	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
76503402	4905 COUNTY HWY	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78886693	120 EVCO CIR	Unk	UNK-NOLG	Unk		2001	UNK-NOLG	Unknown	2001	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78886697	911 W NORTH ST	Unk	DI	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
78886695	4884 CTY HWY V	Unk	DI	Unk		UN	C	1-1/2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
87749407	4886 COUNTY HIGH	Unk	DI	Unk	6"	2022	UNK-NOLG	Unknown	2022	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78886694	4910 COUNTY HIGH	Unk	UNK-NOLG	Unk		UN	C	2"	UN	NONRES	Installed after lead ban	Field inspection only	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82759524	4876 COUNTY HIGH	Unk	UNK-NOLG	Unk		2022	UNK-NOLG	Unknown	2022	NONRES	Installed after lead ban	Installed after lead ban	N			
78032406	981 W NORTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82268782	4848 CTY HWY V IRF	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
82268777	4848 CTY HWY V CA	Unk	DI	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
82268776	4848 CTY HWY V CA	Unk	DI	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
82268775	4848 CTY HWY V STI	Unk	P	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75583535	7203 GENE ST	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
94686007	7219 GENE ST	Unk	DI	Unk		UN	DI	1-1/2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
75583473	7227 GENE ST	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76782763	7231 GENE ST	Unk	DI	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76782799	7235 GENE ST	Unk	DI	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783055	5008 LINDE LN STE 1	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783145	5008 LINDE LN STE 2	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783581	5008 LINDE LN STE 3	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783053	5008 LINDE LN STE 4	Unk	DI	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76783105	7208 GENE ST STE 1	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N			
76783106	7208 GENE ST STE 1	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N	3/6/2025	Visual insp at meter	
78882359	7208 GENE ST STE 1	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N	3/6/2025	Visual insp at meter	
76503392	7208 GENE ST STE 1	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N	3/6/2025	Visual insp at meter	
95061513	7205 CTY HWY I	Unk	DI	Unk		UN	DI	4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
76503394	5005 CAKE PKWY	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
88460845	5000 CAKE PKWY	Unk	DI	Unk		UN	DI	6"	UN	NONRES	Installation record	Field inspection only	N	3/4/2025	Visual insp at meter	
80782750	4951 CAKE PKWY	Unk	DI	Unk		UN	P	1"	UN	NONRES	Installation record	Installed after lead ban	N	3/4/2025	Visual insp at meter	
76783451	404 IROQUOIS CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			

76783330	505 ST CROIX CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783616	501 ST CROIX CT	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783648	500 ST CROIX CT	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/28/2024	Other - describe in notes	
76783232	504 ST CROIX CT	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	5/17/2024	Other - describe in notes	
79515939	516 LYNNBROOK DR	Unk	UNK-NOLG	Unk		2003	UNK-NOLG	Unknown	2003	SF	Installed after lead ban	Installed after lead ban	N			
75583714	505 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	C	Unknown	UN	SF		Field inspection only	Y	5/24/2024	Other - describe in notes	
76783102	549 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783095	553 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76783098	602 OLD INDIAN TRL	Unk	C	Unk		UN	C	1"	UN	SF	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
76782809	632 OLD INDIAN TRL	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installed after lead ban	Installed after lead ban	N			
76782999	529 W NORTH ST	Unk	UNK-NOLG	Unk		2000	UNK-NOLG	Unknown	2000	NONRES	Installed after lead ban	Installed after lead ban	N			
95061508	525 W NORTH ST	Unk	C	Unk		UN	C	2"	UN	NONRES	Installation record	Field inspection only	N			
75583584	523 W NORTH ST	Unk	C	Unk		1984	C	1-1/2"	1984	NONRES	Installation record	Field inspection only	N	3/4/2025	Visual insp at meter	
76783039	517 W NORTH ST ST	Unk	C	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
76503397	505 W NORTH ST	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	NONRES	Installed after lead ban	Installed after lead ban	N			
76503398	501 COUNTRY VIEW	Unk	C	Unk		UN	C	1"	UN	NONRES	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
76782708	602 W NORTH ST	Unk	UNK-NOLG	Unk		1990	UNK-NOLG	Unknown	1990	NONRES	Installed after lead ban	Installed after lead ban	N			
76782822	635 OLD INDIAN TRL	Unk	C	Unk		1986	C	1"	1986	NONRES	Installation record	Installed after lead ban	N	3/3/2025	Visual insp at meter	
76783092	625 W NORTH ST	Unk	UNK-NOLG	Unk		1998	UNK-NOLG	Unknown	1998	NONRES	Installed after lead ban	Installed after lead ban	N			
78886701	637 W NORTH ST	Unk	UNK-NOLG	Unk		1999	UNK-NOLG	Unknown	1999	NONRES	Installed after lead ban	Installed after lead ban	N			
76782837	601 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063722	603 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782747	605 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
80063664	607 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782859	609 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1993	UNK-NOLG	Unknown	1993	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
76782855	613 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782860	615 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
80063688	627 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
79515791	631 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
76782731	633 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1995	UNK-NOLG	Unknown	1995	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063731	637 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882655	632 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882644	628 SEMINOLE WAY	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882614	626 SEMINOLE WAY	Unk	UNK-NOLG	Unk		1992	UNK-NOLG	Unknown	1992	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882309	600 SEMINOLE WAY	Unk	C	Unk		UN	C	Unknown	UN	SF	Installation record	Field inspection only	N			
83646580	211 N LEXINGTON P	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
78882480	219 N LEXINGTON P	Unk	UNK-LG	Unk		UN	UNK-LG	Unknown	UN	SF			N			
79204317	234 N LEXINGTON P	Unk	DI	Unk		UN	C	4"	UN	NONRES	Installation record	Field inspection only	N		Visual insp at meter	
	405 MEADOW	Unk		UN		UN			UN	SF			N			
79515680	407 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
79515577	409 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
75583557	413 MEADOW OAK '	Unk	UNK-NOLG	Unk	Unknown	1992	UNK-LG	Unknown	UN	SF	Installed after lead ban		N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515881	417 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
79515938	419 MEADOW OAK '	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
79515868	410 MEADOW OAK '	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N			
78882308	401 TRAIL SIDE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
75583627	702 W LEXINGTON I	Unk	UNK-NOLG	Unk	Unknown	1992	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78882587	177 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	C	Unknown	UN	SF		Field inspection only	N			
78882259	734 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783584	732 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783404	730 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783410	728 DEFOREST ST	Unk	UNK-NOLG	Unk	Unknown	1989	C	1"	UN	SF	Installed after lead ban	Field inspection only	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
76783482	726 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783516	724 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783621	722 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783291	720 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783426	718 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783361	716 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882500	712 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783225	710 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783312	708 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882695	706 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Mech excav	
78882282	704 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783414	702 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783273	700 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783304	701 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783294	703 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783216	705 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783535	707 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783635	709 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783231	711 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783313	713 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783390	715 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783529	717 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882381	719 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783424	721 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882280	723 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882387	725 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783209	727 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882263	729 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882199	731 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783314	735 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783397	737 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882468	739 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783615	741 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783290	743 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783326	745 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783341	747 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783368	749 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783329	751 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882489	753 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783485	755 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783284	758 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783480	756 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783431	754 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783262	734 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882340	732 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783490	730 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783433	726 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783434	724 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882455	720 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783566	718 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783217	716 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783540	710 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783576	708 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882281	706 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
78882267	704 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
76783544	717 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter	
75378184	602 SPRINGBROOK I	Unk	C	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
80782747	811 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515925	807 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515913	815 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515636	815 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
78032414	819 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
75378237	120 VINBURN RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
79515929	6924 LAKE RD	Unk	C	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Installed after lead ban	N	3/3/2025	Visual insp at meter	
78886696	105 PARADISE CIR	Unk	C	Unk	Unknown	UN	UNK-LG	2"	UN	NONRES	Installation record	Field inspection only	N	3/3/2025	Visual insp at meter	
79515952	108 PARADISE CIR	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
87288724	609 ACKER PKWY	Unk	C	Unk	10"	UN	C	Unknown	UN	NONRES	Installation record	Field inspection only	N			
83646585	110 PARADISE CIR	Unk	C	Unk	1"	2001	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
79318001	119 PARADISE CIR	Unk	C	Unk	1"	2001	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
86482138	4160 REARDON RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Installed after lead ban	N	3/3/2025	Visual insp at meter	
82268780	4197 REARDON RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	NONRES			N			
82759507	4159 REARDON RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
86482116	4180 REARDON RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
86482117	609 ACKER PKWY	Unk	C	Unk	10"	UN	DI	10"	UN	NONRES	Installation record	Field inspection only	N			
83646614	6884 TUSCAN RIDGE	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
79515516	4650 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91505734	6714 CONSERVANCY	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91505733	6716 CONSERVANCY	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
79515503	6773 VILLAGE WALK	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
83646611	4646 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90028057	4651 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
80063730	4653 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942435	4655 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91921193	4657 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
88824610	4659 WHITEBUD TEI	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
75583461	6908 LARKSPUR LN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85668541	4884 INNOVATION I	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85668544	4890 INNOVATION I	Unk	P	Unk	1"	2022	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
85667934	4898 INNOVATION I	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667913	4906 INNOVATION I	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
92263209	4605 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92263202	4607 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92263204	4611 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			

92263205	4613 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
85669123	4671 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
85669127	4679 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
85669128	4681 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
85669126	4677 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701053	4623 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701048	4625 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701051	4619 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701047	4621 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701050	4615 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701046	4617 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701056	4651 BELLFLOWER (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
92779627	4655 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92779626	4657 BELLFLOWER (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92701054	4659 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
92779622	4661 BELLFLOWER (	Unk	P	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N			
79515838	7736 CATCHFLY LN	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
75583589	7709 AUTUMN BLAZ	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
80063782	6919 LARKSPUR LN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
82753297	6913 LARKSPUR LN	Unk	C	Unk	1"	2007	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
84230669	4839 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90655822	4958 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	MF	Installed after lead ban	Installed after lead ban	N			
75179071	4897 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	MF	Installed after lead ban	Installed after lead ban	N			
83646600	4873 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
83646597	4877 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
84230674	4835 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
84230673	4847 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
76782947	4876 INNOVATION (	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
76782948	4878 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
76782952	4880 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
76782951	4882 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
78882650	4872 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
78882653	4870 INNOVATION (	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
79228370	6909 RIVER RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
78032416	1525 RIVER RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installed after lead ban	Field inspection only	N	1/6/2025	Visual insp at meter	
78032417	1525 RIVER RD	Unk	UNK-NOLG	Unk	Unknown	UN	DI	Unknown	UN	NONRES	Installed after lead ban	Field inspection only	N	2/26/2025	Visual insp at meter	
79515576	1505 RIVER RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
88824636	6970 CRYSTAL CREE	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Installed after lead ban	N			
91214056	4501 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214055	4503 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292469	4505 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292473	4507 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292459	4509 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292460	4511 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292470	4513 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292458	4515 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292448	4517 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292447	4519 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292446	4521 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292443	4523 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292456	4525 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292455	4527 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292454	4529 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292453	4531 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292449	4533 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292450	4535 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292451	4537 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292452	4539 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292471	4541 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292465	4543 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292472	4545 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292466	4547 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90292467	4549 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667811	4550 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667818	4548 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214054	4516 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214051	4514 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
92263206	4520 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667911	4518 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667931	4542 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667910	4540 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91921191	4546 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
85667812	4544 SPRINGS CT	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
82268781	7125 RIVER RD	Unk	C	Unk	Unknown	UN	C	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
90942268	6710 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942267	6712 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214058	6714 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942266	6716 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214062	6718 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942265	6704 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942269	6706 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91505731	6719 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214061	6713 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91214064	6715 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
90942264	6708 YAHARA SPRIN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91505730	6718 CONSERVANCY	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
91505732	6720 CONSERVANCY	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
86556108	6750 RIVER RD	Unk	DI	Unk	6"	UN	DI	4"	UN	NONRES	Installation record	Installation record	N			
95064450	6750 RIVER RD	Unk	DI	Unk	6"	UN	DI	4"	UN	NONRES	Installation record	Installation record	N			
75583321	6822 YELLOWWOOI	Unk	UNK-NOLG	Unk	1"	2005	C	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
81946460	6822 YELLOWWOOI	Unk	C	Unk	Unknown	UN	C	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
81340474	4633 LIUNA WAY ST	Unk	DI	Unk	Unknown	UN	DI	8"	UN	NONRES	Installed after lead ban	Installed after lead ban	N	2/26/2025	Visual insp at meter	
75120909	4409 STATE HWY 19	Unk	DI	Unk	Unknown	UN	C	2"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
82062235	4401 HWY 19	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	NONRES			N			
79639877	4190 BEAR TREE PK\	Unk	DI	Unk	6"	2014	UNK-NOLG	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
81946458	6199 METRO DR	Unk	DI	Unk	Unknown	UN	DI	8"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
82308289	6195 METRO DR	Unk	DI	Unk	Unknown	UN	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
79515887	6175 METRO DR 9-1	Unk	UNK-NOLG	Unk	Unknown	1995	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515884	6175 METRO DR 4-8	Unk	UNK-NOLG	Unk	Unknown	1995	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
80782751	6175 METRO DR 1-3	Unk	DI	Unk	Unknown	1995	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
81814288	6135 N AMERICAN L	Unk	UNK-NOLG	Unk	Unknown	UN	C	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
79515889	6129 HWY 51	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	NONRES			N			
90028058	6135 N AMERICAN L	Unk	UNK-NOLG	Unk	Unknown	UN	C	3/4"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
91214057	6129 HWY 51	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	NONRES			N			
82759523	6191 METRO DR	Unk	DI	Unk	Unknown	UN	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N		Visual insp at meter	
82062236	5901 HWY 51	Unk	DI	Unk	Unknown	UN	DI	6"	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
81814289	4246 DAENTL RD	Unk	DI	Unk	Unknown	UN	DI	6"	UN	NONRES	Installation record	Installed after lead ban	N		Visual insp at meter	
81814283	4334 DAENTL RD	Unk	DI	Unk	6"	2007	DI	6"	UN	NONRES	Installation record	Installation record	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
92701061	6132 DANIELLE RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
92779628	6134 DANIELLE RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			
79927923	4205 ANDERSON RD	Unk	C	Unk	Unknown	UN	DI	4"	UN	NONRES	Installation record	Installed after lead ban	N			
81814291	4195 ANDERSON RD	Unk	C	Unk	Unknown	UN	C	2"	UN	NONRES	Installation record	Installed after lead ban	N			
78032421	4165 ANDERSON RD	Unk	C	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Installed after lead ban	N			
79515864	3821 ANDERSON RD	Unk	C	Unk	Unknown	UN	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N			
79515829	4160 ANDERSON RD	Unk	C	Unk	6"	2000	C	1"	UN	NONRES	Installation record	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
80063793	5904 HAASE RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Installed after lead ban	N	2/26/2025		
78032429	5900 HAASE RD	Unk	C	Unk	Unknown	1995	C	1"	UN	NONRES	Installed after lead ban	Installed after lead ban	N	1/6/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515869	5903 HAASE RD	Unk	DI	Unk	Unknown	1995	DI	Unknown	UN	NONRES	Installation record	Installed after lead ban	N	12/10/2024	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
81814285	5912 HAASE RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Installed after lead ban	N	2/26/2025	Visual insp at meter	
81814284	5924 HAASE RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installed after lead ban	Installed after lead ban	N	2/26/2025	Visual insp at meter	
82062222	5927 HAASE RD	Unk	UNK-NOLG	Unk	Unknown	UN	C	2"	UN	NONRES	Installed after lead ban	Installed after lead ban	N	3/5/2025	Visual insp at meter	
81814290	5931 HASSE RD	Unk	UNK-NOLG	Unk	Unknown	UN	C	1-1/2"	UN	NONRES	Installed after lead ban	Installed after lead ban	N	2/26/2025	Visual insp at meter	
81814292	5945 HASSE RD	Unk	DI	Unk	Unknown	UN	C	1-1/2"	UN	NONRES	Installation record	Installed after lead ban	N	2/26/2025	Visual insp at meter	
79515812	5952 HAASE RD	Unk	DI	Unk	Unknown	1995	DI	6"	UN	NONRES	Installed after lead ban	Field inspection only	N	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515860	5959 HAASE RD	Unk	DI	Unk	Unknown	UN	C	1"	UN	NONRES	Installation record	Field inspection only	N	1/6/2025	Visual insp at meter	
81814286	5969 HAASE RD	Unk	DI	Unk	6"	1995	DI	Unknown	UN	NONRES	Installation record	Field inspection only	N	2/26/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
79515859	5969 HASSE RD	Unk	DI	Unk	Unknown	UN	DI	Unknown	UN	NONRES	Installed after lead ban	Field inspection only	N	2/26/2025	Visual insp at meter	
79515854	6162 US HWY 51	Unk	UNK-LG	Unk	Unknown	UN	C	Unknown	UN	NONRES		Field inspection only	N	2/26/2025	Visual insp at meter	
87388698	4617 LIUNA WAY	Unk	UNK-NOLG	Unk	Unknown	2007	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
99958495	4630 DALMORE RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
84085065	4620 DALMORE RD	Unk	DI	Unk	6"	2018	DI	8"	UN	NONRES	Installation record	Field inspection only	N	1/6/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
82759525	4665 DALMORE RD	Unk	DI	Unk	Unknown	UN	DI	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
82759505	4665 DALMORE RD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			
82759506	4665 DALMORE RD (	Unk	UNK-NOLG	Unk	Unknown	UN	DI	Unknown	UN	NONRES	Installed after lead ban	Field inspection only	N	2/26/2025	Visual insp at meter	
82759526	4665 DALMORE RD (	Unk	UNK-NOLG	Unk	6"	UN	DI	1-1/2"	UN	NONRES	Installed after lead ban	Field inspection only	N	2/26/2025	Visual insp at meter	
82265660	4200 SAVANNAH DR	Unk	UNK-NOLG	Unk	Unknown	2010	UNK-NOLG	Unknown	UN	NONRES	Installed after lead ban	Installed after lead ban	N			GIS file "2024-01-25_Deforest_water_services.csv" join to export
78886698	4141 SAVANNAH DR	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	MF	Installed after lead ban	Installed after lead ban	N			
81946461	4139 SAVANNAH DR	Unk	UNK-NOLG	Unk	6"	2014	DI	1-1/2"	UN	NONRES	Installed after lead ban	Field inspection only	N	1/6/2025	Visual insp at me	GIS file "2024-01-25_Deforest_water_services.csv" join to export
83231132	4145 SAVANNAH DR	Unk	DI	Unk	6"	UN	C	Unknown	UN	MF	Installation record	Installed after lead ban	N			
79317897	7123 N TOWNE RD	Unk	C	Unk	1"	UN	C	1"	UN	NONRES	Installation record	Field inspection only	N	2/26/2025		
88065451	953 LAVENDAR WA\	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
87288719	931 SKYLARK DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N			
75378062	112 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Field inspection only	Field inspection only	Y	2/25/2025	Visual insp at meter	
76783379	320 S CLEVELAND A'	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Field inspection only	Field inspection only	Y	2/25/2025	Visual insp at meter	
76783379	320 S CLEVELAND A'	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N			

76783340	520 BRULE PKWY	Unk	C	N	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	3/3/2025	Visual insp at meter
75377934	608 SUNNYBROOK D	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installed after lead ban	Field inspection only	N		
75377882	370 CAMPBELL HILL	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
75583684	944 LIBERTY DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782847	712 YORKTOWN RD	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N	3/12/2025	
76782920	809 LINCOLN GREEN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83646612	904 LIBERTY DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83646598	604 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782820	612 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882679	613 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882680	615 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782932	607 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882504	625 YORKTOWN RD	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75583465	605 LOUIS CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583472	603 LOUIS CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782968	COMMUNITY GARD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75583501	137 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79000062	161 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783189	314 VALERIA DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75378200	321 VALERIA DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75378204	317 VALERIA DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75378215	313 VALERIA DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583409	309 VALERIA DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783501	505 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783435	512 DENNIS DR	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
78882368	109 W NORTH ST # A	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783504	402 N MAIN ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/13/2025	Visual insp at meter
80063690	406 N MAIN ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/13/2025	Visual insp at meter
76782720	404 N MAIN ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/13/2025	Visual insp at meter
76783492	116 ANTIQUE LN C	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783338	613 YAHARA ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783511	415 TRAILSIDE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783611	701 HILLTOP DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783637	424 TRAILSIDE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783626	805 HILLTOP DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783638	906 PHEASANT LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882458	503 VALLEY DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783252	520 LINDE ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882324	212 MADISON AVE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515789	408 COLUMBIA AVE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79000056	217 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783180	421 LINDE ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882491	412 LINDE ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882304	441 YAHARA ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882574	505 YAHARA ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882546	428 ANDERSON ST	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
76783133	408 ANDERSON ST	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
78882278	433 E LINCOLN DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78032447	938 COUNTY HIGHW	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
97689403	650 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783308	436 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783264	406 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515724	312 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882594	304 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882294	300 N STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882528	300 LINDE ST # D	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882537	300 LINDE ST # C	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882529	300 LINDE ST # B	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882533	300 LINDE ST # A	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882552	308 E HOLUM ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N		Visual insp at meter
76783263	404 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882320	440 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882510	712 RUSSELL ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882365	713 RUSSELL ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783384	725 PARK AVE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882681	706 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583500	501 PRAIRIE VIEW C	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Installed after lead ban	N		
75583372	815 SUNNYBROOK D	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583464	813 SUNNYBROOK D	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583269	507 RIVERSIDE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377876	822 WOODS GLEN C	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882596	808 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882697	202 BRUNS ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
85667815	216 BRUNS ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882641	609 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783627	324 S CLEVELAND A	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882225	521 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783392	411 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882341	115 S STEVENSON S	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782718	202 DANBURY CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515976	401 JEFFERSON ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882366	413 JEFFERSON ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75583601	313 SOUTHBOUND I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783141	634 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882247	620 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583540	700 CONSTITUTION	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583545	622 GREENFIELD DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
80063660	801 NASH LN	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
76783080	825 SOUTHBOUND I	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN		Installation record	Installed after lead ban	N		
79318036	902 MACK LN	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
79515778	929 FLYWHEEL CIR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
78882631	606 TANGLEWOOD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
78882612	704 TANGLEWOOD	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
76783155	342 BLACKBERRY LN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
75583676	334 BLACKBERRY LN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
76783099	328 BLACKBERRY LN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN		Installed after lead ban	Installed after lead ban	N		
79515728	413 ROSEMAL LN	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N		
80063711	118 RENATA CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882604	112 RENATA CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882243	209 BRUNS ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
95061517	933 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
95061514	935 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
88658648	950 E NORTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783374	119 CARRIAGE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783371	123 CARRIAGE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783373	117-125 CARRIAGE \	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783376	129 CARRIAGE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783377	127-133 CARRIAGE \	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78886699	206 N MAIN ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
83646555	148 E HOLUM ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377864	102 QUAM LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75377978	104 REIGSTAD ST	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
79317808	201 REIGSTAD ST	Unk	P	Unk	Unknown	UN	C	Unknown	UN		Installed after lead ban	Field inspection only	N		
75583699	100 COMMERCE ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N		Visual insp at meter
75377844	209 HILL ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	N	3/13/2025	Visual insp at meter
75583439	300 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377763	301 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
83119125	317 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75378151	312 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75583452	320 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75583275	329 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
78882688	100 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN		Installation record		N		
75377757	104 MEADOW LN	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN		Installation record		N		
75378099	637 S MAIN ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/11/2025	Visual insp at meter
75378114	629 S MAIN ST	Unk	DI	Unk	Unknown	UN	DI	6"	UN		Installation record	Field inspection only	N		Visual insp at meter
75378135	631 S MAIN ST	Unk	DI	Unk	Unknown	UN	DI	6"	UN		Installation record	Field inspection only	N		Visual insp at meter
78882551	613 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN		Installation record		N		
76783082	517 ACKER PKWY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583310	821 ACKER PKWY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783029	909 ACKER PKWY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377772	617 CHOKECHERRY	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75583351	509 WILD PLUM DR	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
79515841	456 SUNSET DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515643	416 STONERIDGE TE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783007	312 RIVERWOOD BN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75583327	604 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583507	718 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75378098	425 S LEXINGTON PI	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF	Installation record		N		
75377957	816 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515853	951 SOUTH ST	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83646599	131 CROOKED TREE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583607	418 OLD INDIAN TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79317829	212 POCAHONTAS L	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783002	520 SHAWNEE CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79317810	513 W MOHAWK TR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		

79204318	7184 MORRISONVIL	Unk	DI	Unk	Unknown	UN	DI	6"	UN		Installation record	Field inspection only	N		Visual insp at meter
79256122	5025 CTY HWY V	Unk	DI	Unk	Unknown	UN	DI	6"	UN		Installation record	Field inspection only	N		Visual insp at meter
78882276	403 IROQUOIS CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783541	408 IROQUOIS CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063795	413 CHEROKEE CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783527	414 CHEROKEE CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515721	407 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783489	517 FLAMBEAU PKW	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063776	541 FLAMBEAU PKW	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515906	326 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783459	324 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515788	507 TARA CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83119154	337 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783412	521 BRULE PKWY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78032408	512-518 SEMINOLE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76503395	504-510 SEMINOLE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76783091	551 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75583715	505 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76503393	601-607 OLD INDIAN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76782863	611 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515836	625 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
80063713	629 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
75583647	635 SEMINOLE WAY	Unk	C	Unk	Unknown	UN	C	1"	UN		Installation record	Installed after lead ban	N	3/3/2025	Visual insp at meter
76783316	639 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882658	630 SEMINOLE WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76782745	507 OLD INDIAN TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063697	305 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
80063702	307 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83646590	323 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782866	229 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515574	405 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515940	411 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515578	413 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515497	415 MEADOW OAK '	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76782805	405 TRAILSIDE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
76782838	823 W LEXINGTON I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75583529	813 W LEXINGTON I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515679	191 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783201	195 N LEXINGTON P	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783389	714 DEFOREST ST	Unk	C	Unk	Unknown	UN	C	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
78882312	733 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
76783560	752 JEFFERSON CT	Unk	C	Unk	Unknown	UN	C	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
75377880	643 SPRINGBROOK (	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377851	700 CREEK EDGE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377796	704 CREEK EDGE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75377972	712 CREEK EDGE DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
75378040	695 S MAIN ST	Unk	C	Unk	Unknown	UN	UNK-LG	Unknown	UN		Installation record		N		
75377893	677 S MAIN ST	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/3/2025	Visual insp at meter
79515689	120 PARADISE CIR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515683	122 PARADISE CIR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79317935	141 PARADISE CIR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063789	6872 TUSCAN RIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515833	6876 TUSCAN RIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79317906	4631 SUNBURST DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86844798	6794 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86482127	6774 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
87288708	6766 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86482133	6762 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86482129	6758 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
87288697	6529 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
87288704	6525 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76783192	6851 YELLOWWOOI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515912	6849-6871 YELLOW	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515507	6805-6819 YELLOW	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515527	6755 VILLAGE WALK	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79318030	6751-6757 VILLAGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
79515607	6809 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515526	7717 INDIGO DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79318000	7719 INDIGO DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452935	7751 BULRUSH CIR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
84515415	7814 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85668542	4886 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85668543	4888 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85668545	4892 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85668546	4894 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85667938	4896 INNOVATION I	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
85667908	4900 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85667907	4902 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
85667937	4904 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
92263207	4601 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
92263208	4603 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	1"	UN		Installation record	Diameter > 2 inches	N		Visual insp at meter
92263203	4609 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
92701064	7716 STONECROP W	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
85668540	4683 BELLFLOWER I	Unk	C	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
85669124	4673 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
85669125	4675 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	N		Visual insp at meter
92701058	4653 BELLFLOWER I	Unk	P	Unk	Unknown	UN	P	1"	UN	SF	Installation record	Field inspection only	N		Visual insp at meter
86482140	4629 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
87288699	4631 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86741037	4633 BELLFLOWER I	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
86741034	4635 BELLFLOWER I	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
92779606	4637 BELLFLOWER I	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
76783072	7720 CATCHFLY LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452937	4639 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
94090296	4641 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452938	4643 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452936	4645 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
94090290	4647 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
94090289	4649 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
93542853	4701 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
93542849	4703 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
93542854	4705 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
93542850	4707 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
98444935	4709 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
98444934	4711 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
98444931	4713 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
96814448	7715 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
98444930	4715 BELLFLOWER I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
96814428	7713 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
76782907	7705 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
79515768	4750 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
78882302	4790 INNOVATION I	Unk	C	Unk	Unknown	UN	P	1"	UN	SF	Installation record	Installed after lead ban	N	3/6/2025	Visual insp at meter
83119120	4851 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83119124	4859 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
83119123	4863 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
84230670	4843 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
78882652	4874 INNOVATION I	Unk	C	Unk	Unknown	UN	C	1"	UN		Installation record	Installed after lead ban	N		
78882651	4868 INNOVATION I	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installation record	Installed after lead ban	N		
84515386	4831 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
84515376	4817 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
84515388	4815 INNOVATION I	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063794	1117 RIVER RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
92779609	7654 AUTUMN BLAZ	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
88065431	7804 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814994	7793 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
93542848	7791 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814984	7789 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452886	7788 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
92701063	7790 BLUESTEM TRI	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N		
96815002	7796 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814998	7801 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814455	7803 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96452882	7795 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96815085	7797 BLUESTEM TRI	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814433	7714 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
96814988	7704 AUTUMN BLAZ	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
86741057	6982 CRYSTAL CREE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
90942255	4521-4523 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
90942256	4537-4539 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
90942260	4529-4531 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N		
80063705	6820 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063706	6824 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063709	6826 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063712	6828 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		
80063676	6832 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N		

79515813	6838 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
80063692	6846 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
80063684	6848 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
80063655	6850 REDSPIRE LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
90292468	4551 SPRINGS CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
85667912	4514-4520 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90942430	4501-4507 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
85667932	4540-4550 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90292475	4545-4551 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90292476	4541-4543 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90292477	4513-4519 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90292474	4509-4515 SPRINGS	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90942434	4601-4605 BELLFLO'	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
90942431	4607-4613 BELLFLO'	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
85669130	4677-4683 BELLFLO'	Unk	C	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	N	Visual insp at meter
85669129	4671-4675 BELLFLO'	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
91214065	6717 YAHARA SPRIN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
84230685	966 CLOVER LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
90028079	989 GRIFFIN WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
85668595	983 GRIFFIN WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
84515395	963 GRIFFIN WAY	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
90028060	981 CLOVER LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643963	6719 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643959	6717 CONSERVANC	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814996	6715 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814990	6717 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814431	6718 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814992	6719 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92779619	6720 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814989	6721 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643965	6722 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643962	6723 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643961	6724 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643966	6725 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701057	6709 YAHARA SPRIN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701059	6711 YAHARA SPRIN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92779605	6705 YAHARA SPRIN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701068	6707 YAHARA SPRIN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643964	6726 BELLFLOWER (	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
85667936	6727 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643960	6728 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
91505729	6729 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701074	6730 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
91505727	6731 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701070	6732 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
91505719	6733 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
94090292	6734 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96452942	6735 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96452939	6736 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814452	6737 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814987	6714 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814991	6716 BELLFLOWER F	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
88065435	6730-6734 CONSER	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
88065444	6505-6507 TRAILS E	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
88065434	6512-6516 TRAILS E	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
88824638	6521-6523 TRAILS E	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
92779617	6708 CONSERVANC	Unk	C	Unk	Unknown	UN	P	1"	UN	SF	Installation record	Installed after lead ban	N	3/6/2025 Visual insp at meter
86967009	6321 ROSTAD CIR A	Unk	DI	Unk	Unknown	UN	C	Unknown	UN		Installation record	Field inspection only	N	3/13/2025 Visual insp at meter
76503396	4306 DURAFORM LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
88658652	4410 DAENTL RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
79515937	4297 DAENTL RD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
81814287	5920 HAASE RD	Unk	DI	Unk	Unknown	UN	C	1"	UN		Installation record	Field inspection only	N	
80782749	6162 HWY 51	Unk	C	Unk	Unknown	UN	C	Unknown	UN		Installed after lead ban	Field inspection only	N	2/26/2025 Visual insp at meter
78882527	945 STAR GAZER DR	Unk	C	N	Unknown	UN	C	Unknown	UN	SF	Installation record	Field inspection only	Y	3/3/2025 Visual insp at meter
83646604	927 SKYLARK LN	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
92701076	925 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814447	932 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814441	930 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814451	933 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
92701060	926 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
88824617	927 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814443	928 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814445	931 STAR GAZER DR	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
79000057	805 YORKTOWN RD	Unk	C	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
92701071	4133 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643956	4094 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814430	4077 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814426	4080 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643957	4053 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96815005	4081 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
91214050	4135 PARKER CT	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92779625	4075 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701066	4086 GREAT BRIDGE	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N	
92701077	4090 GREAT BRIDGE	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N	
92701075	4062 GREAT BRIDGE	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N	
96814449	4079 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814453	4067 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814450	4082 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814446	4083 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814437	4074 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814439	4055 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96815004	4098 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
91505728	4059 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127695	4087 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92779623	4109 BEAR TREE PK\	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96452941	4089 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96452940	4097 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701072	4088 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814432	4076 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814436	4060 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127690	4061 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96127694	4085 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
97799294	4189 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
92779614	4105 BEAR TREE PK\	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Field inspection only	N	
96814440	4113 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
92701073	4101 BEAR TREE PK\	Unk	C	Unk	Unknown	UN	P	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96814429	4068 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127692	4073 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96452884	4133 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96452883	4135 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
97557296	4137 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96815087	4139 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
97557297	4141 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96452881	4142 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96815086	4143 FOX FOREST W	Unk	P	Unk	Unknown	UN	P	Unknown	UN		Installation record	Installed after lead ban	N	
96452885	4144 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127688	4145 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127693	4147 FOX FOREST W	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96643951	4078 GREAT BRIDGE	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Installed after lead ban	N	
96452879	4070 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96127691	4085 HANOVER DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96815003	4054 GREAT BRIDGE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
99019649	4165 SAVANNAH DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96127689	4105 HANOVER DR	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN		Installation record	Installed after lead ban	N	
96814438	4197 HANOVER DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
85667935	6251 FOUNTAINHEA	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
84515405	6234 DAGNY LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814997	6247 JOHN KENNED	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
84515407	6249 JOHN F KENNE	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96814425	6262 JOHN F KENNE	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN		Installed after lead ban	Installed after lead ban	N	
96815000	6252 RONALD REAG	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814434	6245 RONALD REAG	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96815006	6251 RONALD REAG	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814454	6257 RONALD REAG	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
92779612	6260 RONALD REAG	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installed after lead ban	Installed after lead ban	N	
94090291	6258 RONALD REAG	Unk	P	Unk	Unknown	UN	P	1"	UN	SF	Installation record	Field inspection only	N	Visual insp at meter
94090294	6254 RONALD REAG	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96815001	4086 HANOVER DR	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN		Installation record	Installed after lead ban	N	
94090295	4142 HANOVER DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96815084	6233 DAGNY LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643952	6244 FOUNTAINHEA	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814435	6240 FOUNTAINHEA	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	
96814427	6233 FOUNTAINHEA	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
94090293	6243 FOUNTAINHEA	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N	
96643958	6229 DAGNY LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N	

90028072	4153 HANOVER DR	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N				
96814993	6226 DAGNY LN	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
96814442	6522 HICKORY GLAD	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
96814424	4045 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N				
96643953	4057 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N				
96452880	4064 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
96643955	4069 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N				
96643954	4072 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
96815007	4084 BEAR TREE PK\	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN	SF			N				
93542847	6497 RIDGE VIEW Va	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
96814999	6499 RIDGE VIEW Va	Unk	UNK-LG	Unk	Unknown	UN	UNK-LG	Unknown	UN				N				
98444941	4031 Great Bridge D	Unk	UNK-NOLG	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Field inspection only	Y	3/12/2025	Visual insp at meter		
93542841	6232 Fountainhead	Unk	P	Unk	Unknown	UN	UNK-NOLG	Unknown	UN	SF	Installation record	Field inspection only	Y	3/13/2025	Visual insp at meter		
93542846	4058 Great Bridge	Unk	UNK-NOLG	Unk	Unknown	UN	P	1"	UN		Installed after lead ban	Field inspection only	Y	3/12/2025	Visual insp at meter		
93542851	4129 Fox Forest War	Unk	UNK-NOLG	Unk	Unknown	UN	P	1"	UN		Installation record	Field inspection only	Y	3/12/2025	Visual insp at meter		
93542852	4131 Fox Forest War	Unk	UNK-NOLG	Unk	Unknown	UN	P	1"	UN		Installed after lead ban	Field inspection only	Y	3/12/2025	Visual insp at meter		
0	4060 Great Bridge	Unk	UNK-NOLG	Unk	Unknown	UN	P	1"	UN		Installed after lead ban	Field inspection only	Y	3/12/2025	Visual insp at meter		